

# Town of Brimfield, Massachusetts

## Town Building Assessment Study

### and

## Capital Master Plan

February 24, 2014

Town Hall  
Senior Center  
Town Hall Annex and Barn

Brimfield Public Library  
Public Safety Headquarters  
Highway Department





**BUILDING USE AUDIT**  
Town of Brimfield, Massachusetts

**TABLE OF CONTENTS**

Section	Description
1	Introduction: Introduction Building Location Map Priority Rating System
2	Recommendations: Recommendations Option Descriptions Summary of Priority Costs Cost Summary Code Implications for Repairs and Renovations to the Existing Buildings Need for Swing Space
3	Summary Spreadsheet with Priorities
4	Architectural Assessment Town Hall: Condition Assessment Existing Plans Proposed Plans Structural Assessment MEP Assessment Cost Estimate Program Charts
5	Architectural Assessment Senior Center: Existing Plan Program Charts
6	Architectural Assessment Town Hall Annex: Condition Assessment Existing Plans Proposed Plans Structural Assessment MEP Assessment Cost Estimate Program Charts

- 7            Architectural Assessment Public Safety Headquarters:
  - Condition Assessment
  - Existing and Proposed Plans
  - Structural Assessment
  - MEP Assessment
  - Cost Estimate
  - Program Charts
  
- 8            Architectural Assessment Library:
  - Condition Assessment
  - Existing Plans
  - Proposed Plans
  - Structural Assessment
  - MEP Assessment
  - Cost Estimate
  - Program Charts
  
- 9            Architectural Assessment Highway Department:
  - Condition Assessment
  - Existing Plans
  - Proposed Plans
  - Structural Assessment
  - MEP Assessment
  - Cost Estimate
  - Program Charts
  
- 10          Use of Cost Estimate Information:
  - Use of Cost Estimate Information
  - Mark-up List

Introduction

Recommendations

Summary Spread Sheet with Priorities

Architectural Assessment:  
**TOWN HALL**

Architectural Assessment:  
**SENIOR CENTER**

Architectural Assessment:  
**TOWN HALL ANNEX**

Architectural Assessment:  
**PUBLIC SAFETY H.Q.**

Architectural Assessment:  
**PUBLIC LIBRARY**

Architectural Assessment:  
**HIGHWAY DEPARTMENT**

Use of Cost Estimate Information



# Town Building Assessment Study and Capital Master Plan Town of Brimfield, Massachusetts

## Introduction

Buildings or functions included in this audit are as follows:

- Town Hall
- Town Hall Annex
- Library
- Senior Center
- Public Safety Building (Police, Fire and Ambulance)
- Highway Department

In 2013 DRA Architects with its team of engineers performed visits to each of the buildings and evaluated them to determine the types of improvements that will be necessary. Conversations were held with department heads and those in charge of maintenance. These improvements included such topics as:

- Life Safety
- Health
- American's with Disabilities Compliance
- Site Issues
- Exterior Envelop Issues
- Building Interiors
- Energy and Water Conservation
- Hazardous Materials
- New Construction

With any renovation project it is necessary that International Existing Building Code be reviewed in light of the items of renovation work that are selected. In doing so it may be determined that other items of work will be necessary to achieve compliance.

Each of the improvements was then prioritized into the following categories:

- Current Critical
- Potentially Critical
- Necessary – Not yet Critical
- Recommended

A detailed description of criteria used for each of the categories is included in the report.

For each of the improvements an independent cost estimate was obtained. The estimates are a projection of the costs and include soft costs associated with each item. (Soft costs are the miscellaneous costs associated with professional fees, contingency, bonding costs, bidding expense, testing etc.). The estimator does not have the advantage of detailed drawings for each of the items so

the intent is to provide an order of magnitude that, should the improvement move ahead, will be refined up to the bid date. For many of the like items it will be possible to group them together and save on the soft costs. Similarly, there may be items that can be bid without professional drawings and specifications and, again, the soft costs can be reduced. The cost should be used as an overall budget for each item. A more detailed explanation of the use of the estimates is included later in this report.

This report is organized with the recommendations presented first followed by the reports for each of the buildings from the various engineers each with the cost estimate for the work.

\* \* \*





**Senior Ctr.**





**Library.**



**TH Annex.**



**Town Hall.**



**Public Works**



**Police Station**



**Fire Station**



TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**Priority Rating System**

Priorities are listed to the left of each item:

**Priority** 1 – Current Critical: Conditions in this category require immediate action to:

- Correct a cited safety hazard
- Stop accelerated deterioration
- Return a facility to operation

**Priority** 2 – Potentially Critical: Conditions in this category if not corrected soon may result in:

- Intermittent Operations
- Rapid Deterioration
- Potential Safety Hazards

**Priority** 3 – Necessary, not yet critical.  
Conditions in this category require appropriate attention to preclude a predictable deterioration or potential downtime and possible damage and higher costs.

**Priority** 4 – Recommended.  
Conditions in this category include items that represent a sensible improvement to existing conditions. They are not required for the most basic function of the facility, but will improve overall usability and/or reduce long-term maintenance costs.

- Comment only.



# TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN

## Town of Brimfield, Massachusetts

### **Option Descriptions:**

#### **Option #1**

This option minimizes new construction to accommodate facility needs. Additions to the existing building will be required as indicated below.

#### Town Hall

- Senior Center on upper two floors.

- Use of meeting room by boards and commissions.

- Police Department lower level.

- An addition is required for a stair and elevator.

- A storage building required in the parking lot to accommodate large evidence items.

#### Town Hall Annex

- Single story addition to allow building to be used by all town administrative functions.

- Second floor unused.

- Barn restored and integrated into design.

#### Library

- Single story addition on east side to expand library space.

- Floor raised up in existing rear wing to allow for library to be on one level.

#### Public Safety

- Building modified and expanded for Fire and Ambulance use.

- Police relocated to Town Hall.

#### Highway Garage

- Building expanded for storage and vehicle wash bay.

#### Salt Sheds

- Wood building modified to contain salt mixture and building repaired.

## **Option #2**

This option includes the most new construction to accommodate facility needs. Additions to the existing building will be required as indicated below.

### **Town Hall**

- Senior Center upper two floors.
- Use of meeting room by boards and commissions.
- Lower level vacant.
- An addition is required for a stair and elevator.

### **Town Hall Annex**

- Rear of building demolished.
- Two story addition to allow building to be used by all town hall functions.

### **Library**

- Single story addition on east side to expand library space.
- Floor raised up in existing rear wing to allow for library to be on one level.

### **Public Safety**

- Building modified and expanded for Fire and Ambulance use.
- Police relocated to New Building.

### **Highway Garage**

- Building expanded for storage and vehicle wash bay.

### **Salt Sheds**

- Wood building modified to contain salt mixture and building repaired.

## **Option #3**

In this option the buildings remain as-is and improvements are made to the buildings to resolve items listed in the building assessments. This is often referred to as the "Do Nothing" option as it does not resolve program deficiencies.

\* \* \*

Existing Buildings:	Priority 1	Priority 2	Priority 3	Priority 4	TOTALS
---------------------	------------	------------	------------	------------	--------

Town Hall	\$ 7,216	\$ 1,886,104	\$ 2,073,862	\$ 517,531	\$ 4,484,713
Cumulative Total		\$ 1,893,320	\$ 3,967,182	\$ 4,484,713	

Town Hall Annex	\$ 243,087	\$ 24,846	\$ 1,114,387	\$ 6,465	\$ 1,388,785
Cumulative Total		\$ 267,933	\$ 1,382,320	\$ 1,388,785	

Library		\$ 180,795	\$ 835,723	\$ 33,994	\$ 1,050,512
Cumulative Total		\$ 180,795	\$ 1,016,518	\$ 1,050,512	

Highway Garage		\$ 302,298	\$ 52,979	\$ 278,182	\$ 633,459
Cumulative Total		\$ 302,298	\$ 355,277	\$ 633,459	

Salt Shed		\$ 128,537	\$ 31,208		\$ 159,745
Cumulative Total		\$ 128,537	\$ 159,745	\$ 159,745	

Public Safety		\$ 185,002	\$ 712,221	\$ 451,142	\$ 1,348,365
Cumulative Total		\$ 185,002	\$ 897,223	\$ 1,348,365	

Overall Cumulative Totals	\$ 243,087	\$ 879,563	\$ 2,913,860	\$ 3,232,501	\$ 9,065,579
---------------------------	------------	------------	--------------	--------------	--------------





**BUILDING USE AUDIT**  
Town of Brimfield, Massachusetts

**COST SUMMARY**

The following is a summary of the costs associated with each building, both repairs and additions, and, where applicable, for new construction.

The Building Repairs are a total of all items listed in the building assessments. A separate chart is provided to show the costs associated to each of the priorities for each building. It is important to note that the Building Repairs have been priced as though each item was a separate project and as such the costs are inflated over what they would be if part of a large project. Please refer to "Use of Cost Estimate Information" included in Section 10 for more detail.

**Town Hall**

Building Repairs:	\$ 4,484,713
New Entrance, Elevator and Stair:	\$ 1,101,993
Renovations for Police and Council on Aging:	\$ 4,950,392
Renovations for Council on Aging only:	\$ 3,367,584

**Town Hall Annex**

Building Repairs:	\$ 1,388,785
New Single Story Addition:	\$ 4,097,709
OR	
New Two Story Addition:	\$ 5,883,732

**Library**

Building Repairs:	\$ 1,050,512
New Addition:	\$ 2,147,612

## Highway Department

Building Repairs:	\$ 633,459
New Addition:	\$ 1,648,187
Salt Shed Repairs:	\$ 159,745

## Public Safety Building

Building Repairs:	\$ 1,348,365
New Addition:	\$ 3,594,340
New Police Building (in lieu of Town Hall Location):	\$ 3,196,769

## New Building on New Site (to be selected)

Combined Town Hall, Senior Center and Police Station \$ 8,346,166  
(Does not include cost of land or sale of current buildings)

For comparison note the following:

Town Hall Annex Renovations and Expansion:	\$ 4,097,709
Stair & Elevator addition to Town Hall:	\$ 1,101,993
Senior Center and Police in Town Hall:	\$ 4,950,392
<hr/>	
Total:	\$10,150,094

Town Hall Annex Renovations and Expansion:	\$ 4,097,709
Stair & Elevator addition to Town Hall:	\$ 1,101,993
Senior Center Town Hall:	\$ 3,367,584
New Police Building:	\$ 3,196,769
<hr/>	
Total:	\$11,764,055

# Code Implications for Repairs and Renovations to the Existing Buildings

The International Existing Building (IEBC) applied to the town's buildings and architectural recommendations addresses the requirements for the repair, alteration, change of occupancy, and additions to the studied buildings. The following is intended as a very basic guide only and before any work is undertaken the specific codes should be examined.

The studied town buildings have been previously, or are occupied and are therefore required to comply with the IEBC.

There are three compliance methods for these buildings:

**1. Prescriptive Compliance Method:**

Previously known as Chapter 34 of the International Building Code (IBC) these provisions prescribe specific minimum requirements for the construction work. Routine maintenance and repairs (that would not require permits) do not fit under these requirements.

**2. Work Area Compliance Method:**

These provisions are based on a proportional approach to compliance where upgrades are triggered by the type and extent of the work. There are three levels of alterations defined as follows:

**Alteration-Level 1:**

Includes the removal, replacement or covering of existing materials, elements, equipment or fixtures using items to serve the same purpose.

**Alteration-Level 2:**

Includes the reconfiguration of space, the elimination or addition of any door or window, the reconfiguration or extension of any system, or the installation of any additional equipment.

**Alteration-Level 3:**

This applies when the work area exceeds 50 percent of the aggregate area of the building.

**3. Performance Compliance Method:**

This method provides for evaluating the building based on fire safety, means of egress and general safety. Using values for various building components a summary sheet is completed to show whether or not the work complies with this

section. There are mandatory scores required for fire safety, means of egress and general safety in order for the work to be acceptable.

Although part of the compliance methods, there are factors that need to be considered. Pertinent sections are described below.

**Seismic Improvements:**

In any of the above cases it will need to be determined if seismic improvements are necessary to the structure of the facility. This evaluation would be performed by a licensed structural engineer.

**Unsafe Buildings:**

Buildings that are unsafe are required to be taken down, removed or made safe. The Building Official needs to make this determination.

**Historic Buildings:**

Buildings may be exempted from items of compliance due to accreditation as a historic structure, but only when the lack of compliance will not constitute a distinct life safety hazard.

**Fire Sprinkler Requirements (Alteration Level-2):**

The addition of a sprinkler system to a building is often desired, particularly for historic structures. We include this paragraph as a guide to the requirements.

For the town occupancies with exits or corridors serving an occupant load greater than 30, fire sprinklers are required where the following occur:

- The work area exceeds 50 percent of the floor area.
- The building has sufficient municipal water supply for the fire sprinkler system without the installation of a new fire pump.

\* \* \*

## BUILDING USE AUDIT Town of Brimfield, Massachusetts

### **THE NEED FOR SWING SPACE**

The sequence of the renovations or additions to the Town's building must consider how continuous operations of the Town functions can be maintained during the work. The Town Hall is the only building that is not occupied, except for the offices of the Town Clerk, and therefore would be the best candidate as swing space for office functions.

Town functions could be located temporarily in Town Hall during construction work at the Town Hall Annex, but would require that either the Police Department or Senior Center renovations at Town Hall be delayed until the Annex is complete.

The addition to the Highway Garage would provide temporary vehicle bays for the Fire Department or Ambulance to allow a phased renovation of the Public Safety Building. Similarly, the new addition to the Highway Department would provide some swing space for the Highway Department renovations. A detailed phasing plan is necessary and consideration should be given to a temporary office space to reduce the time of the renovations.

In the renovated Town Hall option, the Police Department relocation is only dependant on vacated space in the Town Hall. This is the same for the Senior Center.

For the Library, the addition and renovations to the existing rear addition should be completed first to provide swing space during renovations to the original building. The wall between the original building and the additions should be made dust tight. A temporary storage trailer should be provided to house some of the collection during the renovations.









# BUILDING USE AUDIT - CONDITION ASSESSMENT

## Town of Brimfield, Massachusetts

### Brimfield Town Hall

21 Main Street

Year Constructed:	1878
Construction Type:	IV
Fire Sprinklers:	No
Building Area per Floor:	
Ground:	3172 SF
First Floor:	3570 SF
Second Floor:	576 SF
Total Area:	7318 SF



Documents Used in Study:  
Assessor's Field Card  
Aerial Photograph


#### General:

There are a number of main challenges that need to be overcome to fully utilize the building. First is handicapped accessibility to the second floor. The current lift only provides access to the first floor. The fire escape at the rear of the building is also not a safe method of exiting the building. It is recommended that a new entrance with a stair and elevator be added to the rear of the building to serve all floors.

The basement area is damp and also faced with wood paneling creating an unhealthy and dangerous (respectively) environment. It is recommended that the wood faced partitions and wood floor be removed, and a new floor constructed with under drains and new sheetrock faced partitions be constructed.

#### Ground Floor

- 3 Accessible entrance door is located on the south-east corner of the structure. Interior approach clearance on push side of door does not meet code. Add a push button operator to the door. (exterior & interior). (Not required if new entrance constructed).
- 2 Town Hall Annex parking lot drains towards Town Hall. Re-grade lawn area to provide a low spot at least 8 feet from Town Hall for the length of the west wall, with a gravel filled trench with a perforated drain running to the catch basin.



2 On the exterior of the building there are two copper rain-leaders that are broken, that connect to plastic pipes at grade. Replace plastic pipe and clean-outs and provide a sleeve that will allow expansion of copper.



2 Brick and stone foundation needs re-pointing at grade. (allow 20% of perimeter).



3 Repair steps and isolate from foundation wall of building to prevent future cracking.



2 Foundation walls allow moisture into the building. Excavate adjacent to building down to bottom of foundation walls. Provide a continuous perforated drain around building. Drain will probably need to be connected to a pumping station with the discharge at the higher catch basins. If foundations are irregular apply gunite to smooth out surface. Apply damproofing over gunite with a drainage stone extending from grade to drain wrapped in filter fabric. Back-fill area. Patch paving where disturbed.




2 It appears that the foundation walls are the primary source of moisture but if this proves not to be the case then the following action will be necessary:

Remove wood flooring and concrete slab. Provide an under-floor drainage system connected to the pumping station described for the foundation drains.

Provide a minimum 6 inch thick stone base and place new concrete slab at a single level throughout basement. Slab needs to include insulation below and a vapor barrier.

2 Wood faced partitions are not code compliant and need to be removed. Demolish interior wood faced partitions in basement and construct new partitions that are faced with moisture resistant sheetrock.



3 Foundation wall needs to be insulated. After drainage system is installed and wall has dried out apply sheetrock faced metal studs and insulation over perimeter walls. this will cover all exterior wall plaster failures.



3 Remove loose paint from exposed pipes below ceiling in the lift and ramp area and repaint.

3 Add storm panels to (14) existing single pane wood windows (double hung / fixed) including some with metal bars (interior). This approach will be considerably less than replacement of the windows with historically accurate windows.

2 In Mechanical #1 patch openings and repair damaged areas to gypsum board ceiling and seal all duct penetrations in ceiling.




2 In Mechanical #1 the exterior stone foundation wall and the first 2 course of brick are deteriorating due to water infiltration. These walls show numerous repairs made over the years. This area of the room has a sump pump in the floor slab and at the time of the inspection there was water on the floor. Replace damaged brick and re-point existing brick chimney for the first 4' above the slab.



2 In Mechanical #2 patch openings and repair damaged areas to gypsum board ceiling and seal all wall penetrations with fire caulk.



2 In Mechanical #2 the exterior stone foundation wall and the first 2 course of brick are deteriorating due to water infiltration. Re-point upper part of interior face of wall.




3 Exterior wall next to lift is damaged. Repair wall and paint to match existing.

3 Seal all pipe and duct wall penetrations throughout Ground Floor. This includes fire caulking at rated partitions. (Corridors, Boiler Room, etc.)



3 More than half of the 17 interior doors do not meet the minimum width required by ADA. Enlarge door openings as require and install new door and hardware.



3 All interior doors are not equipped with lever hardware except for Elevator Lift door. Replace hardware to meet code on existing doors to remain.

- 2 Walls and ceilings in Toilet Rooms #1 & #2 have water damage and stains. Following successful repairs to exterior walls remove deteriorated plaster, add furrings to wall and new moisture resistant sheetrock over a vapor barrier. Paint walls and re-install toilet room accessories and fixture.




- 2 Unprotected step down from elevated wood floor in Corridor #2 to area in front of Unassigned #7 Room. Also, the wood ramp from Corridor #2 to Corridor #3 appears to have a slope greater than 1in12 and has no handrails. Door to Mechanical #1 from Corridor #3 is blocked by the ramp. Add new wood floor construction to resolve transitions between areas and to replace ramp.




- 2 Chase wall exposed by opening in wall by ramp. Infill opening from floor to ceiling.



- 2 Brick / concrete steps and metal pipe handrail to exterior door in Corridor #3 are not to code. Remove and replace with larger platform and steps that will also provide space around column at bottom of stairs. (See next item).



- 2 Clearance between bottom of stairs, column and steps to exterior is too narrow. Create new landing flush with sill of exterior door and aligned with tread of stair. Landing to have steps down to floor with handrails.






- 2 There is a existing oil tank located in under the main egress stairs. This needs to be relocated out of the stair tower.

- 2 In both stairs up to the First Floor the existing riser/tread ratio and handrails do not meet code. the stairs also have projecting nosings. Retain existing stairs. Add new handrails. Infill area under nosings to meet ADA.

## First Floor

- 3 All interior doors are not equipped with lever hardware .  
Replace hardware to meet code.
- 3 All exterior door hardware is old and out dated. Replace hardware to meet ADA and add closers to doors.
- 4 Several locations in the Meeting Room have water stains on the wall or at the intersection of the wall & ceiling. it is assumed that these are from previous water leaks and that repairs have been made. Repaint stained areas with stain blocker and topcoats to match existing.
- 4 The existing curtain for the stage appears to be in poor condition. The majority of the curtain is in the attic where the pully system, for raising and lowering the curtain, is located. At this time restoration has not been included, but it is recommended that the curtain be removed and the remaining ceiling opening be covered with sheetrock as it is open to the attic.
- 3 Add interior storm panels to (15) existing single pane wood windows (double hung / fixed) and replace broken panes of glass.
- 3 There are minor splits in the panels and slightly open joints in the rails of the exterior doors in the Meeting Room. Fill splits and open joints and repaint doors.
- 3 Thresholds are too high. Remove and replace existing wood thresholds at both interior double doors from the Meeting Room.
- 3 Install new handrails at both stairs up to the Stage in the Meeting Room.
- 3 Repair wall and ceiling damage (cracks) in Storage #3 .
- 2 Replace existing wood handrail in both Storage #2 and #3 with new to meet code.
- 3 Repair wall (water stains) and ceiling damage (cracks) in Town Clerk #1 .
- 3 Repair wall (water stains) and ceiling damage (cracks) in Lobby.
- 2 The handrails and guardrails on the egress stair located in the Lobby do not meet code and require replacement. Also the tread/riser ratio is not to code but is grandfathered.




3 Sand and refinish wood floors and stairs. Remove and replace non-slip adhesive strips on stairs.

3 This floor is handicapped accessible, but has no accessible toilet. Install a new handicapped accessible toilet.

### Second Floor

3 Add interior storm panels to (5) existing single pane wood windows (double hung / fixed) and replace broken panes of glass.



4 Ceilings in the Meeting Room, Stair and Attic access all have water stains and damage/patches. Repair as required and re-paint.




3 Sand and refinish wood floors and stairs. Remove and replace non-slip adhesive strips on stairs.



3 The stair handrails and the projecting nosings do not meet ADA. Add new handrails and add tapered wood under nosings.

2 Replace vinyl asbestos tile in attic access space.



The following are items noted in the review of the building that will be addressed if the new layout for the second floor is implemented:

4 This floor is not handicapped accessible. Add an elevator to serve all levels and remove lift. In addition add a new egress stair.

### Attic

3 Insulate attic floor with blown-in insulation. Add attic ventilation.



1 Remove bird/bat droppings from belfry. Seal up openings to prevent future bird/bat access.

### Exterior

2 Re-attach gutter on the east side of building.



3 PVC rainleaders are broken. Replace damage sections. Replace damaged Brick.



2 At front stairs, retain existing 24" high railing and add a new 42" high guardrail on the landing side of the railing.



2 Secure loose metal handrails (3) at front entrance stairs.




3 Sand and refinish wood front entrance stair. Remove non-slip strips, re-paint and apply new strips.



3 Paint is peeling around entire structure. (siding, trim, window/door trim, fascia boards & porch) Scrape and repaint areas where peeling paint occurs (approximately 5%)



3 At front porch roof to wall intersection, cut wood siding back 1" from roof shingles. paint cut edges of siding. Verify existence of metal flashing. If none, install new.



3 Re-point (3) brick chimneys completely. Re-set stone chimney caps.



2 Replace missing boards from two finials and re-paint.



3 Replace flat roof area at second floor.

3 Insulate exterior walls with blown-in insulation on First and Second Floors.

### Mechanical

3 Replace the steam boiler plant with a hot water circulating plant and provide new hot water radiation equipment in place of the steam radiators for better control and comfort.

- 4 Replace all oil fired equipment with gas fired equipment for decreased energy usage due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).
- 3 Replace existing thermostats with programmable type.
- 3 Provide new oil supply lines with code approved jacketing/membrane to each of the furnaces since currently neither of these lines includes this.
- 3 Provide mechanical ventilation using an automatic louver/damper system to serve both of the furnaces serving the ground floor and the main meeting chamber.
- 2 Reconfigure the ductwork of the inline dehumidification unit to draw from and supply back to the supply main from the furnace this unit is serving. As currently configured, there is a good chance that the unit could be short-circuiting air across the furnace then back through the dehumidifier which may explain why the unit was overflowing and not operating at all. Additionally provide interlock wiring such that the unit only operates when the furnace fan is on and also to shut down the unit upon detection of moisture in the overflow drain pan.

**Electrical**

- 4 Upgrade the lighting throughout the building to more energy efficient types with better light distribution and quality.
- 2 Review the coverage of the exit and emergency lighting and provide additional fixtures where required. Replace the existing fixtures with new energy efficient LED types.
- 2 Provide a new emergency generator with an automatic transfer switch.

**Plumbing**

- 3 The well pump and the expansion tank for the pump should be replaced.
- 3 The electric water heater should be replaced.
- 4 The laundry tub should be replaced.
- 4 The water closets should be replaced with low flow fixtures.

**Fire Protection.**

- 2 The building does not have a sprinkler system. A system should be added to the building incorporating a storage tank and a generator or diesel powered fire pump. If the proposed plan incorporating the Police Department is implemented the generator for the Police can be designed to include the sprinkler system.



## **PROGRAM INFORMATION**

With the exception of the Town Clerks offices the building has no occupants. Some spaces in the basement are used by the Police Department for storage.



If all floors were made suitable for occupancy and accessibility the building could be efficiently utilized. Also have a fully used building will made energy use more efficient by not having to heat an unoccupied building.

Reviewing the needs of the Town the Senior Center appeared to be the best fit for the first and second floors, but also would maintain the historic character of the interior spaces. An elevator and egress stair would be added to serve all levels.

The previous occupant of the lower level was the Police Department but dampness is a problem for continued use of this space. With the moisture removed the space could be returned to serve the Police Department again. This use would need to be supplemented by a metal building for large evidence storage.

The test fit plan includes both the Senior Center and Police Department within the Town Hall building. A new entrance at the rear of the building will provide elevator and stair access to all levels from the parking lot.





**GROUND FLOOR PLAN**


**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**EXISTING TOWN HALL FLOOR PLANS**

Scale: 1/8"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 4/17/13

**EX-TH1**





**FIRST FLOOR PLAN**



**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**EXISTING TOWN HALL FLOOR PLANS**

Scale: 1/8"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 4/17/13

**EX-TH2**





**SECOND FLOOR PLAN**

**Town Of Brimfield**  
Municipal Facilities Study and Planning  
Brimfield, Massachusetts


EXISTING TOWN HALL FLOOR PLANS

Scale: 1/8"=1'-0"  
Drawn by: AJ/CGH  
Job No. 13002.00  
Date: 4/17/13

**EX-TH3**







**Drumey Rosane Anderson, Inc.**  
 235 Bear Hill Road, 4th Floor  
 Waltham, MA 02451

Planning 617-964-1700  
 Architecture 617-964-1701 fax  
 Interior Design info@draws.com


**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED TOWN HALL GROUND FLOOR PLAN**

Scale: 1/8"=1'-0"  
 Drawn by: KCB  
 Job No. 13002.00  
 Date: 7-9-13

**PR-TH1**





FIRST FLOOR PLAN



**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

PROPOSED TOWN HALL FIRST FLOOR PLAN

Scale: 1/8"=1'-0"  
 Drawn by: KCB  
 Job No. 13002.00  
 Date: 7-9-13

**PR-TH2**





**SECOND FLOOR PLAN**

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED TOWN HALL SECOND FLOOR PLAN**

Scale: 1/8"=1'-0"  
 Drawn by: KCB  
 Job No. 13002.00  
 Date: 7-9-13

**PR-TH3**



## MUNICIPAL FACILITIES STUDY AND PLANNING Town of Brimfield, Massachusetts

### Town Hall

#### Structural

##### Structural Description:

The Brimfield Town Hall is a two-story, wood framed structure (plus a walkout Ground Floor level), located at 23 Main Street in Brimfield. The building was constructed in 1878 and is listed on the National Register of Historic Places.



The Town Hall is rectangular (nearly square) in plan. Program elements at the Ground Floor include Town Offices, Police Offices, the Public Access Television Station, Bathrooms and Storage. The Ground Floor level is serviced by stairways at the back (south) side and at the northeast corner (at the front entry), and by a LULA elevator at the southeast corner of the building. The Selectman's Office and Town Clerk are located at the First Floor. The two-story Hall/Meeting Room and (elevated) Stage occupy the western two-thirds of this level. A partial Second Floor was constructed along the eastern one-third building, adjacent to the upper Hall. The Planning Center and the Cable Board Office are located at this level, between a flat roof section in the back of the building and the front entry stairway (this level currently get little or no use). Roof forms consist of hips and gables; an entry tower accents the front, northeast corner of the building.

Typical foundation walls are rubble stone with brick masonry upper sections. Ground Floor construction is a concrete slab on grade (thickness unknown); a wood floor (with shallow ramps) was constructed over the southern half of the Ground Floor, reportedly to address water issues. Floor and roof construction was mostly obscured by finishes; no exploratory demolition was conducted to determine floor and roof construction framing sizes/details. First and Second Floor construction is wood framed (2x10 joists observed in several locations) supported by timber beams (6x10 and 10x10 beams observed) and interior brick masonry bearing walls (8" thick) at the Ground Floor. Roof construction consists of

wood rafters spanning (up the slope) to timber purlins. The timber purlins span across the roof slope and are supported by timber trusses, which clear span the Hall below. Exterior cladding is wood siding on wood framing. The present roof is asphalt shingles.

No original construction drawings for the building or previous structural reports were available.

### **Structural Conditions/Issues – Comments and Recommendations:**

Structural conditions at the Brimfield Town Hall were observed (to the extent possible) during a brief tour of the facility on May 13, 2013. Generally speaking, floor and roof construction appears to be performing satisfactorily; there is no evidence of structural distress that would indicate significantly overstressed, deteriorated or failed structural members. Foundations appear to be performing adequately; there are no signs of significant, total or differential settlements.

Structural/structurally related conditions observed during site visit are noted below:

- The condition of the exterior wood siding appears to be generally satisfactory. Exterior, brick masonry joints appear to be in satisfactory condition as well. The spire at the top of the tower has deteriorated and is open to weather (as is another, centrally located spire).
- The capacity of the First and Second Floor framing was not determined; however, floor construction appears to be relatively stiff and is functioning as originally intended.
- The capacity of the roof framing was not determined; however, roof framing appears to be functioning as originally intended. Repair/reinforcing of roof trusses has been conducted in the past.
- As noted above, there have been water issues at the Ground Floor. Rubble stone and brick masonry foundation walls show evidence of water infiltration as well. Roof and perimeter drainage issues should be evaluated, in conjunction with future renovations to the facility.





- Wood framing may typically be protected (to a degree) by the ceiling construction; however, elsewhere it is unprotected. There are no sprinklers. Fire rating requirements should be reviewed in conjunction with future renovations to the facility.

### **Building Code Requirements and Additional Comments:**

#### Massachusetts State Building Code Requirements – General Comments:

Proposed renovations, alterations, repairs and additions to the Brimfield Town Hall would be governed by the provisions of the Massachusetts State Building Code (MSBC – 780 CMR 8<sup>th</sup> Edition) and the Massachusetts Existing Building Code (MEBC). These documents are based on amended versions of the 2009 International Building Code (IBC) and the 2009 International Existing Building Code (IEBC), respectively.

The MEBC allows the Design Team to choose one of three (3) compliance methods. Structurally, the Prescriptive Compliance Method is preferred. Section 101.5.4.0 of the Massachusetts Amendments (Chapter 34) would require that the existing building be investigated in sufficient detail to ascertain the effects of any proposed work (or change in use) in the area under consideration, and the entire building or structure and its foundations, if impacted by the proposed work or change in use.

#### Additions – General Comments:

The design and construction of any proposed additions would be conducted in accordance with the Code for new construction. Significant additions should be structurally separated from the existing building by an expansion (seismic) joint to avoid an increase in gravity loads and/or lateral loads to existing structural elements. Smaller additions can be structurally attached to the existing building, provided they do not increase the demand - capacity ratio of the existing lateral force resisting elements in the building by more than 10%.

#### Renovations/Alterations – General Comments:

Where proposed alterations to existing structural elements carrying gravity loads results in a stress increase of over 5%, the affected element would need to be reinforced or replaced to comply with the Code for new construction. Proposed alterations to existing structural elements carrying lateral load

(perimeter wood walls and Ground Floor masonry walls) which result in an increase in the demand - capacity ratio of over 10% should be avoided, if possible. Essentially, this means that removal of, or major alterations to these walls should be minimized. If this is not avoidable, more significant seismic upgrades/reinforcing will be required; potentially including the addition of lateral force resisting elements (wood shear walls, etc.).

**End of Structural Report**

TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**Town Hall**

21 Main Street

MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS

Prepared By:

Consulting Engineering Services  
510 Chapman Street, Suite 201  
Canton, MA 02021

July 3, 2013

**GENERAL**

The mechanical, electrical, plumbing, and fire protection systems were reviewed in conformance with the requirements of the following State and National codes and regulations, as applicable:

- Massachusetts State Building Code 8th Edition
- Massachusetts State Fire Prevention Regulations
- NFPA Latest Editions
- Massachusetts Plumbing Code
- Massachusetts Mechanical Code
- Massachusetts Electrical code (NEC 2011 Edition)
- Illuminating Engineering Society of North America (IESNA) Lighting Handbook
- ASHRAE 90.1 Latest Edition

The scope of this study does not include operational assessment of the fixtures and equipment reviewed; it includes only a brief visual review of the fixtures and equipment. Therefore notes regarding the condition of the fixtures and equipment may or may not be indicative of the actual condition of the systems and equipment and/or the expected life of the fixtures and equipment. Therefore it is recommended that services of a qualified technician be retained to evaluate the actual condition of fixtures and equipment prior to replacement.

## MECHANICAL

### HEATING

The main meeting chamber on the first floor is served by an oil fired, gravity vent, hot air furnace in the mechanical space on the ground floor with supply registers ducted to floor mount supply registers along the perimeter and underneath a built in bench seat along the front of building and return ducted from floor grilles in the middle of the chamber. Miscellaneous rooms on the ground floor including the public access television room are served by a smaller oil fired, gravity vent, hot air furnace with over head supply distribution ductwork.

Both units appear to be 20+ years old and are in poor condition. Each is piped independently to a single 275 gallon oil tank within the same room with fill and vent piping connections through the adjacent exterior wall on the side of the building. Each unit is controlled by a dedicated wall mounted dial thermostat.

The remainder of the building is heated with two-pipe steam radiators fed from an oil fired steam boiler in another mechanical room on the ground floor. The boiler is supplied from its own 275 gallon oil tank in an adjacent room with fill and vent connection piped through the exterior wall locally. The radiators are controlled by local manual valves at each. The boiler and steam distribution is old and in poor condition, specifically within the mechanical room itself.

There are small lengths of electric baseboard in the two restrooms at the rear of the ground floor.

### AIR CONDITIONING

There is no central air conditioning system in the building. There is a new inline dehumidification unit ducted in parallel with the supply and return lines to/from the smaller furnace serving the ground floor spaces. This unit has a small condensate pump adjacent to it with the discharge tube piped to the exterior of the building through an old window opening.

### VENTILATION

There is no mechanical ventilation system in the building but there are operable windows throughout that appear to be of adequate free area to meet the natural ventilation code requirements, except in the main meeting chamber where the required rates are much higher and in on the ground floor where the windows are very small and in some cases not operable.

There are ceiling cabinet fan/light combination units in each of the ground floor bathrooms.

### RECOMMENDATIONS

Replace the steam boiler plant with a hot water circulating plant and provide new hot water radiation equipment in place of the steam radiators for better control and comfort.

Replace all oil fired equipment with gas fired equipment for decreased energy usage due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

Replace existing thermostats with programmable type.

Provide new oil supply lines with code approved jacketing/membrane to each of the furnaces since currently neither of these lines includes this.

Provide mechanical ventilation using an automatic louver/damper system to serve both of the furnaces serving the ground floor and the main meeting chamber.

Reconfigure the ductwork of the inline dehumidification unit to draw from and supply back to the supply main from the furnace this unit is serving. As currently configured, there is a good chance that the unit could be short-circuiting air across the furnace then back through the dehumidifier which may explain why the unit was overflowing and not operating at all. Additionally provide interlock wiring such that the unit only operates when the furnace fan is on and also to shut down the unit upon detection of moisture in the overflow drain pan.

## **ELECTRICAL**

### EXISTING SYSTEMS

The existing building is served by a single 100amp, 120/240volt electric service. The service is overhead from a local utility company pole.

The service equipment consists of a 100amp, 240v-3p disconnect switch. From that switch there are (2) normal power panels and (2) emergency power panels. The emergency power panels are fed thru a manual transfer switch.

The equipment is approximately 20 years old and in fair condition.

The building has a gasoline powered generator located in the boiler room. This is a very old piece of equipment rated 3950watts at 120volts, single phase. It appears that if this is used, extension cords a plugged into it from electrical loads desired to be on emergency power. With the configuration of the emergency power panels and the fact that the police department once occupied the building, it is more likely that a portable generator was brought to the building and connected rather than use the unit in the boiler room.

The lighting in the building consists of surface mounted wraparound fluorescent fixtures, pendant mounted fluorescent strip fixtures, and original fixtures with incandescent lamps. Some of the small local light fixtures have had compact fluorescent screw-in lamps installed. The lighting in the building is in fair to poor condition and the lighting levels appear to be low.

The emergency lighting consists of individual self-contained battery units or similar fixtures attached to exit signs. This equipment is in fair condition and the coverage should be reviewed and additional fixtures added where necessary.

The exit signs are a mixture of older incandescent and newer fluorescent fixtures. This equipment is in fair condition. The coverage should be reviewed and additional exit signs added where necessary.

The building does have a fire alarm system manufactured by General Electric. This system consists of manual pull stations, smoke and heat detectors, horn/strobe units and a dialer which is manufactured by Silent Knight. This equipment is in fair condition.

There is evidence of the original knob-and-tube wiring in the attic space. This wiring is disconnected and no longer in service.

## RECOMMENDATIONS

Upgrade the lighting throughout the building to more energy efficient types with better light distribution and quality.

Review the coverage of the exit and emergency lighting and provide additional fixtures where required. Replace the existing fixtures with new energy efficient LED types.

Provide a new emergency generator with an automatic transfer switch.

## PLUMBING

### EXISTING SYSTEMS

Cold water is from a well. The pump for the system is in the boiler room, and it appears to be in poor to fair condition. The compression tank for the system is adjacent to the pump, and it appears to be in fair condition.

The exposed water piping in the basement is copper, and it appears to be in fair to good condition.

A tank type electric water heater provides hot water for the building. It appears to be in fair condition, however a hand marked date on the housing indicates that the heater is over 30

years, which is well beyond the life of a typical electric water heater, therefore the water heater should be replaced.

The laundry tub in the water heater room appears to be in fair to poor condition.

The water closets in the two restrooms are the floor mount vitreous china tank type units, they are accessible, and they appear to be in good condition. The water closets are not low flow.

The lavatories in the two restrooms are the wall mounted vitreous china type, they are accessible, and they appear to be in fair condition.

There are three grade mounted propane tanks. The appliances served by those propane tanks were in spaces that were locked during the walk-thru, so this study does not include such information.

There is a sump pump in the furnace/oil tank room.

#### RECOMMENDATIONS

The well pump and the expansion tank for the pump should be replaced.

The electric water heater should be replaced.

The laundry tub should be replaced.

The water closets should be replaced with low flow fixtures.

#### **FIRE PROTECTION**

The building does not have a sprinkler system.







Description	Note	Quantity	Unit	Price	Total
Basic Quantities		GFA		Girth	
basement		5,040	sf	442	lf
level 1		5,040	sf	442	lf
level 2		969	sf	157	lf
<b>General</b>					
New Entrance With Stair And Elevator At Rear Of Building					\$
Town Hall new entrance (see costplan)		1,403	sf	352.53	494,601
Sub Total - Direct Cost					494,601
General Conditions		16.00%			79,136
Overhead & Profit		16.00%			91,798
Design & Price Reserve		15.00%			99,830
Escalation	May-15	8.16%			62,454
Bond		2.40%			19,868
Soft Costs/Design Fees		30.00%			254,306
Total Project Cost					1,101,993
Town Hall Renovation And Addition					\$
Town Hall renovation and addition (see costplan)		12,452	sf	196.42	2,445,836
Sub Total - Direct Cost					2,445,836
General Conditions		10.00%			244,584
Overhead & Profit		12.00%			322,850
Design & Price Reserve		15.00%			451,991
Escalation	May-15	8.16%			282,765
Bond		1.60%			59,968
Soft Costs/Design Fees		30.00%			1,142,398
Total Project Cost					4,950,392
Accessible Entrance Door					\$
add push button operator to door		1	ea	3,341.00	3,341
wire and conduit		100	lf	7.11	711
cut and patch		1	ls	257.79	258
Sub Total - Direct Cost					4,310
General Conditions		20.00%			862
Overhead & Profit		23.00%			1,190
Design & Price Reserve		15.00%			954
Escalation	May-15	8.16%			597
Bond		3.00%			237
Soft Costs/Design Fees		30.00%			2,445
Total Project Cost					10,595
Town Hall Annex Lot					\$
regrade lawn area		3,784	sf	0.12	454
seed lawn		3,784	sf	0.48	1,816
excavate trench		13	cy	11.65	151



Description	Note	Quantity	Unit	Price	Total
gravel filled trench at west wall		13	cy	43.56	566
perforated drain		85	lf	10.45	888
filter fabric		765	sf	1.60	1,224
disposal off site - 10 mile round trip		13	cy	24.89	324
Sub Total - Direct Cost					5,423
General Conditions		20.00%			1,085
Overhead & Profit		23.00%			1,497
Design & Price Reserve		15.00%			1,201
Escalation	May-15	8.16%			751
Bond		3.00%			299
Soft Costs/Design Fees		30.00%			3,077
Total Project Cost					13,333
Copper Rain Leaders					\$
demo plastic pipe rain leader		2	loc	72.60	145
replace cleanout		2	loc	231.08	462
provide sleeve for expansion of copper downspout		2	loc	280.75	562
disposal		1	ea	168.45	168
Sub Total - Direct Cost					1,337



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			267
Overhead & Profit		23.00%			369
Design & Price Reserve		15.00%			296
Escalation	May-15	8.16%			185
Bond		3.00%			74
Soft Costs/Design Fees		30.00%			758
<b>Total Project Cost</b>					<b>\$3,286</b>
<b>Brick and Stone Foudations</b>					
repoint brick and stone foundation 5' tall	20%	442	sf	31.67	\$ 13,998
<b>Sub Total - Direct Cost</b>					<b>13,998</b>
General Conditions		20.00%			2,800
Overhead & Profit		23.00%			3,864
Design & Price Reserve		15.00%			3,099
Escalation	May-15	8.16%			1,939
Bond		3.00%			771
Soft Costs/Design Fees		30.00%			7,941
<b>Total Project Cost</b>					<b>34,412</b>
<b>Foundation Wall Moisture</b>					
excavate adjacent to building		786	cy	18.82	\$ 14,793
perforated drain at perimeter of building		442	lf	10.45	4,619
pipe to pumping station	allowance	100	lf	47.96	4,796
connect to existing pumping station		1	ea	1,452.00	1,452
pipe to catch basin	allowance	100	lf	47.96	4,796
connect to existing catch basin		1	ea	1,452.00	1,452
gunite		5,304	sf	4.22	22,383
foundation damproofing		5,304	sf	1.29	6,842
drainage stone from grade	2' wide	393	cy	43.56	17,119
filter fabric		11,492	sf	1.60	18,387
backfill & compaction		393	cy	27.80	10,925
disposal off site		1	ea	11.96	12
patch paving where disturbed	allowance	200	sf	7.26	1,452
<b>Sub Total - Direct Cost</b>					<b>109,028</b>
General Conditions		20.00%			21,806
Overhead & Profit		23.00%			30,092
Design & Price Reserve		15.00%			24,139
Escalation	May-15	8.16%			15,101
Bond		2.40%			4,804
Soft Costs/Design Fees		30.00%			61,491
<b>Total Project Cost</b>					<b>\$266,461</b>



Description	Note	Quantity	Unit	Price	Total
Under-floor drainage system					\$
demo wood flooring		11,049	sf	1.67	18,452
demo concrete slab		11,049	sf	6.60	72,923
demo wood partitions		5,443	sf	2.57	13,989
dumpster rental		4	weeks	734.71	2,939
load & truck	10 mile round trij	80	cy	55.27	4,422
dump charges		32	ton	87.12	2,788
under-floor drainage system - perimeter		442	lf	10.45	4,619
pipe to pump station	allowance	100	lf	47.96	4,796
pit excavation inside building		274	cy	23.55	6,453
disposal off site		274	cy	11.96	3,277
6" stone base		205	cy	41.41	8,489
vapor barrier		11,049	sf	0.27	2,983
2" rigid insulation	allowance	100	lf	2.02	202
5" concrete slab		171	cy	160.71	27,481
cure and finish slab		11,049	sf	0.96	10,607
premium for working inside existing building	100%	1	ea	68,907.00	68,907
new partitions - moisture resistant	basement	5,443	sf	13.73	74,732
partitions around exterior wall w/insulation	basement	5,304	sf	13.73	72,824
paint partitions	basement	10,747	sf	1.09	11,714
Sub Total - Direct Cost					412,597
General Conditions		16.00%			66,016
Overhead & Profit		18.00%			86,150
Design & Price Reserve		15.00%			84,714
Escalation	May-15	8.16%			52,997
Bond		2.40%			16,859
Soft Costs/Design Fees		30.00%			215,800
Total Project Cost					\$935,133
Remove Paint From Exposed Pipes					\$
remove paint from exposed pipes in lift and ramp a		100	lf	12.10	1,210
paint exposed pipes		100	lf	6.13	613
Sub Total - Direct Cost					1,823
General Conditions		20.00%			365
Overhead & Profit		23.00%			503
Design & Price Reserve		15.00%			404
Escalation	May-15	8.16%			253
Bond		3.00%			100
Soft Costs/Design Fees		30.00%			1,034
Total Project Cost					\$4,482
Add storm panels					\$
add storm panels to existing single pane wood windows		252	sf	13.71	3,455
Sub Total - Direct Cost					3,455



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			691
Overhead & Profit		23.00%			954
Design & Price Reserve		15.00%			765
Escalation	May-15	8.16%			479
Bond		3.00%			190
Soft Costs/Design Fees		30.00%			1,960
<b>Total Project Cost</b>					<b>\$8,494</b>
<b>Patch Openings In Mechanical #1</b>					<b>\$</b>
demo damaged ceiling	allowance	442	sf	1.74	769
dumpster rental			1 weeks	734.71	735
load & truck	10 mile round trij	20	cy	55.27	1,105
dump charges			8 ton	87.12	697
new drywall ceiling	allowance	442	sf	5.23	2,312
paint drywall ceiling	allowance	442	sf	1.19	526
seal duct penetrations	allowance	50	lf	4.53	227
<b>Sub Total - Direct Cost</b>					<b>6,371</b>
General Conditions		20.00%			1,274
Overhead & Profit		23.00%			1,758
Design & Price Reserve		15.00%			1,410
Escalation	May-15	8.16%			882
Bond		3.00%			351
Soft Costs/Design Fees		30.00%			3,614
<b>Total Project Cost</b>					<b>\$15,660</b>
<b>Mechanical #1 Foundation</b>					<b>\$</b>
remove 2 layers of brick	small area	33	lf	11.87	392
dumpster rental			1 weeks	734.71	735
load & truck	10 mile round trij	20	cy	55.27	1,105
dump charges			8 ton	87.12	697
replace 2 layers of brick on top of foundation wall	small area	33	lf	38.91	1,284
repoint brick chimney 4' above slab		24	sf	31.67	760
<b>Sub Total - Direct Cost</b>					<b>4,973</b>
General Conditions		20.00%			995
Overhead & Profit		23.00%			1,373
Design & Price Reserve		15.00%			1,101
Escalation	May-15	8.16%			689
Bond		3.00%			274
Soft Costs/Design Fees		30.00%			2,822
<b>Total Project Cost</b>					<b>12,227</b>



Description	Note	Quantity	Unit	Price	Total
<b>Patch Openings In Mechanical #2</b>					<b>\$</b>
demo damaged ceiling	allowance	150	sf	1.74	261
new drywall ceiling	allowance	150	sf	5.11	767
paint drywall ceiling	allowance	150	sf	1.36	204
seal duct penetrations	allowance	50	lf	4.53	227
<b>Sub Total - Direct Cost</b>					<b>1,459</b>
General Conditions		20.00%			292
Overhead & Profit		23.00%			403
Design & Price Reserve		15.00%			323
Escalation	May-15	8.16%			202
Bond		3.00%			80
Soft Costs/Design Fees		30.00%			828
<b>Total Project Cost</b>					<b>\$3,587</b>
<b>Mechanical #2 Foundation</b>					<b>\$</b>
remove 2 layers of brick		18	lf	11.87	214
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
replace 2 layers of brick on top of foundation wall		18	lf	38.91	700
repoint upper part of brick wall		108	sf	31.67	3,420
<b>Sub Total - Direct Cost</b>					<b>6,871</b>
General Conditions		20.00%			1,374
Overhead & Profit		23.00%			1,896
Design & Price Reserve		15.00%			1,521
Escalation	May-15	8.16%			952
Bond		3.00%			378
Soft Costs/Design Fees		30.00%			3,898
<b>Total Project Cost</b>					<b>\$16,890</b>
<b>Repair Exterior Wall Next To Lift</b>					<b>\$</b>
repair interior of exterior wall next to lift - plaster	small area	36	sf	9.33	336
paint wall to match existing	small area	36	sf	9.19	331
<b>Sub Total - Direct Cost</b>					<b>667</b>
General Conditions		20.00%			133
Overhead & Profit		23.00%			184
Design & Price Reserve		15.00%			148
Escalation	May-15	8.16%			92
Bond		3.00%			37
Soft Costs/Design Fees		30.00%			378
<b>Total Project Cost</b>					<b>\$1,639</b>



Description	Note	Quantity	Unit	Price	Total
<b>Fire Stopping At Ground Floor</b>					<b>\$</b>
fire stopping at ground floor		11,049	sf	0.45	4,972
	776.18				
Sub Total - Direct Cost					4,972
General Conditions		20.00%			994
Overhead & Profit		23.00%			1,372
Design & Price Reserve		15.00%			1,101
Escalation	May-15	8.16%			689
Bond		3.00%			274
Soft Costs/Design Fees		30.00%			2,821
<b>Total Project Cost</b>					<b>\$12,223</b>
<b>Interior Door Widening</b>					<b>\$</b>
modify partition for door clearance		10	loc	2,890.00	28,900
cut and patch		1	ls	1,445.00	1,445
Sub Total - Direct Cost					30,345
General Conditions		20.00%			6,069
Overhead & Profit		23.00%			8,375
Design & Price Reserve		15.00%			6,718
Escalation	May-15	8.16%			4,203
Bond		3.00%			1,671
Soft Costs/Design Fees		30.00%			17,214
<b>Total Project Cost</b>					<b>\$74,595</b>
<b>Interior Door Hardware Replacement</b>					<b>\$</b>
replace knob set with levers		18	ea	1,003.76	18,068
disposal		1	ea	435.60	436
Sub Total - Direct Cost					18,504
General Conditions		20.00%			3,701
Overhead & Profit		23.00%			5,107
Design & Price Reserve		15.00%			4,097
Escalation	May-15	8.16%			2,563
Bond		3.00%			1,019
Soft Costs/Design Fees		30.00%			10,497
<b>Total Project Cost</b>					<b>45,488</b>
<b>Wall &amp; Ceilings in Toilet Rooms #1 &amp; #2</b>					<b>\$</b>
remove and salvage grab bars		4	ea	72.60	290
repair walls as necessary		512	sf	4.94	2,529
repair ceilings as necessary		128	sf	6.98	893
reinstall grab bars		4	ea	69.68	279
Sub Total - Direct Cost					3,991



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			798
Overhead & Profit		23.00%			1,101
Design & Price Reserve		15.00%			884
Escalation	May-15	8.16%			553
Bond		3.00%			220
Soft Costs/Design Fees		30.00%			2,264
<b>Total Project Cost</b>					<b>9,811</b>
<b>Wood Ramp</b>					
\$					
demo wood ramp		27	sf	14.52	392
disposal		1	ea	56.92	57
new ramp	allowance	35	sf	47.97	1,679
hand rails		16	lf	154.20	2,467
paint hand rails		16	lf	4.29	69
<b>Sub Total - Direct Cost</b>					<b>4,664</b>
General Conditions		20.00%			933
Overhead & Profit		23.00%			1,287
Design & Price Reserve		15.00%			1,033
Escalation	May-15	8.16%			646
Bond		3.00%			257
Soft Costs/Design Fees		30.00%			2,646
<b>Total Project Cost</b>					<b>11,466</b>
<b>Step Down To Unassigned Room #7</b>					
\$					
install handrails	allowance	6	lf	157.35	944
paint hand rails	small area	6	lf	9.19	55
signage		1	ea	295.50	296
<b>Sub Total - Direct Cost</b>					<b>1,295</b>
General Conditions		20.00%			259
Overhead & Profit		23.00%			357
Design & Price Reserve		15.00%			287
Escalation	May-15	8.16%			179
Bond		3.00%			71
Soft Costs/Design Fees		30.00%			734
<b>Total Project Cost</b>					<b>3,182</b>
<b>Wood Ramp Corridor #2 to #3</b>					
\$					
demo wood ramp		43	sf	14.52	624
disposal		1	ea	90.60	91
new ramp		50	sf	47.97	2,399
hand rails		16	lf	179.90	2,878
paint hand rails		16	lf	4.29	69
<b>Sub Total - Direct Cost</b>					<b>6,061</b>





Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			1,212
Overhead & Profit		23.00%			1,673
Design & Price Reserve		15.00%			1,342
Escalation	May-15	8.16%			840
Bond		3.00%			334
Soft Costs/Design Fees		30.00%			3,439
<b>Total Project Cost</b>					<b>14,901</b>
<b>Chase Wall</b>					
infill opening floor to ceiling		36	sf	26.10	\$ 940
<b>Sub Total - Direct Cost</b>					<b>940</b>
General Conditions		20.00%			188
Overhead & Profit		23.00%			259
Design & Price Reserve		15.00%			208
Escalation	May-15	8.16%			130
Bond		3.00%			52
Soft Costs/Design Fees		30.00%			533
<b>Total Project Cost</b>					<b>2,310</b>
<b>Door To Mechanical #1</b>					
reconfigure door/ramp as required - 1 door, 50 sf ramp	allowance	1	ea	10,506.25	\$ 10,506
<b>Sub Total - Direct Cost</b>					<b>10,506</b>
General Conditions		20.00%			2,101
Overhead & Profit		23.00%			2,900
Design & Price Reserve		15.00%			2,326
Escalation	May-15	8.16%			1,455
Bond		3.00%			579
Soft Costs/Design Fees		30.00%			5,960
<b>Total Project Cost</b>					<b>25,827</b>
<b>Plaster And Paint Corridor #3</b>					
repair plaster		144	sf	3.09	\$ 445
paint wall		144	sf	1.09	157
<b>Sub Total - Direct Cost</b>					<b>602</b>
General Conditions		20.00%			120
Overhead & Profit		23.00%			166
Design & Price Reserve		15.00%			133
Escalation	May-15	8.16%			83
Bond		3.00%			33
Soft Costs/Design Fees		30.00%			341
<b>Total Project Cost</b>					<b>1,478</b>



Description	Note	Quantity	Unit	Price	Total
<b>Brick/Concrete Steps</b>					<b>\$</b>
remove brick and concrete steps		6	lfr	14.71	88
remove pipe handrail		6	lfr	3.08	18
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trij	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new metal pan steps		6	lfr	130.69	784
radial rubber stair tread/riser		6	lfr	19.56	117
guard rail		6	lf	179.90	1,079
paint guard rail	small area	6	lf	14.70	88
<b>Sub Total - Direct Cost</b>					<b>4,711</b>
General Conditions		20.00%			942
Overhead & Profit		23.00%			1,300
Design & Price Reserve		15.00%			1,043
Escalation	May-15	8.16%			652
Bond		3.00%			259
Soft Costs/Design Fees		30.00%			2,672
<b>Total Project Cost</b>					<b>11,579</b>
<b>Relocate Oil Tank</b>					<b>\$</b>
relocate oil tank		1	ea	1,279.31	1,279
<b>Sub Total - Direct Cost</b>					<b>1,279</b>
General Conditions		20.00%			256
Overhead & Profit		23.00%			353
Design & Price Reserve		15.00%			283
Escalation	May-15	8.16%			177
Bond		3.00%			70
Soft Costs/Design Fees		30.00%			725
<b>Total Project Cost</b>					<b>3,143</b>
<b>Stairs</b>					<b>\$</b>
handrails		85	lf	154.20	13,107
paint hand rails		85	lf	4.29	365
infill area under nosings	wood	245	lfr	22.04	5,400
<b>Sub Total - Direct Cost</b>					<b>18,872</b>
General Conditions		20.00%			3,774
Overhead & Profit		23.00%			5,209
Design & Price Reserve		15.00%			4,178
Escalation	May-15	8.16%			2,614
Bond		3.00%			1,039
Soft Costs/Design Fees		30.00%			10,706
<b>Total Project Cost</b>					<b>46,392</b>



Description	Note	Quantity	Unit	Price	Total
<b>New Landing</b>					\$
new concrete landing		50	sf	102.77	5,139
concrete steps on grade	allowance	8	lfr	107.50	860
rubber on landing		50	sf	122.67	6,134
rubber on steps		8	lfr	122.67	981
guardrails		8	lf	107.32	859
paint guardrails		8	lf	14.70	118
<b>Sub Total - Direct Cost</b>					<u>14,091</u>
General Conditions		20.00%			2,818
Overhead & Profit		23.00%			3,889
Design & Price Reserve		15.00%			3,120
Escalation	May-15	8.16%			1,952
Bond		3.00%			776
Soft Costs/Design Fees		30.00%			7,994
<b>Total Project Cost</b>					<u><u>34,640</u></u>
<b>First Floor</b>					
<b>Replace Door Hardware</b>					\$
replace knob set with levers		9	ea	1,003.76	9,034
disposal		1	ea	217.80	218
<b>Sub Total - Direct Cost</b>					<u>9,252</u>
General Conditions		20.00%			1,850
Overhead & Profit		23.00%			2,553
Design & Price Reserve		15.00%			2,048
Escalation	May-15	8.16%			1,281
Bond		3.00%			510
Soft Costs/Design Fees		30.00%			5,248
<b>Total Project Cost</b>					<u><u>22,742</u></u>
<b>Exterior Door Hardware</b>					\$
remove exterior door hardware		4	ea	68.97	276
disposal		1	ea	96.80	97
exterior door hardware		4	ea	1,563.23	6,253
<b>Sub Total - Direct Cost</b>					<u>6,626</u>
General Conditions		20.00%			1,325
Overhead & Profit		23.00%			1,829
Design & Price Reserve		15.00%			1,467
Escalation	May-15	8.16%			918
Bond		3.00%			365
Soft Costs/Design Fees		30.00%			3,759
<b>Total Project Cost</b>					<u><u>16,289</u></u>



Description	Note	Quantity	Unit	Price	Total
<b>Meeting Room Paint</b>					\$
paint with stain blocker - water damaged areas		930	sf	1.53	1,423
paint - match existing		1,500	sf	1.09	1,635
Sub Total - Direct Cost					4,327
General Conditions		20.00%			865
Overhead & Profit		23.00%			1,194
Design & Price Reserve		15.00%			958
Escalation	May-15	8.16%			599
Bond		3.00%			238
Soft Costs/Design Fees		30.00%			2,454
<b>Total Project Cost</b>					10,635
<b>Stage Curtain</b>					\$
remove stage curtain		15	lf	14.52	218
disposal		1	ea	72.60	73
drywall ceiling		248	sf	5.11	1,267
paint ceiling		248	sf	1.36	337
Sub Total - Direct Cost					1,895
General Conditions		20.00%			379
Overhead & Profit		23.00%			523
Design & Price Reserve		15.00%			420
Escalation	May-15	8.16%			263
Bond		3.00%			104
Soft Costs/Design Fees		30.00%			1,075
<b>Total Project Cost</b>					4,659
<b>Add storm panels</b>					\$
add storm panels to existing single pane wood windows		270	sf	13.71	3,702
Sub Total - Direct Cost					3,702
General Conditions		20.00%			740
Overhead & Profit		23.00%			1,022
Design & Price Reserve		15.00%			820
Escalation	May-15	8.16%			513
Bond		3.00%			204
Soft Costs/Design Fees		30.00%			2,100
<b>Total Project Cost</b>					\$9,101
<b>Repair Meeting Room Exterior Door</b>					\$
fill splits and joints in exterior doors		2	leaf	360.93	722
paint exterior doors		2	leaf	131.39	263
Sub Total - Direct Cost					985



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			197
Overhead & Profit		23.00%			272
Design & Price Reserve		15.00%			218
Escalation	May-15	8.16%			136
Bond		3.00%			54
Soft Costs/Design Fees		30.00%			559
<b>Total Project Cost</b>					<b>2,421</b>
<b>Meeting Room Threshold</b>					
					\$
remove threshold		6	lf	7.26	44
disposal		1	ea	24.20	24
new wood threshold		6	lf	28.78	173
<b>Sub Total - Direct Cost</b>					<b>241</b>
General Conditions		20.00%			48
Overhead & Profit		23.00%			66
Design & Price Reserve		15.00%			53
Escalation	May-15	8.16%			33
Bond		3.00%			13
Soft Costs/Design Fees		30.00%			136
<b>Total Project Cost</b>					<b>590</b>
<b>Stage Railings</b>					
					\$
add handrails up stairs at stage		12	lf	154.20	1,850
paint handrails		12	lf	4.29	51
<b>Sub Total - Direct Cost</b>					<b>1,901</b>
General Conditions		20.00%			380
Overhead & Profit		23.00%			525
Design & Price Reserve		15.00%			421
Escalation	May-15	8.16%			263
Bond		3.00%			105
Soft Costs/Design Fees		30.00%			1,079
<b>Total Project Cost</b>					<b>4,674</b>
<b>Wall and Ceiling Repairs In Storage #3</b>					
					\$
repair walls	allowance	576	sf	3.44	1,981
repair ceilings	allowance	113	sf	4.47	505
paint walls		576	sf	1.09	628
paint ceilings		113	sf	1.36	154
<b>Sub Total - Direct Cost</b>					<b>3,268</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			654
Overhead & Profit		23.00%			902
Design & Price Reserve		15.00%			724
Escalation		8.16%			453
Bond		3.00%			180
Soft Costs/Design Fees		30.00%			1,854
<b>Total Project Cost</b>					<b>8,035</b>
<b>Replace Handrail In Storage #2 #3</b>					
					\$
remove existing wood handrail		16	lf	3.63	58
disposal		1	ea	48.40	48
new wood handrail		16	lf	154.57	2,473
paint handrail		16	lf	14.70	235
<b>Sub Total - Direct Cost</b>					<b>2,814</b>
General Conditions		20.00%			563
Overhead & Profit		23.00%			777
Design & Price Reserve		15.00%			623
Escalation		8.16%			390
Bond		3.00%			155
Soft Costs/Design Fees		30.00%			1,597
<b>Total Project Cost</b>					<b>6,919</b>
<b>Repair Town Clerk #1</b>					
					\$
repair water stains	allowance	684	sf	3.44	2,353
repair ceiling damage (cracks)	allowance	188	sf	4.47	840
paint wall		684	lf	1.09	746
paint ceiling		188	sf	1.36	256
<b>Sub Total - Direct Cost</b>					<b>4,195</b>
General Conditions		20.00%			839
Overhead & Profit		23.00%			1,158
Design & Price Reserve		15.00%			929
Escalation		8.16%			581
Bond		3.00%			231
Soft Costs/Design Fees		30.00%			2,380
<b>Total Project Cost</b>					<b>10,313</b>
<b>Repair Lobby</b>					
					\$
repair water stains		828	sf	3.44	2,848
repair ceiling damage (cracks)		255	sf	4.47	1,140
paint wall		828	lf	1.09	903
paint ceiling		255	sf	1.36	347
<b>Sub Total - Direct Cost</b>					<b>5,238</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			1,048
Overhead & Profit		23.00%			1,446
Design & Price Reserve		15.00%			1,160
Escalation		8.16%			726
Bond		3.00%			289
Soft Costs/Design Fees		30.00%			2,972
<b>Total Project Cost</b>					<b>12,879</b>
<b>Lobby Stair</b>					<b>\$</b>
demo lobby stair		70	lfr	33.88	2,372
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
steel pan stair		70	lfr	130.69	9,148
radial rubber stair tread/riser		70	lfr	19.56	1,369
new guard rail		24	lf	178.50	4,284
new hand rail		24	lf	154.20	3,701
paint guard rail		24	lf	14.70	353
paint hand rail		24	lf	4.29	103
cut and patch as required		1	ea	1,193.35	1,193
<b>Sub Total - Direct Cost</b>					<b>25,060</b>
General Conditions		20.00%			5,012
Overhead & Profit		23.00%			6,917
Design & Price Reserve		15.00%			5,548
Escalation		8.16%			3,471
Bond		3.00%			1,380
Soft Costs/Design Fees		30.00%			14,216
<b>Total Project Cost</b>					<b>61,604</b>
<b>Sand and Refinish Wood Stairs</b>					<b>\$</b>
remove non slip adhesive strips on stairs		70	lf	8.84	619
sand and refinish steps - level 1		70	lfr	9.89	692
<b>Sub Total - Direct Cost</b>					<b>1,311</b>
General Conditions		20.00%			262
Overhead & Profit		23.00%			362
Design & Price Reserve		15.00%			290
Escalation		8.16%			182
Bond		3.00%			72
Soft Costs/Design Fees		30.00%			744
<b>Total Project Cost</b>					<b>3,223</b>



Description	Note	Quantity	Unit	Price	Total
<b>Work Around Lift</b>					\$
remove existing wall around lift		348	sf	2.56	891
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trij	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
partitions		348	sf	13.73	4,778
paint partitions		348	sf	1.09	379
relocate lift control as required	allowance	1	ea	514.00	514
<b>Sub Total - Direct Cost</b>					9,099
General Conditions		20.00%			1,820
Overhead & Profit		23.00%			2,511
Design & Price Reserve		15.00%			2,015
Escalation		8.16%			1,260
Bond		3.00%			501
Soft Costs/Design Fees		30.00%			5,162
<b>Total Project Cost</b>					22,368
<b>Install ADA Restroom</b>					\$
install ADA restroom		1	ea	12,975.91	12,976
<b>Sub Total - Direct Cost</b>					12,976
General Conditions		20.00%			2,595
Overhead & Profit		23.00%			3,581
Design & Price Reserve		15.00%			2,873
Escalation		8.16%			1,797
Bond		3.00%			715
Soft Costs/Design Fees		30.00%			7,361
<b>Total Project Cost</b>					31,898
<b>Second Floor</b>					
<b>Add storm panels</b>					\$
add storm panels to existing single pane wood windows		5	ea	203.93	1,020
repair broken pains of glass	allowance	5	ea	118.48	592
disposal		1	ea	48.40	48
<b>Sub Total - Direct Cost</b>					1,660
General Conditions		20.00%			332
Overhead & Profit		23.00%			458
Design & Price Reserve		15.00%			368
Escalation	May-15	8.16%			230
Bond		3.00%			91
Soft Costs/Design Fees		30.00%			942
<b>Total Project Cost</b>					\$4,081





Description	Note	Quantity	Unit	Price	Total
<b>Repair Ceilings In Meeting Room, Stair and Attic</b>					<b>\$</b>
repair water damaged ceilings as required		3,325	sf	4.01	13,333
paint ceiling to match existing		3,325	sf	1.36	4,522
<b>Sub Total - Direct Cost</b>					<b>17,855</b>
General Conditions		20.00%			3,571
Overhead & Profit		23.00%			4,928
Design & Price Reserve		15.00%			3,953
Escalation		8.16%			2,473
Bond		3.00%			983
Soft Costs/Design Fees		30.00%			10,129
<b>Total Project Cost</b>					<b>43,892</b>
<b>Sand and Refinish Wood Stairs</b>					<b>\$</b>
remove non slip adhesive strips on stairs		60	lf	8.84	530
sand and refinish steps - attic		60	lfr	9.90	594
<b>Sub Total - Direct Cost</b>					<b>1,124</b>
General Conditions		20.00%			225
Overhead & Profit		23.00%			310
Design & Price Reserve		15.00%			249
Escalation		8.16%			156
Bond		3.00%			62
Soft Costs/Design Fees		30.00%			638
<b>Total Project Cost</b>					<b>2,764</b>
<b>Stair</b>					<b>\$</b>
demo stair		70	lfr	33.88	2,372
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new steel pan stair		70	lfr	130.69	9,148
radial rubber stair tread/riser		70	lfr	19.56	1,369
new guard rail		24	lf	179.90	4,318
new hand rail		24	lf	154.20	3,701
paint guard rail		24	lf	14.70	353
paint hand rail		24	lf	4.29	103
cut and patch as required		1	ea	1,195.05	1,195
<b>Sub Total - Direct Cost</b>					<b>25,096</b>
General Conditions		20.00%			5,019
Overhead & Profit		23.00%			6,926
Design & Price Reserve		15.00%			5,556
Escalation		8.16%			3,476
Bond		3.00%			1,382
Soft Costs/Design Fees		30.00%			14,237
<b>Total Project Cost</b>					<b>61,692</b>
<b>Vinyl Asbestos In Attic Access Space</b>					<b>\$</b>



Description	Note	Quantity	Unit	Price	Total
remove asbestos in attic access space		108	sf	4.84	523
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trij	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
vct floor		108	sf	2.94	318
vinyl base		41	lf	2.48	102
Sub Total - Direct Cost					3,480
General Conditions		20.00%			696
Overhead & Profit		23.00%			960
Design & Price Reserve		15.00%			770
Escalation		8.16%			482
Bond		3.00%			192
Soft Costs/Design Fees		30.00%			1,974
Total Project Cost					8,554
Attic Floor					\$
blown in insulation		2,623	sf	1.21	3,174
add attic ventilation - add exhasut fan	allowance	1	ea	829.77	830
Sub Total - Direct Cost					4,004
General Conditions		20.00%			801
Overhead & Profit		23.00%			1,105
Design & Price Reserve		15.00%			887
Escalation		8.16%			555
Bond		3.00%			221
Soft Costs/Design Fees		30.00%			2,272
Total Project Cost					9,845
Remove Bird/Bat Droppings					\$
remove bird/bat droppings	labor allowance	2	day	401.55	803
seal openings to prevent bird/bat access	allowance	1	ea	2,132.00	2,132
Sub Total - Direct Cost					2,935
General Conditions		20.00%			587
Overhead & Profit		23.00%			810
Design & Price Reserve		15.00%			650
Escalation		8.16%			407
Bond		3.00%			162
Soft Costs/Design Fees		30.00%			1,665
Total Project Cost					7,216



Description	Note	Quantity	Unit	Price	Total
<b>EXTERIOR</b>					
Re-attach gutter on east side of building					\$
re-attach gutter		79	lf	8.42	665
Sub Total - Direct Cost					665
General Conditions		20.00%			133
Overhead & Profit		23.00%			184
Design & Price Reserve		15.00%			147
Escalation	May-15	8.16%			92
Bond		3.00%			37
Soft Costs/Design Fees		30.00%			377
Total Project Cost					1,635
<b>Copper Rain Leaders</b>					
					\$
demo plastic pipe rain leader		2	loc	72.60	145
replace cleanout		2	loc	231.08	462
provide sleeve for expansion of copper downspout		2	loc	280.75	562
replace/repoint damaged bricks	allowance	50	sf	31.67	1,584
disposal		1	ea	168.45	168
Sub Total - Direct Cost					2,921
General Conditions		20.00%			584
Overhead & Profit		23.00%			806
Design & Price Reserve		15.00%			647
Escalation	May-15	8.16%			405
Bond		3.00%			161
Soft Costs/Design Fees		30.00%			1,657
Total Project Cost					\$7,181
<b>Front Stairs</b>					
					\$
guardrail on landing side of railing	allowance	12	lf	179.90	2,159
paint guard rail		12	lf	14.70	176
Sub Total - Direct Cost					2,335
General Conditions		20.00%			467
Overhead & Profit		23.00%			644
Design & Price Reserve		15.00%			517
Escalation	May-15	8.16%			323
Bond		3.00%			129
Soft Costs/Design Fees		30.00%			1,325
Total Project Cost					5,740
<b>Front Stairs</b>					
					\$
secure lose metal handrails		21	lf	17.13	360
Sub Total - Direct Cost					360



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			72
Overhead & Profit		23.00%			99
Design & Price Reserve		15.00%			80
Escalation	May-15	8.16%			50
Bond		3.00%			20
Soft Costs/Design Fees		30.00%			204
<b>Total Project Cost</b>					<b>885</b>
<b>Front Stair</b>					
\$					
sand and prep stairs		58	lfr	2.92	169
remove non-slip strips		58	lf	8.84	513
disposal		1	ea	48.40	48
paint front stairs		58	lfr	6.88	399
new non-slip strips		58	lf	3.80	220
<b>Sub Total - Direct Cost</b>					<b>1,349</b>
General Conditions		20.00%			270
Overhead & Profit		23.00%			372
Design & Price Reserve		15.00%			299
Escalation		8.16%			187
Bond		3.00%			74
Soft Costs/Design Fees		30.00%			765
<b>Total Project Cost</b>					<b>3,316</b>
<b>Peeling Paint</b>					
\$					
scrape, prime and paint envelope of building - siding/trim/window/door trim/fascia/porch	5% allowance	393	sf	12.25	4,814
<b>Sub Total - Direct Cost</b>					<b>4,814</b>
General Conditions		20.00%			963
Overhead & Profit		23.00%			1,329
Design & Price Reserve		15.00%			1,066
Escalation	May-15	8.16%			667
Bond		3.00%			265
Soft Costs/Design Fees		30.00%			2,731
<b>Total Project Cost</b>					<b>11,835</b>
<b>Front Porch Wall Intersection</b>					
\$					
cut wood siding back 1" from shingles		30	lf	8.15	245
disposal		1	ea	72.60	73
install metal flashing to roof		30	lf	16.85	506
patch siding as required		30	lf	37.31	1,119
patch roof as required		30	lf	39.31	1,179
<b>Sub Total - Direct Cost</b>					<b>3,122</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			624
Overhead & Profit		23.00%			862
Design & Price Reserve		15.00%			691
Escalation	May-15	8.16%			432
Bond		3.00%			172
Soft Costs/Design Fees		30.00%			1,771
<b>Total Project Cost</b>					<b>7,674</b>
<b>Repoint 3 Brick Chimneys</b>					
repoint 2 chimneys		160	sf	31.67	5,067
re-set chimney caps		3	ea	201.26	604
staging		160	sf	3.24	518
<b>Sub Total - Direct Cost</b>					<b>6,189</b>
General Conditions		20.00%			1,238
Overhead & Profit		23.00%			1,708
Design & Price Reserve		15.00%			1,370
Escalation	May-15	8.16%			857
Bond		3.00%			341
Soft Costs/Design Fees		30.00%			3,511
<b>Total Project Cost</b>					<b>15,214</b>
<b>Finials</b>					
replace missing boards at finials	2 locations	2	loc	388.02	776
paint finials		2	ea	357.27	715
<b>Sub Total - Direct Cost</b>					<b>1,491</b>
General Conditions		20.00%			298
Overhead & Profit		23.00%			411
Design & Price Reserve		15.00%			330
Escalation	May-15	8.16%			206
Bond		3.00%			82
Soft Costs/Design Fees		30.00%			845
<b>Total Project Cost</b>					<b>3,663</b>
<b>Flat Roof Replacement</b>					
demo roof		266	sf	1.78	473
new membrane roof		266	sf	21.62	5,751
<b>Sub Total - Direct Cost</b>					<b>6,224</b>
General Conditions		20.00%			1,245
Overhead & Profit		23.00%			1,718
Design & Price Reserve		15.00%			1,378
Escalation	May-15	8.16%			862
Bond		3.00%			343
Soft Costs/Design Fees		30.00%			3,531
<b>Total Project Cost</b>					<b>15,301</b>



Description	Note	Quantity	Unit	Price	Total
<b>Insulate walls</b>					
blown in insulation at first and second floors		7,188	sf	1.21	8,697
Sub Total - Direct Cost					8,697
General Conditions		20.00%			1,739
Overhead & Profit		23.00%			2,400
Design & Price Reserve		15.00%			1,925
Escalation	May-15	8.16%			1,204
Bond		3.00%			479
Soft Costs/Design Fees		30.00%			4,933
<b>Total Project Cost</b>					<b>21,377</b>

**Mechanical**

<b>Replace Steam Boiler Plant</b>					
remove steam boiler and radiator heating system	allowance	11,049	sf	2.80	30,937
dumpster rental		2	weeks	734.71	1,469
load & truck	10 mile round trip	40	cy	55.27	2,211
dump charges		16	ton	87.12	1,394
new hot water heating system	allowance	11,049	sf	59.31	655,316
Sub Total - Direct Cost					691,327
General Conditions		14.00%			96,786
Overhead & Profit		16.00%			126,098
Design & Price Reserve		15.00%			137,132
Escalation	May-15	8.16%			85,790
Bond		2.00%			22,743
Soft Costs/Design Fees		30.00%			347,963
<b>Total Project Cost</b>					<b>1,507,839</b>

<b>Replace Oil Fired Equipment</b>					
remove oil fired equipment		1	ea	753.06	753
disposal		1	ea	242.00	242
new gas service - trench only - service by gas company		200	lf	26.18	5,236
misc. exterior repairs from trench		1	ea	1,936.00	1,936
cast iron gas boiler	300mbh	1	ea	8,606.06	8,606
hot water pumps	40gpm	2	ea	2,629.12	5,258
gas piping allowance	1 1/4"	100	lf	16.95	1,695
Sub Total - Direct Cost					23,726
General Conditions		20.00%			4,745
Overhead & Profit		23.00%			6,548
Design & Price Reserve		15.00%			5,253
Escalation	May-15	8.16%			3,286
Bond		3.00%			1,307
Soft Costs/Design Fees		30.00%			13,460
<b>Total Project Cost</b>					<b>58,325</b>

**Replace Existing Thermostats**



Description	Note	Quantity	Unit	Price	Total
demo existing thermostats	allowance	20	ea	72.60	1,452
disposal		1	ea	48.40	48
new thermostats	allowance	20	ea	256.75	5,135
Sub Total - Direct Cost					6,635
General Conditions		20.00%			1,327
Overhead & Profit		23.00%			1,831
Design & Price Reserve		15.00%			1,469
Escalation	May-15	8.16%			919
Bond		3.00%			365
Soft Costs/Design Fees		30.00%			3,764
Total Project Cost					16,310
New Oil Supply Lines					
demo old oil supply lines	allowance	100	lf	4.84	484
disposal		1	ea	72.60	73
new oil supply lines with jacketing/membrane	allowance	100	lf	29.40	2,940
Sub Total - Direct Cost					3,497
General Conditions		20.00%			699
Overhead & Profit		23.00%			965
Design & Price Reserve		15.00%			774
Escalation	May-15	8.16%			484
Bond		3.00%			193
Soft Costs/Design Fees		30.00%			1,984
Total Project Cost					8,596
Provide Mechanical Ventilation					
automatic louver/damper system to serve furnaces and main meeting chamber		1	ea	2,673.32	2,673
electrician		1	day	628.33	628
Sub Total - Direct Cost					3,301
General Conditions		20.00%			660
Overhead & Profit		23.00%			911
Design & Price Reserve		15.00%			731
Escalation	May-15	8.16%			457
Bond		3.00%			182
Soft Costs/Design Fees		30.00%			1,873
Total Project Cost					8,115
Reconfigure Ductwork					
reconfigure ductwork at dehumidification unit	allowance	1	ea	1,540.50	1,541
provide interlock wiring/contols for unit		1	ea	513.50	514
Sub Total - Direct Cost					2,055
General Conditions		20.00%			411
Overhead & Profit		23.00%			567



Description	Note	Quantity	Unit	Price	Total
Design & Price Reserve		15.00%			455
Escalation	May-15	8.16%			285
Bond		3.00%			113
Soft Costs/Design Fees		30.00%			1,166
<b>Total Project Cost</b>					<b>5,052</b>

**Plumbing**

<b>Replace Well Pump</b>					
demo well pump		1	ea	208.12	208
demo expansion tank		1	ea	174.24	174
disposal		1	ea	55.47	55
new well pump		1	ea	4,416.10	4,416
new expansion tank		1	ea	3,697.20	3,697
<b>Sub Total - Direct Cost</b>					<b>8,550</b>
General Conditions		20.00%			1,710
Overhead & Profit		23.00%			2,360
Design & Price Reserve		15.00%			1,893
Escalation	May-15	8.16%			1,184
Bond		3.00%			471
Soft Costs/Design Fees		30.00%			4,850
<b>Total Project Cost</b>					<b>21,018</b>

<b>Replace Electric Water Heater</b>					
remove electric water heater		1	ea	62.48	62
disposal		1	ea	48.40	48
new electric water heater		1	ea	2,233.73	2,234
<b>Sub Total - Direct Cost</b>					<b>2,344</b>
General Conditions		20.00%			469
Overhead & Profit		23.00%			647
Design & Price Reserve		15.00%			519
Escalation	May-15	8.16%			325
Bond		3.00%			129
Soft Costs/Design Fees		30.00%			1,330
<b>Total Project Cost</b>					<b>5,763</b>

<b>Replace Laundry Tub</b>					
remove laundry tub		1	ea	165.77	166
disposal		1	ea	48.40	48
new laundry tub		1	ea	3,517.48	3,517
<b>Sub Total - Direct Cost</b>					<b>3,731</b>





Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			746
Overhead & Profit		23.00%			1,030
Design & Price Reserve		15.00%			826
Escalation	May-15	8.16%			517
Bond		3.00%			206
Soft Costs/Design Fees		30.00%			2,117
<b>Total Project Cost</b>					<b>9,173</b>

<b>Replace Water Closets</b>					
remove water closet		4	ea	117.13	469
disposal		1	ea	48.40	48
low flow water closet		4	ea	2,485.34	9,941
<b>Sub Total - Direct Cost</b>					<b>10,458</b>

General Conditions		20.00%			2,092
Overhead & Profit		23.00%			2,887
Design & Price Reserve		15.00%			2,316
Escalation	May-15	8.16%			1,449
Bond		3.00%			576
Soft Costs/Design Fees		30.00%			5,933
<b>Total Project Cost</b>					<b>25,711</b>

**Fire Protection**

<b>Fire Protection</b>					
add sprinkler system to existing		11,049	sf	4.62	51,046
cut and patch		11,049	sf	0.23	2,541
water storage tanks 11'4"x30"x10'4"		1	ea	14,121.25	14,121
generator - gas 50kw		1	ea	29,760.60	29,761
<b>Sub Total - Direct Cost</b>					<b>97,469</b>

General Conditions		20.00%			19,494
Overhead & Profit		23.00%			26,901
Design & Price Reserve		15.00%			21,580
Escalation	May-15	8.16%			13,500
Bond		2.40%			4,295
Soft Costs/Design Fees		30.00%			54,972
<b>Total Project Cost</b>					<b>238,211</b>

**Electrical**

<b>Upgrade Lighting</b>					
demo lighting		11,049	sf	0.58	6,408
dumpster rental		2	weeks	734.71	1,469
load & truck	10 mile round trip	40	cy	55.27	2,211
dump charges		16	ton	87.12	1,394
upgrade lighting throughout		11,049	sf	14.75	162,973
<b>Sub Total - Direct Cost</b>					<b>174,455</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			34,891
Overhead & Profit		18.00%			37,682
Design & Price Reserve		15.00%			37,054
Escalation	May-15	8.16%			23,181
Bond		2.40%			7,374
Soft Costs/Design Fees		30.00%			94,391
<b>Total Project Cost</b>					<b>409,028</b>
<b>Exit Signs</b>					
demo existing exit signs		10	ea	62.48	625
disposal		1	ea	48.40	48
exit signs throughout		11,049	sf	0.49	5,414
<b>Sub Total - Direct Cost</b>					<b>6,087</b>
General Conditions		20.00%			1,217
Overhead & Profit		23.00%			1,680
Design & Price Reserve		15.00%			1,348
Escalation	May-15	8.16%			843
Bond		3.00%			335
Soft Costs/Design Fees		30.00%			3,453
<b>Total Project Cost</b>					<b>14,963</b>
<b>Generator</b>					
generator - gas 50kw		1	ea	29,760.60	29,761
<b>Sub Total - Direct Cost</b>					<b>29,761</b>
General Conditions		20.00%			5,952
Overhead & Profit		23.00%			8,214
Design & Price Reserve		15.00%			6,589
Escalation	May-15	8.16%			4,122
Bond		3.00%			1,639
Soft Costs/Design Fees		30.00%			16,883
<b>Total Project Cost</b>					<b>73,160</b>

Town Hall - Renovate First Floor And Second Floor Only			
Town Hall - Renovate First Floor And Second Floor Only	7,412 sf	216.60	1,605,439
Sub Total - Direct Cost			<u>1,605,439</u>
General Conditions	12.00%		192,653
Overhead & Profit	14.00%		251,733
Design & Price Reserve	15.00%		307,474
Escalation	Aug-15	8.16%	192,356
Bond		1.60%	40,794
Soft Costs/Design Fees		30.00%	777,135
Total Project Cost			<u><u>3,367,584</u></u>



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW POLICE STATION  
 BRIMFIELD, MA 01010

GFA

4,088



Description	Note	Quantity	Unit	Price	Total
<b>General</b>					
<del>New Police Station</del>					<del>\$</del>
<del>New Police Station (see cost plan)</del>		4,088	sf	372.80	1,524,006
<del>Sub Total - Direct Cost</del>					<del>1,524,006</del>
<del>General Conditions</del>				<del>12.00%</del>	<del>182,881</del>
<del>Overhead &amp; Profit</del>				<del>14.00%</del>	<del>238,964</del>
<del>Design &amp; Price Reserve</del>				<del>15.00%</del>	<del>291,878</del>
<del>Escalation</del>	<del>Aug-15</del>			<del>8.16%</del>	<del>182,599</del>
<del>Bond</del>				<del>1.60%</del>	<del>38,725</del>
<del>Soft Costs/Design Fees</del>				<del>30.00%</del>	<del>737,716</del>
<del>Total Project Cost</del>					<del>3,196,769</del>
Police Station Storage Building					\$
Pre-Engineered Steel Building		500	sf	95.57	47,785
Sub Total - Direct Cost					47,785
General Conditions				20.00%	9,557
Overhead & Profit				23.00%	13,189
Design & Price Reserve				15.00%	10,580
Escalation	Aug-15			8.16%	6,619
Bond				3.00%	2,632
Soft Costs/Design Fees				30.00%	27,109
Total Project Cost					117,471



COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL NEW ENTRANCE  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Addition Component		GFA(SF):		1,403 Date:		Jul-13		Sheet No: 1 OF 2	
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element Quantities	Unit	Element Unit Rate	
		\$	\$	Floor Area					
<b>A</b>	<b>SUBSTRUCTURE</b>		36,113	25.74	7.3%				
	A10 Foundations	34,205		24.38		1,403 SF	SF	24.38	
	A20 Basement Construction	1,908		1.36		1,403 SF	SF	1.36	
<b>B</b>	<b>SHELL</b>		160,041	114.07	32.4%				
	B10 Superstructure	33,756		24.06		1,403 SF	SF	24.06	
	B20 Exterior Closure	118,650		84.57		3,164 SF	SF	37.50	
	B30 Roofing	7,635		5.44		509 SF	SF	15.00	
<b>C</b>	<b>INTERIORS</b>		90,375	64.42	18.3%				
	C10 Interior Construction	18,085		12.89		1,403 SF	SF	12.89	
	C20 Stairs	60,000		42.77		2 FLT	FLT	30000.00	
	C30 Interior Finishes	12,290		8.76		1,403 SF	SF	8.76	
<b>D</b>	<b>SERVICES</b>		170,821	121.75	34.5%				
	D10 Conveying Systems	97,500		69.49		3 stops	stops	32500.00	
	D20 Plumbing	8,418		6.00		1,403 SF	SF	6.00	
	D30 HVAC	32,395		23.09		1,403 SF	SF	23.09	
	D40 Fire Protection	7,717		5.50		1,403 SF	SF	5.50	
	D50 Electrical Systems	24,791		17.67		1,403 SF	SF	17.67	
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		4,911	3.50	1.0%				
	E10 Equipment	2,806		2.00		1,403 SF	SF	2.00	
	E20 Furnishings	2,105		1.50		1,403 SF	SF	1.50	



COSTPRO, INC.

Project Cost Plan (Uniformat II Level 3)

Sheet No: 2 OF 2

Date: Jul-13

Project: New Addition Component

Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
<b>F SPECIAL CONSTRUCTION &amp; DEMOLITION</b>		4,139	2.95	0.8%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	4,139		2.95		1,403	SF	2.95
<b>G BUILDING SITEWORK</b>		28,201	20.10	5.7%			
G10 Site Preparation	3,508		2.50		1,403	SF	2.50
G20 Site Improvements	15,573		11.10		1,403	SF	11.10
G30 Site Civil/Mechanical Utilities	7,015		5.00		1,403	SF	5.00
G40 Site Electrical Utilities	2,105		1.50		1,403	SF	1.50
G90 Other Site Construction	0		0.00		1,403	SF	0.00
<b>SUBTOTAL</b>		494,601	352.53	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
<b>Z90 PROJECT COST ESTIMATE</b>	\$	494,601 \$	352.53				



COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL RENOVATION AND ADDITION 1ST AND 2ND FLOOR ONLY  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Renovation And Addition		GFA(SF):		7,412		Date: Aug-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element Quantities	Unit	Element Unit Rate		
		\$	\$	Floor Area						
<b>A</b>	<b>SUBSTRUCTURE</b>		11,506		0.7%					
	A10 Foundations	10,898		1.47		447 SF	SF	24.38		
	A20 Basement Construction	608		0.08		447 SF	SF	1.36		
<b>B</b>	<b>SHELL</b>		297,711		18.5%					
	B10 Superstructure	33,756		4.55		1,403 SF	SF	24.06		
	B20 Exterior Closure	257,250		34.71		6,860 SF	SF	37.50		
	B30 Roofing	6,705		0.90		447 SF	SF	15.00		
<b>C</b>	<b>INTERIORS</b>		348,642		21.7%					
	C10 Interior Construction	166,027		22.40		7,412 SF	SF	22.40		
	C20 Stairs	60,000		8.09		2 FLT	FLT	30000.00		
	C30 Interior Finishes	122,615		16.54		7,412 SF	SF	16.54		
<b>D</b>	<b>SERVICES</b>		562,308		35.0%					
	D10 Conveying Systems	97,500		13.15		3 STOP	STOP	32500.00		
	D20 Plumbing	59,915		8.08		7,412 SF	SF	8.08		
	D30 HVAC	211,704		28.56		7,412 SF	SF	28.56		
	D40 Fire Protection	34,758		4.69		7,412 SF	SF	4.69		
	D50 Electrical Systems	158,431		21.37		7,412 SF	SF	21.37		
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		65,001		4.0%					
	E10 Equipment	33,151		4.47		7,412 SF	SF	4.47		
	E20 Furnishings	31,850		4.30		7,412 SF	SF	4.30		



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL RENOVATION AND ADDITION 1ST AND 2ND FLOOR ONLY  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Renovation And Addition		Date: Aug-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		90,135	12.16	5.6%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	90,135		12.16		6,009	SF	15.00
G BUILDING SITEWORK		230,164	31.05	14.3%			
G10 Site Preparation	68,646		9.26		7,412	SF	9.26
G20 Site Improvements	81,552		11.00		7,412	SF	11.00
G30 Site Civil/Mechanical Utilities	50,400		6.80		7,412	SF	6.80
G40 Site Electrical Utilities	29,566		3.99		7,412	SF	3.99
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		1,605,467	216.60	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	1,605,467 \$	216.60				

COSTPRO INC.

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL RENOVATION AND ADDITION 1ST AND 2ND FLOOR ONLY  
 BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Addition Component		GFA(SF):		1,403		Date: Aug-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element	Unit	Element	Unit Rate	
		\$	\$	Floor Area		Quantities				
<b>A</b>	<b>SUBSTRUCTURE</b>		11,506	8.20	1.9%					
	A10 Foundations	10,898		7.77		447	SF		24.38	
	A20 Basement Construction	608		0.43		447	SF		1.36	
<b>B</b>	<b>SHELL</b>		297,711	212.20	49.3%					
	B10 Superstructure	33,756		24.06		1,403	SF		24.06	
	B20 Exterior Closure	257,250		183.36		6,860	SF		37.50	
	B30 Roofing	6,705		4.78		447	SF		15.00	
<b>C</b>	<b>INTERIORS</b>		90,375	64.42	15.0%					
	C10 Interior Construction	18,085		12.89		1,403	SF		12.89	
	C20 Stairs	60,000		42.77		2	FLT		30000.00	
	C30 Interior Finishes	12,290		8.76		1,403	SF		8.76	
<b>D</b>	<b>SERVICES</b>		170,821	121.75	28.3%					
	D10 Conveying Systems	97,500		69.49		3	STOP		32500.00	
	D20 Plumbing	8,418		6.00		1,403	SF		6.00	
	D30 HVAC	32,395		23.09		1,403	SF		23.09	
	D40 Fire Protection	7,717		5.50		1,403	SF		5.50	
	D50 Electrical Systems	24,791		17.67		1,403	SF		17.67	
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		4,911	3.50	0.8%					
	E10 Equipment	2,806		2.00		1,403	SF		2.00	
	E20 Furnishings	2,105		1.50		1,403	SF		1.50	



COSTPRO, INC.

0

Project Cost Plan (Uniformat II Level 3)

Project: New Addition Component		Date: Aug-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
<b>F SPECIAL CONSTRUCTION &amp; DEMOLITION</b>		0	0.00	0.0%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	0		0.00		0	SF	2.95
<b>G BUILDING SITEWORK</b>		28,201	20.10	4.7%			
G10 Site Preparation	3,508		2.50		1,403	SF	2.50
G20 Site Improvements	15,573		11.10		1,403	SF	11.10
G30 Site Civil/Mechanical Utilities	7,015		5.00		1,403	SF	5.00
G40 Site Electrical Utilities	2,105		1.50		1,403	SF	1.50
G90 Other Site Construction	0		0.00		1,403	SF	0.00
<b>SUBTOTAL</b>		603,525	430.17	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
<b>Z90 PROJECT COST ESTIMATE</b>	\$	603,525 \$	430.17				

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL RENOVATION AND ADDITION 1ST AND 2ND FLOOR ONLY  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Renovation Component		GFA(SF):		6,009		Date: Aug-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element	Unit	Element	Unit Rate	
		\$	\$	Floor Area		Quantities				
<b>A</b>	<b>SUBSTRUCTURE</b>		0	0.00	0.0%					
	A10 Foundations	0		0.00		0 SF			0.00	
	A20 Basement Construction	0		0.00		0 SF			0.00	
<b>B</b>	<b>SHELL</b>		0	0.00	0.0%					
	B10 Superstructure	0		0.00		0 SF			6.00	
	B20 Exterior Closure	0		0.00		0 SF			14.82	
	B30 Roofing	0		0.00		0 SF			12.59	
<b>C</b>	<b>INTERIORS</b>		258,267	42.98	25.8%					
	C10 Interior Construction	147,942		24.62		6,009 SF			24.62	
	C20 Stairs	0		0.00		0 FLT			65450.00	
	C30 Interior Finishes	110,325		18.36		6,009 SF			18.36	
<b>D</b>	<b>SERVICES</b>		391,487	65.15	39.1%					
	D10 Conveying Systems	0		0.00		0 STOP			32500.00	
	D20 Plumbing	51,497		8.57		6,009 SF			8.57	
	D30 HVAC	179,309		29.84		6,009 SF			29.84	
	D40 Fire Protection	27,041		4.50		6,009 SF			4.50	
	D50 Electrical Systems	133,640		22.24		6,009 SF			22.24	
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		60,090	10.00	6.0%					
	E10 Equipment	30,345		5.05		6,009 SF			5.05	
	E20 Furnishings	29,745		4.95		6,009 SF			4.95	



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL RENOVATION AND ADDITION 1ST AND 2ND FLOOR ONLY  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Renovation Component		Date: Aug-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		90,135	15.00	9.0%			
F10 Special Construction	0		0.00		0	SF	28.25
F20 Selective Demolition	90,135		15.00		6,009	SF	15.00
G BUILDING SITEWORK		201,963	33.61	20.2%			
G10 Site Preparation	65,138		10.84		6,009	SF	10.84
G20 Site Improvements	65,979		10.98		6,009	SF	10.98
G30 Site Civil/Mechanical Utilities	43,385		7.22		6,009	SF	7.22
G40 Site Electrical Utilities	27,461		4.57		6,009	SF	4.57
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		1,001,942	166.74	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	1,001,942	166.74				

EXISTING and PROPOSED TOWN HALL  
Program Areas

EXISTING SPACE	EXISTING AREA	NEW USE	PROPOSED AREA GROUND FLOOR ONLY & NEW FOR ROOM NAMES
<b>TOWN HALL - GROUND FLOOR</b>		<b>Police Department</b>	
Corridor #1	305	Part of Police	
Corridor #2	543	Corridor#2	423
Corridor #3	238	Stair	238
Toilet #1	64	Toilet #1	64
Toilet #2	64	Toilet #2	64
Unassigned #1	84	Police Department	2271
Unassigned #2	166	Part of Police	
Unassigned #3	131	Part of Police	
Unassigned #4	37	Part of Police	
Unassigned #5	147	Part of Police	
Unassigned #6	131	Part of Police	
Unassigned #7	119	Part of Police	
Mechanical #1	445	Mechanical #1	346
Mechanical #2	147	Mechanical #2	147
Community TV #1	142	Part of Police	
Community #2	409	Part of Police	
		Addition:	
		Elevator	61
		Lobby	162
		Stair	169
<b>BUILDING AREA - GROUND FLOOR</b>	<b>3172</b>		<b>3945</b>

<b>TOWN HALL - FIRST FLOOR</b>		<b>Council-On-Aging</b>	
Lobby	190	Lobby	190
Meeting Room	1967	Meeting Room/Reception	1967
Stage	393	Stage	393
Town Clerk #1	467	Part of Kitchen	
Town Clerk #2	232	Part of Kit, Director, Conf & Restr.m.	
Storage #1	69	Part of Conference	
Storage #2	92	Corridor	109
Storage #3	113	Storage #3	113
Vault	48	Part of Director	
Outhouse	27	Outhouse	27
		Kitchen	556
		Restroom	63
		Conference Room	102
		Director	80
		Hall	61
		Addition:	
		Elevator	61
		Lobby	162
		Stair	169
<b>BUILDING AREA - FIRST FLOOR</b>	<b>3598</b>		<b>4053</b>

<b>TOWN HALL - SECOND FLOOR</b>			
Meeting Room	576	Meeting Room	576
Stair	126	Stair	126
Attic Access	108	Meeting Room	107
		Addition:	
		Hall	74
		Elevator	61
		Lobby	166
		Stair	169
<b>BUILDING AREA - SECOND FLOOR</b>	<b>810</b>		<b>1279</b>

<b>TOWN HALL - NET ROOM AREA</b>			
Ground Floor	3769		4174
First Floor	3869		4274
Second Floor	819		1305
<b>TOTAL TOWN HALL - TOTAL BUILDING AREA</b>	<b>8457</b>		<b>9753</b>

<b>TOWN HALL - GROSS AREA</b>			
Ground Floor	3987		4496
First Floor	4069		4578
Second Floor	969		1571
<b>TOTAL TOWN HALL - NET GROSS AREA</b>	<b>9025</b>		<b>10645</b>





## BUILDING USE AUDIT - CONDITION ASSESSMENT Town of Brimfield, Massachusetts

### **Senior Center**

20 Main Street

The current Senior Center is located in rented space on the first floor of the First Congregation Church opposite the Town Hall.



#### **General:**

Plans were developed to ascertain the useable floor area for the Senior Center.

As this is not a town Owned facility a condition assessment was not performed.

#### **Program:**

The Senior Center is located in one large room that has use of the kitchen. This space houses all the functions. There are no private offices but a small room is available should a private conversation be required.


A design for a new Senior Center was previously developed and located to the rear of the Town Hall Annex. The building would have incorporated the Annex Barn, and the link from the Barn to the house would have been demolished. This approach was not pursued due to issues with the well. We chose not to include this as an option as it will preclude the use of the Town Hall Annex.

The Town Hall building has most of the features required for a Senior Center including a large meeting space and smaller office areas on the first and second floor that can accommodate the requirements for this function. A proposed layout for this option was developed. Senior activities typically occur during the mornings. The meeting space could be used by other Town functions requiring a large space in the evening. These could include Historical Commission meetings, training or public informational meetings that are currently accommodated at the Hitchcock Academy. Concerns with this include the ability to secure


Senior Center items. This could be overcome with moveable lockable pods (closets) for the Senior Center items.

In conversations with Conservation there is minimal space available in the Town Center for new construction. If buildable Town land is available elsewhere an option for a new building could be pursued.

REFER TO THE TOWN HALL DOCUMENTS FOR PROPOSED PLANS.



**GROUND FLOOR PLAN**



**Drumey Rosane Anderson, Inc.**  
 235 Bear Hill Road, 4th Floor  
 Waltham, MA 02451

Planning 617-964-1700  
 Architecture 617-964-1701 fax  
 Interior Design info@draws.com

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**EXISTING SENIOR CENTER FLOOR PLAN**

Scale: 3/32"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 6/21/13

**EX-SC1**



COUNCIL ON AGING  
Existing Space in Church

EXISTING SPACE	EXISTING AREA
<b>CHURCH</b>	
Senior Activities Area	2302
Shared Kitchen	443
Women's Room	56
Men's Room	59
<b>TOTAL AREA</b>	<b>2860</b>

See Town Hall for Proposed



# BUILDING USE AUDIT - CONDITION ASSESSMENT

## Town of Brimfield, Massachusetts

### Brimfield Town Hall Annex

23 Main Street

#### Year Constructed:

- Benjamin Salisbury House 1819
- Salisbury Carriage House 1819
- Additions (Most recent) 1990
- New Roof 1996

Construction Type: VB

Fire Sprinklers: No

#### Building Area per Floor:

Basement:	644 SF
First Floor:	3022 SF
Second Fl:	1330 SF
Total Area:	5042 SF



#### Documents Used in Study:

- Assessor's Field Card
- Aerial Photograph


#### General:

#### The building is not handicapped accessible:


- G** Entrance door is located on the east side of the structure and approach is very narrow (4'-3"). Approach clearance on pull side of door does not meet code.  
It appears that the ramp in the approach area is more than a 1/12 slope. Changes will be cost prohibitive.



- 3** Concrete Ramp from parking to the main entrance is badly deteriorated and in need of replacement. Steel structure and exposed rebar rusted. Hand rails are rusted and too low (30" high) without extensions. There is no toe kick on the railings. Ramp should be demolished and a replacement ramp constructed.



- 3** Re-point brick chimney and provide a stainless steel cap.





- 3 Paint is peeling around entire structure. Scrape and repaint areas where peeling paint occurs.



- 3 Roof damage above main entry at skylight. Blue tarp visible in this area. Repair flashing and roofing at skylight.



- 3 Side entrance concrete steps and landing that are pulling away from the building. They have a rise of 8" and a 4" step in to the building. Metal handrails and railings are low (30") without extensions. It is recommended that steps be removed and door secured shut. Behind the steps is a window into the basement. this should be cleaned and painted.



- 3 Main Street (North) entrance has a 8" step into building and the concrete stoop is not deep enough for the approach. (2'-4" x 7'-0"). Board from facade missing from below door. Replace stoop with new brick stoop aligned with floor at least 6'-0" deep with steps and railings down to side walk.



- 3 Wood rot apparent at grade on extension to barn both sides.



- 3 Replace missing fascia boards and trim from areas around entire structure.



- Unused concrete stairs on west side of structure. No action recommended.




- 3 Foundation wall cracked around west side of building. Re-point wall areas.







- 3 Brownstone facing to east side of foundation has shifted under bay windows. Re-set stone.



- 3 Fire escape made of a wood structure on the west side of the building is unusable. Remove platform and patch siding.




- 3 Window shutters need repair and replacement of missing louvers.



- 3 Due to status of second floor construction (see structural items below) all doors locked and warning signs installed to prevent use of second floor spaces.

- 2 In the Meeting room, exterior door from vestibule does not meet required push side area. Remove vestibule and secure door shut.



- Rest room is not ADA compliant (area, door knobs and plumbing). One ADA restroom is provided so no action required.

- 3 Ceiling cracks and damage throughout entire second floor. Paint peeling and water damage throughout. Make repairs to roof.



- 3 Floors throughout first floor are uneven, either sloping or bowing. (See structural report) Floor areas need to be reinforced structurally or fully replaced.



2 Stair handrail to second floor is loose and needs to be repaired and re-secured.



3 Threshold into Tax Collectors office is raised and not ADA compliant. Replace threshold.

3 Cemetery Commission office has an opening in the ceiling covered and taped with plastic. Replace damaged section of ceiling.



### STRUCTURAL

3 First Floor framing over the Basement be thoroughly evaluated and reinforced/permanently re-supported in conjunction with future renovations to the building.



3 First Floor framing over the crawl space be thoroughly evaluated and reinforced as required to increase capacity for the intended use, in conjunction with future renovations to the building. In the meantime, caution should be exercised in placing heavy loads (file cabinets, equipment, etc.) in these areas.



3 Roof and surface drainage needs to be evaluated in conjunction with future renovations to the building. Roof and surface water should be directed away from foundation walls and wall joints should be raked and re-pointed as required.

3 Second Floor framing be thoroughly evaluated and reinforced as required to increase capacity for the intended use, in conjunction with future renovations to the building. In the meantime, caution should be exercised in placing heavy loads (file cabinets, equipment, etc.) at this level.



Hip roof framing over the northern section of the original house is performing satisfactorily; however, it is somewhat undersized with respect to current code requirements.

Review and reinforcing of these areas is recommended, in conjunction with future renovations to the building. In the interim, maintenance personnel should clear drifted snow, should it accumulate during the winter months.



Further review of exterior walls is recommended, in conjunction with future renovations to the building.

3 The handicap ramp on the east side of the original house needs to be replaced.



1 The supporting post for the central, north- south Loft Floor beam in the Barn has been removed. In the absence of the column, this beam has little or no live load capacity. FBRA recommends that the beam be temporarily shored, without delay. Loft Floor joists in the western bay (right hand side in photo at right - 3"x4½" @ 2'-6" o.c., spanning 10½ +/- feet) have minimal live load capacity and have deflected considerably. Joists in this bay be temporarily shored and/or that (storage) loading be removed.



1 The capacity of the wood framed First Floor in the Barn was not determined; however, the floor is considerably uneven throughout, suggesting that there may be damage and/or deficiencies present. These need to be investigated and corrected.



1 A new foundation needs to be constructed if the Barn is retained/rebuilt.

1 The wood framed exterior walls of the Barn are in poor condition and have failed in several locations. Walls need to be reconstructed.



## MECHANICAL

3 Upgrade the boiler plant from oil to a gas-fired condensing unit to save energy with better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

3 Replace existing thermostats with programmable type.

## ELECTRICAL

3 Provide new lighting, including emergency lighting in the basement.

2 Provide exterior emergency lighting.

## PLUMBING

4 The water closets should be replaced by low flow fixtures.

## PROGRAM INFORMATION

The current building follows the traditional arrangement of New England historic farmhouses often referred to as "Big House, Little House, Back House, Barn". Over the years this has been expanded to create a second floor and to expand the width of the "Little House" portion.

Structurally, the second floor has little carrying capacity and has not been used for occupancy. The first floor will need to be reinforced/replaced to carry the loading for office space use.

The Barn is structurally unsound and needs major repairs to halt further deterioration and possible collapse. The smaller "Back House" is also in poor condition. Low headroom suggests that this portion be removed.


The first option expands the town hall functions around a restored barn and around the existing well. A new accessible entrance will be created, and with a new interior ramp will provide access throughout the first floor of the existing building and addition.

A second option calls for the demolition of the "little house back house and barn" portions and the construction of a two story new wing to the rear of the house. The new wing will provide space for all town offices and the original house would be the museum for historic artifacts and books from the library.



**Drumey Rosane Anderson, Inc.**  
235 Bear Hill Road, 4th Floor  
Waltham, MA 02451

Planning 617-964-1700  
Architecture 617-964-1701 fax  
Interior Design info@draws.com




**BASEMENT PLAN**

**Town Of Brimfield**  
Municipal Facilities Study and Planning  
Brimfield, Massachusetts


**EXISTING TOWN HALL ANNEX BASEMENT PLAN**

Scale: 3/32"=1'-0"  
Drawn by: AJ/CGH  
Job No. 13002.00  
Date: 4/17/13



**EX-THA1**






**FIRST FLOOR PLAN**

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**EXISTING TOWN HALL ANNEX FLOOR PLANS**




Scale: 3/32"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 4/17/13

**EX-THA2**








**SECOND FLOOR PLAN**

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts


**EXISTING TOWN HALL ANNEX SECOND FLOOR PLAN**



Scale: 3/32"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 4/17/13

**EX-THA3**





FIRST FLOOR PLAN




**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED TOWN HALL ANNEX FLOOR PLANS**  
**SINGLE STORY SCHEME**

Scale: 1/16" = 1'-0"  
 Drawn by:  
 Job No. 13002.00  
 Date: 4/17/13





FIRST FLOOR PLAN



PARKING LOT



**Drummey Rosane Anderson, Inc.**  
 235 Bear Hill Road, 4th Floor  
 Waltham, MA 02451

Planning 617-964-1700  
 Architecture 617-964-1701 fax  
 Interior Design info@draws.com

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED TOWN HALL ANNEX FLOOR PLANS**  
**REVISED SINGLE STORY SCHEME**


Scale: 1/16" = 1'-0"  
 Drawn by:  
 Job No. 13002.00  
 Date: 9-12-13

**PR-THA1r**





FIRST FLOOR PLAN



SECOND FLOOR PLAN



**Drumey Rosane Anderson, Inc.**  
 235 Bear Hill Road, 4th Floor  
 Waltham, MA 02451

Planning 617-964-1700  
 Architecture 617-964-1701 fax  
 Interior Design info@draws.com

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts


**PROPOSED TOWN HALL ANNEX FLOOR PLANS**  
**TWO STORY SCHEME**

Scale: 1/16" = 1'-0"  
 Drawn by:  
 Job No. 13002.00  
 Date: 7-9-13

**PR-THA2**







**FIRST FLOOR PLAN**

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED TOWN BUILDING FLOOR PLANS**  
**TOWN HALL - SENIOR CENTER - POLICE**

Scale: 1/16" = 1'-0"  
 Drawn by:  
 Job No. 13002.00  
 Date: 9-16-13



MUNICIPAL FACILITIES STUDY AND PLANNING  
Town of Brimfield, Massachusetts

**Town Office Annex and Barn**  
Structural

**Structural Description:**

The Brimfield Town Office Annex is a two-story, wood framed structure (plus a partial Basement), located at 23 Main Street, adjacent to the Town Hall. The former Benjamin Salisbury House, constructed in 1819, is listed on the National Register of Historic Places. The facility consists of the original house with a Barn in the back, connected to the house by a one-story link structure.



The Town Office Annex is rectangular in plan, with a sloping roof (intersecting hips). There is a partial (unoccupied) Basement, located under the front (north) section of the original house. A crawl space was constructed to the south of the Basement. Program elements at the First Floor include Town Offices (Selectmen and various Town Departments), a Meeting Room and Bathrooms. Two additional offices, a Kitchen and storage spaces are located at the Second Floor. The First Floor is accessed by a handicap ramp on the east side of the building. The Second Floor is accessed by front and back stairways; there is no elevator. The Barn and the connecting link are used for storage purposes.

Typical foundation walls are rubble stone. Basement Floor construction in the original house consists of a concrete slab on grade (thickness unknown) in limited areas (dirt floor elsewhere). First Floor construction is wood framed; the arrangement of the framing is somewhat disorganized. Over the east and west sides of the Basement, First Floor joists (8" hand-hewn, spaced at 26" +/- o.c.) span approximately 14 feet in the north-south direction to 8"x7" timber beams. The timber beams span 14 +/- feet to similar, north-south timber beams on either side of the central, stair bay. Wood joists in this bay span in the east-west direction, approximately 10 feet. A number of adjustable steel pipe columns have been installed (12 +/- total) to shore up the First Floor construction in this area. To the south of the Basement, First Floor construction consists of 1¾" x 6¾" wood joists spaced at 21" +/- o.c., spanning in the north-south direction. Attic Floor construction in the south section consists of 2" x 6½" joists spaced at 22½" +/- o.c., spanning 8 +/- feet in the north-south direction and mortised into an 8" x 7¼" beam that clear spans the space (approximately 16 feet). Second Floor framing details could not be determined; however, the construction appears to be similar to that at the Attic level.

The southern section of the Second Floor is approximately 8 inches higher (one riser) than the front/northern section. Hip roof construction at the front (north) section of the building consists of 5"x 4½" rafters spaced at 32" +/- o.c. spanning to a central, east-west ridge beam and hip members on the east and west sides. Roof framing for the intersecting hip to the south could not be observed, but is expected to be similar. The present roof is asphalt shingles.

The gable roof of the link structure is framed with 4x4 rafters spaced at 2'-0" +/- o.c., spanning in the east-west direction to a ridge nailer. Rafters are tied across the space (approximately 16 feet) by 2x8 ceiling joists. The floor of the link building is a concrete slab on grade (thickness unknown). The roof is asphalt shingles.

The Barn is a timber framed structure with a Loft and a structured First Floor. Roof framing members were exposed to view; however, sizes could not be determined. Loft Floor construction consists of 3"x7" or 3"x4½" joists, spaced at 2'-6" +/- o.c. spanning 10½ +/- feet in the east-west direction to 7½"x7½" timber beams. It appears that an original support post may have been removed in the past; the north-south span for this timber beam is approximately 24 feet. First Floor construction is wood framed; sizes/spans and the arrangement of framing were not determined during the site visit. The First Floor of the Barn is approximately 8" (one riser) above the floor of the link structure.

No original construction drawings or previous structural reports for the Annex or the Barn were available.

### **Structural Conditions/Issues – Comments and Recommendations:**

Structural conditions at the Brimfield Town Office Annex and Barn were observed (to the extent possible) during a brief tour of the facility on May 13, 2013. A number of foundation and framing deficiencies were observed, as noted below.

- The front (northern) section of the First Floor in the original house appears to be relatively stiff under foot, as the framing has been shored up with adjustable steel pipe columns in numerous locations (photo right). In the absence of the additional supports, the capacity of this framing would be marginal; the supporting timber beams are particularly undersized. FBRA recommends that First Floor framing over the Basement be thoroughly evaluated and reinforced/permanently re-supported in conjunction with future renovations to the building.



- To the south of the Basement, First Floor joists over the crawl space (1¾"x6 ¾" @ 21" o.c. – photo right) in the original house are inadequate for office use. The floor is flexible under foot. The balance of the First Floor structure (further to the south) is flexible and uneven, suggesting that similar conditions are present throughout. FBRA recommends that First Floor framing over the crawl space be thoroughly evaluated and reinforced as required to increase capacity for the intended use, in conjunction with future renovations to the building. In the meantime, caution should be exercised in placing heavy loads (file cabinets, equipment, etc.) in these areas.



- Rubble stone foundation walls in the original house have taken on moisture over the years and show signs of deterioration. Mortar has desintegrated and turned into powder in some areas; elsewhere, mortar appears to be relatively intact. FBRA recommends that roof and surface drainage be evaluated in conjunction with future renovations to the building. Roof and surface water should be directed away from foundation walls and wall joints should be raked and repointed as required.

- Second Floor framing in the original house is flexible under foot. The floor construction sags considerably; particularly at the back/southern section. Member sizes/spans could not be determined; however framing may be similar to that observed at the Attic space above. The 8"x 7½" beam which spans in the east-west direction (approximately 16 feet) has limited capacity to support live load. FBRA recommends that Second Floor framing be thoroughly evaluated and reinforced as required to increase capacity for the intended use, in conjunction with future renovations to the building. In the meantime, caution should be exercised in placing heavy loads (file cabinets, equipment, etc.) at this level.



- Hip roof framing over the northern section of the original house is performing satisfactorily; however, it is somewhat undersized with respect to current code requirements.

- Gable roof framing over the link structure is performing satisfactorily and nearly meets current snow load requirements for Brimfield. However, there are potential snow drift areas adjacent to the Barn and the original house (photo right). Review and reinforcing of these areas is recommended, in conjunction with future renovations to the building. In the interim, maintenance personnel should clear drifted snow, should it accumulate during the winter months.



- The condition of the exterior walls in the original house could not be determined; however, the northeast corner of the structure is not plumb. The corner walls tilt inwards to the south and to the west. Further review is recommended, in conjunction with future renovations to the building.

- The handicap ramp on the east side of the original house (photos right) has deteriorated significantly; likely due to moisture and de-icing salts. Repair or replacement is required.



- Wood framing in the original house may typically be protected (to a degree) by the ceiling construction; however, elsewhere it is unprotected. There are no sprinklers. Fire rating requirements should be reviewed in conjunction with future renovations to the facility.

- As noted above, it appears that a supporting post for the central, north-south Loft Floor beam in the Barn has been removed. In the absence of the column, this beam has little or no live load capacity. FBRA recommends that the beam be temporarily shored, without delay. Loft Floor joists in the western bay (right hand side in photo at right - 3"x4½" @ 2'-6" o.c., spanning 10½ +/- feet) have minimal live load capacity and have deflected considerably. FBRA recommends that joists in this bay be temporarily shored and/or that (storage) loading be removed.



- The capacity of the wood framed First Floor in the Barn was not determined; however, the floor is considerably uneven throughout, suggesting that there may be damage and/or deficiencies present.

- Barn roof construction was observed (from a distance) and generally appears to be performing satisfactorily; however, walls and foundations supporting this construction are in poor condition, as noted below.
- The rubble stone foundations of the Barn are in poor condition (photo right) and have failed in some locations (e.g. the southwest corner). It appears that the foundation is beyond repair, FBRA recommends that a new foundation be constructed if the Barn is retained/rebuilt.
- The wood framed exterior walls of the Barn are in poor condition and have failed in several locations. Walls are bowing out at the First Floor and Loft Floor levels on the back (south) and west sides of the structure. Wall construction at the southeast corner has failed. There are a number of areas where wood trim/cornices are rotted and/or missing, allowing water to enter the building.



### **Building Code Requirements and Additional Comments:**

#### **Massachusetts State Building Code Requirements – General Comments:**

Proposed renovations, alterations, repairs and additions to the Brimfield Town Office Annex and Barn would be governed by the provisions of the Massachusetts State Building Code (MSBC – 780 CMR 8<sup>th</sup> Edition) and the Massachusetts Existing Building Code (MEBC). These documents are based on amended versions of the 2009 International Building Code (IBC) and the 2009 International Existing Building Code (IEBC), respectively.

The MEBC allows the Design Team to choose one of three (3) compliance methods. Structurally, the Prescriptive Compliance Method is preferred. Section 101.5.4.0 of the Massachusetts Amendments (Chapter 34) would require that the existing building be investigated in sufficient detail to ascertain the effects of any proposed work (or change in use) in the area under consideration, and the entire building or structure and its foundations, if impacted by the proposed work or change in use.

#### **Additions – General Comments:**

The design and construction of any proposed additions would be conducted in accordance with the Code for new construction. Significant additions should be structurally separated from the existing building by an expansion (seismic) joint to avoid an increase in gravity loads and/or lateral loads to existing structural elements. Smaller additions can be structurally attached to

the existing building, provided they do not increase the demand - capacity ratio of the existing lateral force resisting elements in the building by more than 10%.

#### Renovations/Alterations – General Comments:

Where proposed alterations to existing structural elements carrying gravity loads results in a stress increase of over 5%, the affected element would need to be reinforced or replaced to comply with the Code for new construction. Proposed alterations to existing structural elements carrying lateral load (perimeter wood walls and Ground Floor masonry walls) which result in an increase in the demand - capacity ratio of over 10% should be avoided, if possible. Essentially, this means that removal of, or major alterations to these walls should be minimized. If this is not avoidable, more significant seismic upgrades/reinforcing will be required; potentially including the addition of lateral force resisting elements (wood shear walls, etc.).

#### Renovations/Alterations – Anticipated Scope of Structural Work:

##### Original House and Link Structure

As noted above, First and Second Floor construction appears to be inadequate for office use (as well as other potential uses). The preliminary cost estimate should carry allowances for the following structural work.

- Repair/repointing of original rubble stone foundation walls.
- Address roof drainage and surface drainage around the building perimeter.
- Repair/reinforcing/reconstruction of the First and Second Floor framing, including permanent supports/foundations in the Basement.
- Construction of a new slab on grade in the Basement on compacted granular fill and a vapor barrier.
- Reinforcing of the roof structure; particularly for snow drift conditions at the link structure.
- Repair/reconstruction of the handicap ramp on the east side of the facility.
- Installation of a new elevator, if required by code.
- Installation of a sprinkler system, if required by code or desired by the Town.



## Barn

- Based on field observations, it appears that it would be more cost effective to dismantle the Barn and salvage floor and roof framing to be used in a reconstruction effort. Framing deficiencies are pervasive and would be difficult to repair/reinforce in place.
- Once the Barn framing has been dismantled, the existing rubble stone foundation walls should be removed and a new, reinforced concrete foundation should be constructed.

**End of Structural Report**



TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**Town Hall Annex**

23 Main Street

MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS

Prepared By:

Consulting Engineering Services  
510 Chapman Street, Suite 201  
Canton, MA 02021

July 3, 2013

**GENERAL**

The mechanical, electrical, plumbing, and fire protection systems were reviewed in conformance with the requirements of the following State and National codes and regulations, as applicable:

- Massachusetts State Building Code 8th Edition
- Massachusetts State Fire Prevention Regulations
- NFPA Latest Editions
- Massachusetts Plumbing Code
- Massachusetts Mechanical Code
- Massachusetts Electrical code (NEC 2011 Edition)
- Illuminating Engineering Society of North America (IESNA) Lighting Handbook
- ASHRAE 90.1 Latest Edition

The scope of this study does not include operational assessment of the fixtures and equipment reviewed; it includes only a brief visual review of the fixtures and equipment. Therefore notes regarding the condition of the fixtures and equipment may or may not be indicative of the actual condition of the systems and equipment and/or the expected life of the fixtures and equipment. Therefore it is recommended that services of a qualified technician be retained to evaluate the actual condition of fixtures and equipment prior to replacement.

## MECHANICAL

### HEATING

The building is served by an oil fired gravity vent hot water boiler located in the basement that is in fair condition. There is a single 275 gallon oil tank in the basement with exterior fill and vent connections piped from the front of the building. The plant consists of (4) zones, each with a dedicated circulator pump, all of which are in good condition. Controls are very basic, wall mounted dial thermostats wired in parallel to a common boiler relay module. The boiler also serves the domestic water heating needs (see Plumbing Section below).

The four heating zones include 3 on the first floor (2 in front, 1 in rear) and the fourth incorporating the entire second floor. Radiation equipment is a combination of steel and cast iron baseboards generally along the perimeter of each room except for a couple of short lengths in the central corridor of the first floor. There is also a small hot water unit heat in the basement that appears to be supplied from one of the first floor zone supply lines.

There are several small lengths of electric baseboard heat in the main corridor on the first floor and at the bottom of the rear stairwell plus a small recessed wall mounted electric cabinet heater in the kitchen on the second floor.

### AIR CONDITIONING

There is no central air conditioning system in the building. Several window/wall mount units were noted in the storage area and it is assumed they are used in the warmer months for local room conditioning as needed.

### VENTILATION

There is no mechanical ventilation system in the building but there are operable windows throughout that appear to be of adequate free area to meet the natural ventilation code requirements.

There are ceiling cabinet fan/light combination units in each of the first floor bathrooms and in one of the second floor bathrooms but no exhaust at all in the front bathroom on the second floor. There is also a cabinet style exhaust fan mounted in the wall of the stairs leading to the basement that pulls air from the first floor and blows it into the basement. It is unclear what the purpose of this unit is. The electric range/oven in on the second floor has a local recirculation hood over it as well.

## RECOMMENDATIONS

Upgrade the boiler plant from oil to a gas-fired condensing unit to save energy with better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

Replace existing thermostats with programmable type.

Provide an exhaust fan to serve the bathroom on the second floor.

## ELECTRICAL

### EXISTING SYSTEMS

This building appears to be served by (3) electrical services evident by the (3) revenue meters located on the outside of the building.

One electric service is located in the basement. This is a 200amp, single phase electric service. There is a meter socket and panelboard that make up the service equipment. This equipment is in fair to poor condition.

There are newer electrical panels located throughout the building. We believe these are part of the other (2) electrical services, although this could not be verified. These panelboards are in good condition.

The exposed wiring in the basement consists of many different types of wiring. Some of this wiring is very old and in poor condition.

The lighting throughout the building consists of recessed or surface mounted fluorescent fixtures. These fixtures are in good condition.

The lighting in the basement is in poor condition and additional fixtures are required for proper lighting for service, etc.

Emergency lighting consists of two-head self-contained battery units. These units are in good condition.

Exit signs are fluorescent units. These signs are in good condition.

### RECOMMENDATIONS

Provide new lighting, including emergency lighting in the basement.

Provide exterior emergency lighting.

## PLUMBING

### EXISTING SYSTEMS

Cold water is from a well. The pump for the system is in the well, therefore the condition of the pump is not included in this study. The compression tank for the system is adjacent to the boiler in the basement, and it appears to be in fair to good condition.

Hot water is provided via a coil in the heating boiler. The hot water discharge from coil is routed through a manually adjustable mixing valve, thereby tempering the water so that it is not too hot at the fixtures.

The exposed water piping in the basement is copper, and it appears to be in fair to good condition. The exposed drain piping in the basement is cast iron, plastic, and copper, and it appears to be in fair to good condition.

The water closet in the main floor restroom is a floor mount vitreous china tank type unit, and it appears to be in good condition. The water closets in the two restrooms upstairs are the floor mount vitreous china tank type units, they are not accessible, and they appear to be in fair to good condition. None of the water closets are low flow.

The lavatory in the main floor restroom is the wall mounted vitreous china type, it is accessible, and it appears to be in good condition. The lavatories in the two restrooms upstairs are the molded into the countertop vitreous china type and they are not accessible. One of the lavatories upstairs appears to be in fair to good condition, whereas the other appears to be in poor to fair condition.

One of the restrooms upstairs has a tub, either vitreous china or enameled steel/cast iron, and it appears to be in fair condition. The shower valve for this tub is not pressure balanced.

The other restroom upstairs has a multiple piece shower surround that appears to be in poor condition. The valve for this shower is not pressure balanced.

The kitchen upstairs has a double bowl stainless steel sink. Both the sink and the faucet appear to be in fair to good condition.

### RECOMMENDATIONS

The water closets should be replaced by low flow fixtures.

The lavatory upstairs in fair to poor condition should be replaced.

The multiple piece shower surround should be replaced, and both of the shower valves should be replaced by pressure balanced valves.

## **FIRE PROTECTION**

The building does not have a sprinkler system.







Description	Note	Quantity	Unit	Price	Total
Basic Quantities		GFA	Girth		
level 1		3,494	sf	397 lf	
level 2		2,278	sf	216 lf	
<b>General</b>					
3 Handicapped Ramps					\$
demo half existing handicapped ramp		277	sf	11.48	3,180
demo existing railings		55	lf	4.97	273
new handicapped ramp - triple switch back into confined space		1	ea	35,042.79	35,043
dumpster rental		1	weeks	753.69	754
load & truck	10 mile round trip	20	cy	56.70	1,134
dump charges		8	ton	89.37	715
Sub Total - Direct Cost					41,099
General Conditions		20.00%			8,220
Overhead & Profit		23.00%			11,343
Design & Price Reserve		15.00%			9,099
Escalation	Aug-15	8.16%			5,692
Bond		3.00%			2,264
Soft Costs/Design Fees		30.00%			23,315
Total Project Cost					101,032
3 Repoint Chimney					\$
cut and repoint chimney		60	sf	31.67	1,900
install stainless steel chimney cap		1	ea	242.00	242
staging		60	sf	3.24	194
Sub Total - Direct Cost					2,336
General Conditions		20.00%			467
Overhead & Profit		23.00%			645
Design & Price Reserve		15.00%			517
Escalation	Aug-15	8.16%			324
Bond		3.00%			129
Soft Costs/Design Fees		30.00%			1,325
Total Project Cost					\$5,743
3 Exterior Painting					\$
scape, sand, prime, paint structure		7,356	sf	2.89	21,259
Sub Total - Direct Cost					21,259

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX  
BRIMFIELD, MA 01010

GFA

5,772



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			4,252
Overhead & Profit		23.00%			5,868
Design & Price Reserve		15.00%			4,707
Escalation	Aug-15	8.16%			2,945
Bond		3.00%			1,171
Soft Costs/Design Fees		30.00%			12,061
<b>Total Project Cost</b>					<b>\$52,263</b>
<b>3 Roof Damage At Main Entry Skylight</b>					<b>\$</b>
demo roof shingles as required	allowance small arc	100	sf	2.42	242
disposal		1	ea	96.80	97
flashing at skylight	allowance	16	lf	14.52	232
new shingles around skylight	allowance	100	sf	3.93	393
<b>Sub Total - Direct Cost</b>					<b>964</b>
General Conditions		20.00%			193
Overhead & Profit		23.00%			266
Design & Price Reserve		15.00%			213
Escalation	Aug-15	8.16%			133
Bond		3.00%		288.95	53
Soft Costs/Design Fees		30.00%			547
<b>Total Project Cost</b>					<b>\$2,369</b>
<b>3 Side Entrance Steps</b>					<b>\$</b>
demo concrete steps		16	lfr	11.19	179
demo landing		20	sf	11.19	224
demo railing		12	lf	3.39	41
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
secure door shut		1	ea	164.55	165
clean and paint window		1	ea	336.88	337
<b>Sub Total - Direct Cost</b>					<b>3,483</b>
General Conditions		20.00%			697
Overhead & Profit		23.00%			961
Design & Price Reserve		15.00%			771
Escalation	Aug-15	8.16%			482
Bond		3.00%			192
Soft Costs/Design Fees		30.00%			1,976
<b>Total Project Cost</b>					<b>\$8,562</b>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX  
BRIMFIELD, MA 01010

GFA

5,772



Description	Note	Quantity	Unit	Price	Total
<b>3 Main Street Stoop</b>					<b>\$</b>
demo brick stoop		16	sf	9.68	155
disposal		1	ea	72.60	73
new brick stoop		42	sf	51.88	2,179
guardrails		14	lf	107.32	1,502
paint guardrails		14	lf	14.70	206
Sub Total - Direct Cost					4,115
General Conditions		20.00%			823
Overhead & Profit		23.00%			1,136
Design & Price Reserve		15.00%			911
Escalation	Aug-15	8.16%			570
Bond		3.00%			227
Soft Costs/Design Fees		30.00%			2,335
<b>Total Project Cost</b>					<b>\$10,117</b>
<b>3 Wood Rot At Grade</b>					<b>\$</b>
demo trim at grade		50	lf	1.83	92
disposal		1	ea	48.40	48
new trim at grade 1x6		50	lf	5.02	251
paint trim		72	lf	3.06	220
Sub Total - Direct Cost					611
General Conditions		20.00%			122
Overhead & Profit		23.00%			169
Design & Price Reserve		15.00%			135
Escalation	Aug-15	8.16%			85
Bond		3.00%			34
Soft Costs/Design Fees		30.00%			347
<b>Total Project Cost</b>					<b>\$1,503</b>
<b>3 Replace Missing Fascia</b>					<b>\$</b>
replace missing fascia around entire structure and paint materials		8	days	370.64	2,965
		1	ea	1,785.36	1,785
Sub Total - Direct Cost					4,750
General Conditions		20.00%			950
Overhead & Profit		23.00%			1,311
Design & Price Reserve		15.00%			1,052
Escalation	Aug-15	8.16%			658
Bond		3.00%			262
Soft Costs/Design Fees		30.00%			2,695
<b>Total Project Cost</b>					<b>\$11,678</b>



Description	Note	Quantity	Unit	Price	Total
3 Cracked Foundation Wall					\$
repair cracked foundation		1	ea	324.25	324
repoint wall area	small area	10	sf	31.67	317
Sub Total - Direct Cost					641
General Conditions		20.00%			128
Overhead & Profit		23.00%			177
Design & Price Reserve		15.00%			142
Escalation	Aug-15	8.16%			89
Bond		3.00%			35
Soft Costs/Design Fees		30.00%			364
Total Project Cost					<u>1,576</u>
3 Reset Stone Under Bay Window					\$
reset stone under bay window	allowance	2	days	883.74	1,767
repoint stone	allowance	48	sf	31.67	1,520
Sub Total - Direct Cost					3,287
General Conditions		20.00%			657
Overhead & Profit		23.00%			907
Design & Price Reserve		15.00%			728
Escalation	Aug-15	8.16%			455
Bond		3.00%			181
Soft Costs/Design Fees		30.00%			1,865
Total Project Cost					<u>8,080</u>
3 Fire Escape					\$
remove fire escape	laborer	1	day	422.30	422
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
patch siding as required	carpenter	1	day	542.64	543
materials	allowance	1	ea	115.60	116
Sub Total - Direct Cost					3,618
General Conditions		20.00%			724
Overhead & Profit		23.00%			999
Design & Price Reserve		15.00%			801
Escalation	Aug-15	8.16%			501
Bond		3.00%			199
Soft Costs/Design Fees		30.00%			2,053
Total Project Cost					<u>8,895</u>



Description	Note	Quantity	Unit	Price	Total
<b>3 Window Shutters</b>					<b>\$</b>
repair/replace missing louvers		33	ea	271.32	8,954
paint shutters		33	ea	153.13	5,053
Sub Total - Direct Cost					<u>14,007</u>
General Conditions		20.00%			2,801
Overhead & Profit		23.00%			3,866
Design & Price Reserve		15.00%			3,101
Escalation	Aug-15	8.16%			1,940
Bond		3.00%			771
Soft Costs/Design Fees		30.00%			7,946
Total Project Cost					<u><u>\$34,432</u></u>
<b>3 Second Floor Doors Locked And Signage</b>					<b>\$</b>
lock all second floor doors	allowance	7	loc	92.27	646
signage	allowance	7	ea	91.96	644
Sub Total - Direct Cost					<u>1,290</u>
General Conditions		20.00%			258
Overhead & Profit		23.00%			356
Design & Price Reserve		15.00%			286
Escalation	Aug-15	8.16%			179
Bond		3.00%			71
Soft Costs/Design Fees		30.00%			732
Total Project Cost					<u><u>\$3,172</u></u>
<b>3 Remove Vestibule</b>					<b>\$</b>
demo wall	small area	96	sf	2.42	232
demo door/frame/hardware		1	ea	47.96	48
disposal		1	ea	96.80	97
secure door shut		1	ea	164.55	165
patch finishes as required		1	ea	578.00	578
Sub Total - Direct Cost					<u>1,120</u>
General Conditions		20.00%			224
Overhead & Profit		23.00%			309
Design & Price Reserve		15.00%			248
Escalation	Aug-15	8.16%			155
Bond		3.00%			62
Soft Costs/Design Fees		30.00%			635
Total Project Cost					<u><u>\$2,753</u></u>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX  
BRIMFIELD, MA 01010

GFA

5,772



Description	Note	Quantity	Unit	Price	Total
<b>3 Ceiling Cracks And Roof</b>					<b>\$</b>
misc. roof repairs and flashings		2,278	sf	4.84	11,026
Sub Total - Direct Cost					11,026
General Conditions		20.00%			2,205
Overhead & Profit		23.00%			3,043
Design & Price Reserve		15.00%			2,441
Escalation	Aug-15	8.16%			1,527
Bond		3.00%			607
Soft Costs/Design Fees		30.00%			6,255
Total Project Cost					<u>\$27,104</u>
<b>3 First Floor Floors</b>					<b>\$</b>
reinforce floors as required from basement	allowance	3,494	sf	14.52	50,733
repair floor finishes as required	allowance	3,494	sf	1.94	6,778
Sub Total - Direct Cost					57,511
General Conditions		20.00%			11,502
Overhead & Profit		23.00%			15,873
Design & Price Reserve		15.00%			12,733
Escalation	Aug-15	8.16%			7,966
Bond		2.40%			2,534
Soft Costs/Design Fees		30.00%			32,436
Total Project Cost					<u>\$140,555</u>
<b>2 Handrail To Second Floor</b>					<b>\$</b>
repair handrail and resecure		12	lf	33.88	407
Sub Total - Direct Cost					407
General Conditions		20.00%			81
Overhead & Profit		23.00%			112
Design & Price Reserve		15.00%			90
Escalation	Aug-15	8.16%			56
Bond		3.00%			22
Soft Costs/Design Fees		30.00%			230
Total Project Cost					<u>\$998</u>
<b>3 Threshold</b>					<b>\$</b>
demo threshold		3	lf	48.40	145
disposal		1	ea	24.20	24
new threshold		3	lf	30.86	93
Sub Total - Direct Cost					262



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			52
Overhead & Profit		23.00%			72
Design & Price Reserve		15.00%			58
Escalation	Aug-15	8.16%			36
Bond		3.00%			14
Soft Costs/Design Fees		30.00%			148
<b>Total Project Cost</b>					<b>\$642</b>

<b>3 Cemetery Office Ceiling</b>					<b>\$</b>
repair ceiling	small area	8	sf	18.38	147
paint ceiling	small area	106	sf	2.72	288
<b>Sub Total - Direct Cost</b>					<b>435</b>
General Conditions		20.00%			87
Overhead & Profit		23.00%			120
Design & Price Reserve		15.00%			96
Escalation	Aug-15	8.16%			60
Bond		3.00%			24
Soft Costs/Design Fees		30.00%			247
<b>Total Project Cost</b>					<b>\$1,069</b>

**Structural**

<b>3 First Floor Framing</b>					<b>\$</b>
reinforce floors as required from basement	allowance	3,494	sf	14.52	50,733
repair floor finishes as required	allowance	3,494	sf	1.94	6,778
<b>Sub Total - Direct Cost</b>					<b>57,511</b>
General Conditions		20.00%			11,502
Overhead & Profit		23.00%			15,873
Design & Price Reserve		15.00%			12,733
Escalation	Aug-15	8.16%			7,966
Bond		2.40%			2,534
Soft Costs/Design Fees		30.00%			32,436
<b>Total Project Cost</b>					<b>\$140,555</b>

<b>2 Roof And Surface Water</b>					<b>\$</b>
gutters	allowance	405	lf	22.26	9,015
downspouts	allowance	288	lf	30.98	8,922
pipng away from foundation	allowance	128	lf	30.98	3,965
repoint wall joints as required	allowance	192	lf	31.67	6,081
<b>Sub Total - Direct Cost</b>					<b>27,983</b>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX  
BRIMFIELD, MA 01010

GFA

5,772



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			5,597
Overhead & Profit		23.00%			7,723
Design & Price Reserve		15.00%			6,195
Escalation	Aug-15	8.16%			3,876
Bond		3.00%			1,541
Soft Costs/Design Fees		30.00%			15,875
<b>Total Project Cost</b>					<b>\$68,790</b>
<b>3 Second Floor Framing</b>					<b>\$</b>
reinforce floors as required	allowance	2,278	sf	14.52	33,077
repair floor finishes as required	allowance	2,278	sf	1.94	4,419
<b>Sub Total - Direct Cost</b>					<b>37,496</b>
General Conditions		20.00%			7,499
Overhead & Profit		23.00%			10,349
Design & Price Reserve		15.00%			8,302
Escalation	Aug-15	8.16%			5,194
Bond		3.00%			2,065
Soft Costs/Design Fees		30.00%			21,272
<b>Total Project Cost</b>					<b>\$92,177</b>
<b>3 Handicapped Ramps</b>					<b>\$</b>
demo half existing handicapped ramp		277	sf	11.48	3,180
demo existing railings		55	lf	4.97	273
new handicapped ramp - triple switch back into confined space		1	ea	35,042.79	35,043
dumpster rental		1	weeks	753.69	754
load & truck	10 mile round trip	20	cy	56.70	1,134
dump charges		8	ton	89.37	715
<b>Sub Total - Direct Cost</b>					<b>41,099</b>
General Conditions		20.00%			8,220
Overhead & Profit		23.00%			11,343
Design & Price Reserve		15.00%			9,099
Escalation	Aug-15	8.16%			5,692
Bond		3.00%			2,264
Soft Costs/Design Fees		30.00%			23,315
<b>Total Project Cost</b>					<b>101,032</b>
<b>1 Supporting Post For Loft shoring</b>					<b>\$</b>
		44	lf	95.60	4,206
<b>Sub Total - Direct Cost</b>					<b>4,206</b>



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX  
BRIMFIELD, MA 01010

GFA

5,772



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			841
Overhead & Profit		23.00%			1,161
Design & Price Reserve		15.00%			931
Escalation	Aug-15	8.16%			583
Bond		3.00%			232
Soft Costs/Design Fees		30.00%			2,386
<b>Total Project Cost</b>					<b>\$10,340</b>
<b>3 Barn First Floor Framing</b>					
reinforce floors as required	allowance	833	sf	24.20	\$ 20,159
Sub Total - Direct Cost					20,159
General Conditions		20.00%			4,032
Overhead & Profit		23.00%			5,564
Design & Price Reserve		15.00%			4,463
Escalation	Aug-15	8.16%			2,792
Bond		3.00%			1,110
Soft Costs/Design Fees		30.00%			11,436
<b>Total Project Cost</b>					<b>\$49,556</b>
<b>3 Barn Foundation</b>					
jack and reset barn	allowance	833	sf	14.52	\$ 12,095
demo existing foundation	allowance	833	sf	4.84	4,032
new foundation including slab	allowance	833	sf	24.92	20,758
Sub Total - Direct Cost					36,885
General Conditions		20.00%			7,377
Overhead & Profit		23.00%			10,180
Design & Price Reserve		15.00%			8,166
Escalation	Aug-15	8.16%			5,109
Bond		3.00%			2,032
Soft Costs/Design Fees		30.00%			20,925
<b>Total Project Cost</b>					<b>\$90,674</b>
<b>3 Barn Walls</b>					
demo barn exterior walls	allowance	1,284	sf	14.52	\$ 18,644
temporary shoring	allowance	107	lf	96.80	10,358
new barn board studded walls	allowance	1,284	sf	4.11	5,277
dumpster rental		2	weeks	753.69	1,507
load & truck	10 mile round trip	20	cy	56.70	1,134
dump charges		8	ton	89.37	715
Sub Total - Direct Cost					37,635



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			7,527
Overhead & Profit		23.00%			10,387
Design & Price Reserve		15.00%			8,332
Escalation	Aug-15	8.16%			5,213
Bond		3.00%			2,073
Soft Costs/Design Fees		30.00%			21,350
<b>Total Project Cost</b>					<b>\$92,517</b>

**Mechanical**

4	Replace Oil Fired Equipment					
	remove oil fired equipment		1	ea	753.06	753
	disposal		1	ea	242.00	242
	new gas service - trench only - service by gas company		200	lf	26.18	5,236
	misc. exterior repairs from trench		1	ea	1,936.00	1,936
	cast iron gas boiler	300mbh	1	ea	8,606.06	8,606
	hot water pumps	40gpm	2	ea	2,629.12	5,258
	gas piping allowance	1 1/4"	100	lf	16.95	1,695
	<b>Sub Total - Direct Cost</b>					<b>23,726</b>

General Conditions		20.00%			4,745
Overhead & Profit		23.00%			6,548
Design & Price Reserve		15.00%			5,253
Escalation	Aug-15	8.16%			3,286
Bond		3.00%			1,307
Soft Costs/Design Fees		30.00%			13,460
<b>Total Project Cost</b>					<b>58,325</b>

3	Replace Existing Thermostats					
	demo existing thermostats	allowance	15	ea	72.60	1,089
	disposal		1	ea	48.40	48
	new thermostats	allowance	15	ea	256.75	3,851
	<b>Sub Total - Direct Cost</b>					<b>4,988</b>

General Conditions		20.00%			998
Overhead & Profit		23.00%			1,377
Design & Price Reserve		15.00%			1,104
Escalation	Aug-15	8.16%			691
Bond		3.00%			275
Soft Costs/Design Fees		30.00%			2,830
<b>Total Project Cost</b>					<b>12,263</b>



Description	Note	Quantity	Unit	Price	Total
<b>Electrical</b>					
Upgrade Lighting					
demo lighting		5,772	sf	0.58	3,348
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
upgrade lighting throughout		5,772	sf	14.75	85,137
Sub Total - Direct Cost					91,022
General Conditions		20.00%			18,204
Overhead & Profit		23.00%			25,122
Design & Price Reserve		15.00%			20,152
Escalation	Aug-15	8.16%			12,607
Bond		2.40%			4,011
Soft Costs/Design Fees		30.00%			51,335
Total Project Cost					222,453
2 Upgrade Exterior Lighting					
demo exterior lighting fixture	allowance	10	ea	72.60	726
disposal		1	ea	145.20	145
upgrade existing exterior lighting to LED	allowance	10	ea	771.00	7,710
Sub Total - Direct Cost					8,581
General Conditions		20.00%			1,716
Overhead & Profit		23.00%			2,368
Design & Price Reserve		15.00%			1,900
Escalation	Aug-15	8.16%			1,189
Bond		3.00%			473
Soft Costs/Design Fees		30.00%			4,868
Total Project Cost					\$21,095
<b>Plumbing</b>					
Upgrade Fixtures To Low Flow					
demo fixtures		1	ea	145.20	145
toilet		1	ea	2,485.34	2,485
Sub Total - Direct Cost					2,630
General Conditions		20.00%			526
Overhead & Profit		23.00%			726
Design & Price Reserve		15.00%			582
Escalation	Aug-15	8.16%			364
Bond		3.00%			145
Soft Costs/Design Fees		30.00%			1,492
Total Project Cost					\$6,465



Description	Note	Quantity	Unit	Price	Total
Town Hall Annex 2 Story Additon/Renovation					\$
Town Hall Annex 2 story addition/renovation		8,290	sf	350.66	2,906,971
Sub Total - Direct Cost					2,906,971
General Conditions		10.00%			290,697
Overhead & Profit		12.00%			383,720
Design & Price Reserve		15.00%			537,208
Escalation	Aug-15	8.16%			336,077
Bond		1.60%			71,275
Soft Costs/Design Fees		30.00%			1,357,784
Total Project Cost					<u>\$5,883,732</u>
Town Hall Annex 1 Story Additon/Renovation					\$
Town Hall Annex 1 story addition/renovation		6,681	sf	297.62	1,988,399
Sub Total - Direct Cost					1,988,399
General Conditions		12.00%			238,608
Overhead & Profit		12.00%			267,241
Design & Price Reserve		15.00%			374,137
Escalation	Aug-15	8.16%			234,060
Bond		1.60%			49,639
Soft Costs/Design Fees		30.00%			945,625
Total Project Cost					<u>\$4,097,709</u>



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL ANNEX RENOVATION AND ADDITION 1 STORY  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Annex Renovation And Addit GFA(SF):		6,681		Date: Jul-13		Sheet No: 1 OF 2	
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
<b>A SUBSTRUCTURE</b>		114,466	17.13	5.8%			
A10 Foundations	108,418		16.23		4,447 SF	SF	24.38
A20 Basement Construction	6,048		0.91		4,447 SF	SF	1.36
<b>B SHELL</b>		703,114	105.24	35.4%			
B10 Superstructure	227,132		34.00		6,681 SF	SF	34.00
B20 Exterior Closure	390,377		58.43		5,684 SF	SF	68.68
B30 Roofing	85,605		12.81		4,447 SF	SF	19.25
<b>C INTERIORS</b>		279,900	41.89	14.1%			
C10 Interior Construction	164,486		24.62		6,681 SF	SF	24.62
C20 Stairs	0		0.00		0 FLT	FLT	0.00
C30 Interior Finishes	115,414		17.27		6,681 SF	SF	17.27
<b>D SERVICES</b>		484,585	72.53	24.4%			
D10 Conveying Systems	0		0.00		0 STOP	STOP	0.00
D20 Plumbing	61,392		9.19		6,681 SF	SF	9.19
D30 HVAC	244,543		36.60		6,681 SF	SF	36.60
D40 Fire Protection	30,065		4.50		6,681 SF	SF	4.50
D50 Electrical Systems	148,585		22.24		6,681 SF	SF	22.24
<b>E EQUIPMENT &amp; FURNISHINGS</b>		89,267	13.36	4.5%			
E10 Equipment	33,739		5.05		6,681 SF	SF	5.05
E20 Furnishings	55,528		8.31		6,681 SF	SF	8.31

COSTPRO INC.

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL ANNEX RENOVATION AND ADDITION 1 STORY  
 BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Annex Renovation And Addit		Date: Jul-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		42,960	6.43	2.2%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	42,960		6.43		3,494	SF	12.30
G BUILDING SITEWORK		274,088	41.02	13.8%			
G10 Site Preparation	48,676		7.29		6,681	SF	7.29
G20 Site Improvements	89,011		13.32		6,681	SF	13.32
G30 Site Civil/Mechanical Utilities	96,175		14.40		6,681	SF	14.40
G40 Site Electrical Utilities	40,226		6.02		6,681	SF	6.02
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		1,988,380	297.62	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	1,988,380	297.62				

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL ANNEX RENOVATION AND ADDITION 2 STORY  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Annex Renovation And Addit GFA(SF):		8,290	Date: Jul-13	Sheet No: 1 OF 2				
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element	Unit	Element
		\$	\$	Floor Area		Quantities		Unit Rate
<b>A</b>	<b>SUBSTRUCTURE</b>		106,692		3.7%			
	A10 Foundations	101,055		12.19		4,145 SF	SF	24.38
	A20 Basement Construction	5,637		0.68		4,145 SF	SF	1.36
<b>B</b>	<b>SHELL</b>		899,252		30.9%			
	B10 Superstructure	386,777		46.66		10,012 SF	SF	38.63
	B20 Exterior Closure	432,684		52.19		6,300 SF	SF	68.68
	B30 Roofing	79,791		9.62		4,145 SF	SF	19.25
<b>C</b>	<b>INTERIORS</b>		613,154		21.1%			
	C10 Interior Construction	246,496		29.73		10,012 SF	SF	24.62
	C20 Stairs	196,350		23.69		3 FLT	FLT	65450.00
	C30 Interior Finishes	170,308		20.54		10,012 SF	SF	17.01
<b>D</b>	<b>SERVICES</b>		809,218		27.8%			
	D10 Conveying Systems	65,000		7.84		2 STOP	STOP	32500.00
	D20 Plumbing	93,513		11.28		10,012 SF	SF	9.34
	D30 HVAC	382,984		46.20		10,012 SF	SF	38.25
	D40 Fire Protection	45,054		5.43		10,012 SF	SF	4.50
	D50 Electrical Systems	222,667		26.86		10,012 SF	SF	22.24
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		141,985		4.9%			
	E10 Equipment	50,561		6.10		10,012 SF	SF	5.05
	E20 Furnishings	91,424		11.03		10,012 SF	SF	9.13



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 TOWN HALL ANNEX RENOVATION AND ADDITION 2 STORY  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Town Hall Annex Renovation And Addit		Date: Jul-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		56,205	6.78	1.9%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	56,205		6.78		5,772	SF	9.74
G BUILDING SITEWORK		280,465	33.83	9.6%			
G10 Site Preparation	45,609		5.50		10,012	SF	4.56
G20 Site Improvements	102,637		12.38		10,012	SF	10.25
G30 Site Civil/Mechanical Utilities	93,261		11.25		10,012	SF	9.31
G40 Site Electrical Utilities	38,958		4.70		10,012	SF	3.89
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		2,906,971	350.66	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	2,906,971	350.66				



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
TOWN HALL  
BRIMFIELD, MA 01010

GFA 14,859



Description	Note	Quantity	Unit	Price	Total
New Town Complex - Town Hall Component					
New Town Complex - Town Hall Component		6,770	sf	301.10	2,038,474
Sub Total - Direct Cost					2,038,474
General Conditions		6.00%			122,308
Overhead & Profit		6.00%			129,647
Design & Price Reserve		15.00%			343,564
Escalation	Aug-15	8.16%			214,934
Bond		1.34%			38,176
Soft Costs/Design Fees		30.00%			866,131
Total Project Cost					3,753,234
New Town Complex - Police Station Component					
New Town Complex - Police Station Component		4,119	sf	307.40	1,266,190
Sub Total - Direct Cost					1,266,190
General Conditions		6.00%			75,971
Overhead & Profit		6.00%			80,530
Design & Price Reserve		15.00%			213,404
Escalation	Aug-15	8.16%			133,505
Bond		1.34%			23,713
Soft Costs/Design Fees		30.00%			537,994
Total Project Cost					2,331,307
New Town Complex - Senior Center Component					
New Town Complex - Senior Center Component		3,970	sf	309.45	1,228,520
Sub Total - Direct Cost					1,228,520
General Conditions		6.00%			73,711
Overhead & Profit		6.00%			78,134
Design & Price Reserve		15.00%			207,055
Escalation	Aug-15	8.16%			129,533
Bond		1.34%			23,007
Soft Costs/Design Fees		30.00%			521,988
Total Project Cost					2,261,948

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
NEW TOWN HALL - SENIOR CENTER - POLICE STATION  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Town Hall-Senior Center-Police		GFA(SF):	14,859	Date:	Oct-13	Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element	Unit	Element
		\$	\$	Floor Area		Quantities		Unit Rate
<b>A</b>	<b>SUBSTRUCTURE</b>		382,471	25.74	8.4%			
	A10 Foundations	362,263		24.38		14,859	SF	24.38
	A20 Basement Construction	20,208		1.36		14,859	SF	1.36
<b>B</b>	<b>SHELL</b>		1,392,568	93.72	30.7%			
	B10 Superstructure	357,507		24.06		14,859	SF	24.06
	B20 Exterior Closure	749,024		50.41		10,906	SF	68.68
	B30 Roofing	286,037		19.25		14,859	SF	19.25
<b>C</b>	<b>INTERIORS</b>		638,639	42.98	14.1%			
	C10 Interior Construction	365,828		24.62		14,859	SF	24.62
	C20 Stairs	0		0.00		0	FLT	0.00
	C30 Interior Finishes	272,811		18.36		14,859	SF	18.36
<b>D</b>	<b>SERVICES</b>		1,162,719	78.25	25.6%			
	D10 Conveying Systems	0		0.00		0	STOP	0.00
	D20 Plumbing	144,876		9.75		14,859	SF	9.75
	D30 HVAC	572,072		38.50		14,859	SF	38.50
	D40 Fire Protection	66,866		4.50		14,859	SF	4.50
	D50 Electrical Systems	378,905		25.50		14,859	SF	25.50
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		262,128	17.64	5.8%			
	E10 Equipment	188,575		12.69		14,859	SF	12.69
	E20 Furnishings	73,553		4.95		14,859	SF	4.95



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW TOWN HALL - SENIOR CENTER - POLICE STATION  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Town Hall-Senior Center-Police		Date: Oct-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		0	0.00	0.0%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	0		0.00		0	SF	0.00
G BUILDING SITEWORK		694,659	46.75	15.3%			
G10 Site Preparation	74,295		5.00		14,859	SF	5.00
G20 Site Improvements	297,180		20.00		14,859	SF	20.00
G30 Site Civil/Mechanical Utilities	222,885		15.00		14,859	SF	15.00
G40 Site Electrical Utilities	100,299		6.75		14,859	SF	6.75
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		4,533,184	305.08	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	4,533,184	\$		305.08		

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
NEW TOWN HALL COMBINED  
BRIMFIELD, MA 01010



COSTPRO, INC.

Project Cost Plan (Uniformat II Level 3)

Project: Town Hall Component		GFA(SF):		6,770		Date: Oct-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element Quantities	Unit	Element Unit Rate		
		\$	\$	Floor Area						
<b>A</b>	<b>SUBSTRUCTURE</b>		174,260	25.74	8.5%					
	A10 Foundations	165,053		24.38		6,770	SF	24.38		
	A20 Basement Construction	9,207		1.36		6,770	SF	1.36		
<b>B</b>	<b>SHELL</b>		646,087	95.43	31.7%					
	B10 Superstructure	162,886		24.06		6,770	SF	24.06		
	B20 Exterior Closure	352,878		52.12		5,138	SF	68.68		
	B30 Roofing	130,323		19.25		6,770	SF	19.25		
<b>C</b>	<b>INTERIORS</b>		290,974	42.98	14.3%					
	C10 Interior Construction	166,677		24.62		6,770	SF	24.62		
	C20 Stairs	0		0.00		0	FLT	65450.00		
	C30 Interior Finishes	124,297		18.36		6,770	SF	18.36		
<b>D</b>	<b>SERVICES</b>		529,753	78.25	26.0%					
	D10 Conveying Systems	0		0.00		0	STOP	32500.00		
	D20 Plumbing	66,008		9.75		6,770	SF	9.75		
	D30 HVAC	260,645		38.50		6,770	SF	38.50		
	D40 Fire Protection	30,465		4.50		6,770	SF	4.50		
	D50 Electrical Systems	172,635		25.50		6,770	SF	25.50		
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		80,902	11.95	4.0%					
	E10 Equipment	47,390		7.00		6,770	SF	7.00		
	E20 Furnishings	33,512		4.95		6,770	SF	4.95		



COSTPRO, INC.

0

Project Cost Plan (Uniformat II Level 3)

Project: Town Hall Component		Date: Oct-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		0	0.00	0.0%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	0		0.00		0	SF	2.95
G BUILDING SITEWORK		316,498	46.75	15.5%			
G10 Site Preparation	33,850		5.00		6,770	SF	5.00
G20 Site Improvements	135,400		20.00		6,770	SF	20.00
G30 Site Civil/Mechanical Utilities	101,550		15.00		6,770	SF	15.00
G40 Site Electrical Utilities	45,698		6.75		6,770	SF	6.75
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		2,038,474	301.10	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	2,038,474	\$				
			301.10				

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
NEW POLICE STATION COMBINED  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Renovation Component		GFA(SF):		4,119 Date: Oct-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element Quantities	Element Unit	Element Unit Rate
		\$	\$	Floor Area				
<b>A</b>	<b>SUBSTRUCTURE</b>		106,023	25.74	8.4%			
	A10 Foundations	100,421		24.38		4,119 SF	SF	24.38
	A20 Basement Construction	5,602		1.36		4,119 SF	SF	1.36
<b>B</b>	<b>SHELL</b>		386,082	93.73	30.5%			
	B10 Superstructure	99,103		24.06		4,119 SF	SF	24.06
	B20 Exterior Closure	207,688		50.42		3,024 SF	SF	68.68
	B30 Roofing	79,291		19.25		4,119 SF	SF	19.25
<b>C</b>	<b>INTERIORS</b>		177,035	42.98	14.0%			
	C10 Interior Construction	101,410		24.62		4,119 SF	SF	24.62
	C20 Stairs	0		0.00		0 FLT	FLT	65450.00
	C30 Interior Finishes	75,625		18.36		4,119 SF	SF	18.36
<b>D</b>	<b>SERVICES</b>		322,313	78.25	25.5%			
	D10 Conveying Systems	0		0.00		0 STOP	STOP	32500.00
	D20 Plumbing	40,160		9.75		4,119 SF	SF	9.75
	D30 HVAC	158,582		38.50		4,119 SF	SF	38.50
	D40 Fire Protection	18,536		4.50		4,119 SF	SF	4.50
	D50 Electrical Systems	105,035		25.50		4,119 SF	SF	25.50
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		82,174	19.95	6.5%			
	E10 Equipment	61,785		15.00		4,119 SF	SF	15.00
	E20 Furnishings	20,389		4.95		4,119 SF	SF	4.95

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
NEW POLICE STATION COMBINED  
BRIMFIELD, MA 01010



Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Renovation Component		Date: Oct-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		0	0.00	0.0%			
F10 Special Construction	0		0.00		0	SF	0.00
F20 Selective Demolition	0		0.00		0	SF	2.95
G BUILDING SITEWORK		192,563	46.75	15.2%			
G10 Site Preparation	20,595		5.00		4,119	SF	5.00
G20 Site Improvements	82,380		20.00		4,119	SF	20.00
G30 Site Civil/Mechanical Utilities	61,785		15.00		4,119	SF	15.00
G40 Site Electrical Utilities	27,803		6.75		4,119	SF	6.75
G90 Other Site Construction	0		0.00		0	SF	0.00
SUBTOTAL		1,266,190	307.40	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	1,266,190	\$				
			307.40				

COSTPRO INC.  
TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
NEW SENIOR CENTER COMBINED  
BRIMFIELD, MA 01010



COSTPRO, INC.

Project Cost Plan (Uniformat II Level 3)

Project: Renovation Component		GFA(SF):		3,970		Date: Oct-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	%	Element Quantities	Unit	Element Unit Rate		
		\$	\$	Floor Area						
<b>A</b>	<b>SUBSTRUCTURE</b>		102,188	25.74	8.3%	3,970	SF	24.38		
	A10 Foundations	96,789		24.38						
	A20 Basement Construction	5,399		1.36						
<b>B</b>	<b>SHELL</b>		360,399	90.78	29.3%	3,970	SF	24.06		
	B10 Superstructure	95,518		24.06						
	B20 Exterior Closure	188,458		47.47						
	B30 Roofing	76,423		19.25						
<b>C</b>	<b>INTERIORS</b>		170,630	42.98	13.9%	3,970	SF	24.62		
	C10 Interior Construction	97,741		24.62						
	C20 Stairs	0		0.00		0	FLT	65450.00		
	C30 Interior Finishes	72,889		18.36		3,970	SF	18.36		
<b>D</b>	<b>SERVICES</b>		310,653	78.25	25.3%	0	STOP	32500.00		
	D10 Conveying Systems	0		0.00						
	D20 Plumbing	38,708		9.75		3,970	SF	9.75		
	D30 HVAC	152,845		38.50		3,970	SF	38.50		
	D40 Fire Protection	17,865		4.50		3,970	SF	4.50		
	D50 Electrical Systems	101,235		25.50		3,970	SF	25.50		
<b>E</b>	<b>EQUIPMENT &amp; FURNISHINGS</b>		99,052	24.95	8.1%	3,970	SF	20.00		
	E10 Equipment	79,400		20.00						
	E20 Furnishings	19,652		4.95		3,970	SF	4.95		





COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW SENIOR CENTER COMBINED  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Renovation Component		Date: Oct-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount \$	Total Cost \$	Rate \$/SF Floor Area	%	Element Quantities	Element Unit	Element Unit Rate
F SPECIAL CONSTRUCTION & DEMOLITION		0	0.00	0.0%			
F10 Special Construction	0		0.00		0 SF		0.00
F20 Selective Demolition	0		0.00		0 SF		2.95
G BUILDING SITEWORK		185,598	46.75	15.1%			
G10 Site Preparation	19,850		5.00		3,970 SF		5.00
G20 Site Improvements	79,400		20.00		3,970 SF		20.00
G30 Site Civil/Mechanical Utilities	59,550		15.00		3,970 SF		15.00
G40 Site Electrical Utilities	26,798		6.75		3,970 SF		6.75
G90 Other Site Construction	0		0.00		0 SF		0.00
SUBTOTAL		1,228,520	309.45	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0	0.00				
Z20 CONTINGENCIES	0.0%	0	0.00				
Z30 CM AT RISK PREMIUM	0.0%	0	0.00				
Z90 PROJECT COST ESTIMATE	\$	1,228,520	\$				
			309.45				

TOWN HALL ANNEX  
Program Areas

Currently Shared Spaces	EXISTING SPACE	EXISTING SPACE ELSEWHERE	EXISTING SPACE NOTES	PROPOSED AREA	SINGLE STORY SCHEME	SINGLE STORY NOTES	TWO STORY SCHEME (SECOND FLOOR SPACES IN BLUE)	TWO STORY NOTES
	694							
	694			694	694		694	
<b>TOWN HALL ANNEX - BASEMENT</b>								
	Mechanical / Open Space							
<b>TOTAL TOWN HALL ANNEX - BASEMENT</b>								

Currently Shared Spaces	EXISTING SPACE	EXISTING SPACE ELSEWHERE	EXISTING SPACE NOTES	PROPOSED AREA	SINGLE STORY SCHEME	SINGLE STORY NOTES	TWO STORY SCHEME (SECOND FLOOR SPACES IN BLUE)	TWO STORY NOTES
1	277			235	235		199	
1				200	235		202	
		549	Currently in Town Hall	150	191		154	
				450	453		504	2nd Floor
2	215			50	51		51	
				300	302		361	
				40	40		72	
		250	Currently on 2nd Floor	150	172		153	2nd Floor
2	25			50	23		290	Incl Mail & Supplies
		468	Currently in Town Hall	300	293		311	
		232	Currently in Town Hall	100	156		100	
		47	Currently in Town Hall	100	116		107	
		69	Currently in Town Hall	100	96		100	
	8			8	8			
3	274			200	198		198	
3				100	114		103	
				100	100		107	
				150	172		153	2nd Floor
	66				112	2 Rooms	157	3 Rooms
	20					Not Required	53	
	167			300	338		317	
4	106			150	164		153	2nd Floor
4								
		260	Currently on 2nd Floor	260	258		317	In Cemetery Comm. 2nd Floor
	172			250	277		250	2nd Floor
	30			50	50		59	2nd Floor
	128			275	275		310	
	60							In Offices
	0			200	159		201	
				150				See Copier
	277						97	2nd Floor
	23							
	795							
		638	Currently in Library					
	2643			4418	4588		535	
	624			1325	1775		5614	
	3267			5743	6363		3825	
<b>TOTAL TOWN HALL ANNEX</b>								

<b>TOWN HALL ANNEX - SECOND FLOOR</b>	
Conservation	260
Closet	12
Closet	14
Toilet And Shower #1	51
Treasurer	250
Corridor	98
Closet	11
Storage #1	296
Toilet And Shower #2	72
Kitchen	218
Closet	18
Storage #2	30

<b>TOTAL ANNEX -EXISTING SECOND FLOOR</b>	<b>1330</b>
-------------------------------------------	-------------

<b>TOWN HALL ANNEX - NET ROOM AREA</b>	
Basement	694
First Floor	3018
Second Floor	1330

<b>TOTAL TOWN HALL ANNEX - NET ROOM AREA</b>	<b>5042</b>
----------------------------------------------	-------------



BUILDING USE AUDIT - CONDITION ASSESSMENT  
Town of Brimfield, Massachusetts

**Brimfield Public Safety Headquarters**

34 Wales Road

Year Constructed: Unknown  
Addition Constructed: 1993  
Construction Type: IIB  
Fire Sprinklers: No  
Building Area: 5,647 SF



Documents Used in Study:  
Assessor Field Card

**General:**

**The building is not handicapped accessible:**


3 One (1) exterior and all interior doors are not equipped with lever hardware. Replace all hardware to meet code.

4 One toilet room is in general, but not full compliance with ADA and the other does not comply. Make minor modifications to door and clearances so at least one room fully complies.




3 Doors from Fire Equipment Bays into Day Room and Ambulance Office have door clearance issues. Reconfigure doors and partitions to provide the correct clearance.

3 Day Room kitchen base cabinet has no knee space and is not ADA compliant. Change base cabinets.




The sink in this base cabinet is not connected to any cold/hot water or to a waste line. The water supply is currently contaminated and bottled water is supplied to the facility. See Plumbing.

4 Suspended ceiling panels are aged (dull/dirty & sagging) and need to be replaced.



4 Replace (3) existing single pane steel windows in the Fire Equipment Bays with new insulated metal windows.



2 Install new Vehicle Exhaust Removal System in both the Fire Equipment Bays and Ambulance bays. (8 bays total)

3 Replace damaged existing single door between Day Room & Ambulance Bays with new insulated door.



4 Install new trench drain and associated piping in existing concrete slab in Fire Equipment Bays and Ambulance Bays. (8 bays total)



3 Install new closers on all doors (2 single & 1 double) from the Day Room into Fire / Ambulance Bays.

### Exterior

3 All existing gutters to be cleaned, reattached to fascia with slope to downspout and all joints and end caps sealed to stop water stains and damage to exterior walls.



3 Water from downspouts be piped away from the building, to minimize damage to cmu wall, foundation and finish grade. Clean all water stains from walls. Fill in all low spots to create a positive slope away from building.




3 Joint between original building and addition at west end is cracked. Saw cut joint and create expansion joint in wall.(Fire Equipment Bay #8)



3 Minor re-pointing of cmu and brick around entire existing building. (5%)

3 Replace aprons at overhead doors at front of building with concrete aprons with frost walls. Aprons to extend at least 4 feet from building.



- 3 Miscellaneous wood rot / damage and paint peeling at existing Texture 1-11 siding, door / window trim and fascia boards. Patch, prime and re-paint trim. Replace Texture 1-11 with painted cement siding. Replace trim at new siding.




- 3 Portions of trim at overhead doors are deteriorated or missing. Remove damaged sections and patch remainder. Replace missing trim at overhead door jambs. Repaint.



- 3 Repaint west wall of east Equipment Bays.

- 2 Bricks at corner of east wall are spalling. Replace damaged brick. Saw cut a joint between brick and CMU to create an expansion joint. Add filler, backer rod and sealant to joint.



- 3 Floor at overhead doors in east equipment bays is crack. Cut out damaged portions and replace doweling work into adjacent slabs. (It is suggested that this work be coordinated with the new trench drains and new concrete aprons)

- Exterior walls are uninsulated at Equipment Bays.

- 3 Hose Dryer is in need of replacement.

## MECHANICAL

- 4 Update heating equipment from oil to gas to save energy due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

- 3 Update to programmable type thermostats for control of the furnaces and/or the electric unit heaters.

- 3 Replace the common area furnace with two units and reconfigure the ductwork to provide better zoning and control. Separate the distribution to the police offices from that of the common area and provide dedicated thermostats for each unit.

- 3 Provide an exhaust fan in the bathroom adjacent to the EMT office.
- 3 Provide direct ducted outdoor air for the furnace serving the fire truck garage with a roof cap intake and damper assembly linked to the furnace operation. Also add a general exhaust fan in this garage to operate during occupied periods in conjunction with the furnace.
- 3 Replace the other garage's electric unit heaters with a warm air furnace and supply air distribution similar to the fire truck garage and provide a direct ducted outdoor air/intake and damper assembly as noted above. Also include a general exhaust fan in this garage to operate in conjunction with the new furnace.

## ELECTRICAL

- 3 The manual transfer switch should be replaced with an automatic transfer switch and controls.
- 2 New LED exit signs with integral batteries should be provided to replace the existing.
- 2 The exterior lighting should be replaced with a high-efficiency LED type fixture to improve the lighting levels and reduce energy costs.
- 2 A fire alarm system should also be added to the facility.

## PLUMBING

- 2 If it is determined that filtration and/or treatment could make the well water potable, a filtration and/or treatment system should be provided such that the well water is potable. As it is likely that the filtration/treatment system will reduce the water pressure to an unacceptable level, the well pump should be replaced by a higher head well pump.
- 2 Once the well water is made potable, a new faucet should be provided at the sink and it should be (re)connected to the water system.
- 3 The electric water heater should be replaced in the near future. The new water heater should be provided with a mixing valve, such that 140°F can be maintained in the tank without the possibility of scalding at the fixtures.
- 4 Both of the water closets should be replaced with low flow fixtures.

## **PROGRAM INFORMATION**


The building currently serves the Fire and Police departments, and Ambulance service. Workspaces are inadequate and do not meet the needs of the departments. The police were formally housed in Town Hall up until they were moved out due to structural issues with that building. If the police were moved out of this building, either to a new building or back to a renovated Town Hall the current Public Safety Building, with an addition, will be able to meet the needs of the Fire Department and Ambulance service. An addition is necessary to provide bunk rooms and the associated shower and locker rooms for the FD.

Equipment bays are very tight in area and height due to the configuration of the building. It is recommended that the roof of the two west bays be reconstructed to a higher elevation and two new overhead doors be provided on the north and south sides of these bays. With a new driveway along the north side of the building the larger pieces of FD equipment would have drive through bays. Smaller equipment would then be housed in the east end. Ambulance bays will remain in their current locations.

Refer to Public Safety Space Needs and associated Test Fit plans.







**FIRST FLOOR PLAN**

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts


**EXISTING PUBLIC SAFETY HEADQUARTERS FLOOR PLAN**



Scale: N.T.S.  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 4/17/13


**EX-PF1**





**FIRST FLOOR PLAN**


**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts  
**PROPOSED PUBLIC SAFETY HEADQUARTERS FLOOR PLAN**




Scale: N.T.S.  
 Drawn by: AJ/KCB  
 Job No. 13002.00  
 Date: 7-9-13

**PR-PF1**





**FIRST FLOOR PLAN**



**Town Of Brimfield**  
Municipal Facilities Study and Planning  
Brimfield, Massachusetts

**PROPOSED POLICE STATION FLOOR PLAN**

Scale: 1/8"=1'-0"  
Drawn by: AJ/KCB  
Job No. 13002.00  
Date: 7-9-13

**PR-POL**



MUNICIPAL FACILITIES STUDY AND PLANNING  
Town of Brimfield, Massachusetts

## Public Safety Headquarters

### Structural

#### Structural Description:

The Public Safety Headquarters is a one-story, steel framed structure, located at 34A Wales Road in Brimfield. The construction date of the building is unknown; however, it appears to be 1970's vintage. The facility is "T" shaped in plan, approximately 150 feet long (east-west) and 70 feet/40 feet wide (front and back sections, respectively). A single Fire Truck bay was added to the north side of the front section sometime after the original construction, increasing the number of Fire Truck bays from three (3) to four (4) in this section.



Offices, a Break Room, Storage spaces and Bathrooms are located behind the front, Fire Truck bays. There are four (4) additional vehicular bays at the western end of the facility, including two Ambulance bays. Roof construction is flat (pitched to drain); the roof of the front section (Fire Truck bays) is several feet higher than that of the western section.

Typical foundation construction is assumed to be conventional spread footings, with a concrete slab on grade First (Ground) Floor. Roof construction over the (higher) front section consists of 1½" deep, narrow rib steel roof deck spanning to 12" deep, open web steel joists. The joists are spaced at 6+/- feet on centers and span approximately 17 feet in the north-south direction to steel beams. Steel beams (W16+W10 composite sections) clear span the bay in the east-west direction, approximately 38 feet. Roof construction over the added bay in this section consists of 1½" deep, wide rib, galvanized steel roof deck spanning to W12 steel beams. The steel beams are spaced at 6+/- feet on centers and span approximately 18 feet in the north-south direction to masonry bearing walls at each end. The roof of the western (Office and Ambulance bay) section is also steel framed, consisting of 1½" deep, narrow rib steel roof deck spanning to 12" deep, open web steel joists. The joists are spaced at 6+/- feet on centers and span approximately 16 feet in the east-west direction to steel beams. Steel beams (W12's, spanning 20+/- feet) are continuous over an interior W6 column and are supported at the north and south ends by masonry exterior wall construction. Exterior walls are typically solid brick and block construction; 12" thick (8" CMU plus 4" brick veneer). Lateral stability (wind and seismic loads) is provided by interior and perimeter masonry walls (presumably unreinforced) in each direction.

No original construction drawings or previous structural reports were available.




### **Structural Conditions/Issues – Comments and Recommendations:**

Structural conditions at the Public Safety Headquarters were observed during a brief tour of the facility on May 13, 2013. A significant portion of the roof and wall construction was exposed to view, except in the Office area. Ceiling tiles in the Office area were removed, to allow an examination of the roof structure above. Generally speaking, roof construction appears to be performing satisfactorily; there is no evidence of structural distress that would indicate significantly overstressed, deteriorated or failed structural members. Foundations appear to be performing adequately; there are no signs of significant, total or differential settlements. The concrete slab on grade appears to be in satisfactory condition; however, exterior approach slabs at vehicular bays have suffered damage from freeze/thaw action and/or de-icing salts.

Structural/structurally related conditions observed during site visit are noted below:

- The condition of the exterior brick veneer is generally satisfactory; however some cracking was observed and repair/repainting is required in certain locations.
- The capacity of the roof framing was not determined (steel joists are a proprietary design) ; however, roof framing appears to be functioning as originally intended. One area of potential concern is at the junction of the high and low roofs; it does not appear that snow drift loading was accounted for in the original design.
- Steel roof framing is unprotected and has no fire resistance rating. There are no sprinklers. Fire rating requirements should be reviewed in conjunction with future renovations to the facility.



### **Building Code Requirements and Additional Comments:**

Proposed renovations, alterations, repairs and additions to the Brimfield Public Safety Headquarters would be governed by the provisions of the Massachusetts State Building Code (MSBC – 780 CMR 8<sup>th</sup> Edition) and the Massachusetts Existing Building Code (MEBC). These documents are based on amended versions of the 2009 International Building Code (IBC) and the 2009 International Existing Building Code (IEBC), respectively.

The MEBC allows the Design Team to choose one of three (3) compliance methods. Structurally, the Prescriptive Compliance Method is preferred. Regardless of the compliance method chosen, the MEBC may require that the (presumably unreinforced) masonry walls of the building be evaluated with respect to the provisions of Appendix A1 of the IEBC (depending on the extent of the renovation/alteration work and/or proposed change(s) in use). In addition, Section 101.5.4.0 of the Massachusetts Amendments (Chapter 34) requires that the existing

building be investigated in sufficient detail to ascertain the effects of the proposed work (or change in use) on the area under consideration, and the entire building or structure and its foundations, if impacted by the proposed work or change in use.

#### Additions – General Comments:

The design and construction of proposed additions would be conducted in accordance with the Code for new construction. Significant additions should be structurally separated from the existing building by an expansion (seismic) joint to avoid an increase in gravity loads and/or lateral loads to existing structural elements. Smaller additions can be structurally attached to the existing building, provided they do not increase the demand - capacity ratio of the existing lateral force resisting elements in the building by more than 10%. Presently, no additions to this building are proposed.

#### Renovations/Alterations – General Comments:

Where proposed alterations to existing structural elements carrying gravity loads results in a stress increase of over 5%, the affected element will need to be reinforced or replaced to comply with the Code for new construction. Proposed alterations to existing structural elements carrying lateral load (masonry walls in this case) which result in an increase in the demand - capacity ratio of over 10% should be avoided, if possible. Essentially, this means that removal of, or major alterations to the existing, (presumably unreinforced) masonry walls in the building should be minimized. If this is not avoidable, more significant seismic upgrades or reinforcing will be required; potentially including the addition of lateral force resisting elements (braces, shear walls, etc.).

#### Proposed Alterations and Renovations - Anticipated Scope of Structural Work:

Proposed alterations to the building include raising the height of the roof over the westernmost, two (2) vehicular bays in the building and creating two, higher drive-through Fire Truck bays with roll up doors at the north and south ends. The anticipated scope of structural work would include the following:

- Construct a temporary, wood framed wall at the eastern edge of the work area to protect the remaining portion of the building from weather and construction activities.
- Demolish and remove the existing roof structure in the subject bays, taking necessary precautions not to damage the existing, remaining structure to the east. An option may include salvaging the existing, open web steel roof joists to be used in the construction of the new (higher) roof.
- Provide temporary bracing to keep the structure safe and aligned at all times.

- Demolish and remove the existing masonry walls in the subject bays; including the north, south west and interior (north-south) walls. The existing masonry walls are presumably unreinforced and do not meet current building code requirements. Accordingly, the vertical extension of these walls to support the new, higher roof construction would not be permissible by code.
- Construct new, reinforced masonry bearing walls (8" CMU with a 4" brick veneer) to support the higher roof. The new walls will rest on the existing foundation (with drilled-in dowels) and be reinforced/grouted. Openings for overhead doors will be provided on the north and south sides. On the east side of the new, higher roof, provide a steel column extension above the existing, interior column. The vertical wall defining the step in the roof elevation should be lightweight construction; steel studs and panels.
- Construct a new, steel framed roof at the higher level, with 1½" deep, 20 gauge, Type WR galvanized steel roof deck, open web steel joists (new or salvaged), supported on new, reinforced masonry bearing walls (or new steel beams in the alternate approach). The estimated total weight of structural steel (steel beams, columns and joists) is approximately *9.0 psf*.

**End of Structural Report**

TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**Police & Fire Building**

34 Wales Street

MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS

Prepared By:

Consulting Engineering Services  
510 Chapman Street, Suite 201  
Canton, MA 02021

June 26, 2013

**GENERAL**

The mechanical, electrical, plumbing, and fire protection systems were reviewed in conformance with the requirements of the following State and National codes and regulations, as applicable:

- Massachusetts State Building Code 8th Edition
- Massachusetts State Fire Prevention Regulations
- NFPA Latest Editions
- Massachusetts Plumbing Code
- Massachusetts Mechanical Code
- Massachusetts Electrical code (NEC 2011 Edition)
- Illuminating Engineering Society of North America (IESNA) Lighting Handbook
- ASHRAE 90.1 Latest Edition

The scope of this study does not include operational assessment of the fixtures and equipment reviewed; it includes only a brief visual review of the fixtures and equipment. Therefore notes regarding the condition of the fixtures and equipment may or may not be indicative of the actual condition of the systems and equipment and/or the expected life of the fixtures and equipment. Therefore it is recommended that services of a qualified technician be retained to evaluate the actual condition of fixtures and equipment prior to replacement.

## MECHANICAL

### HEATING

An oil fired, gravity vent, hot air furnace hung horizontally near the ceiling within the main fire truck garage serves this area. Supply air distribution is routed to registers generally located to blow towards each overhead door. This unit is controlled from a local dial type thermostat in the garage. This unit has no direct ducted outdoor air and is vented directly through the roof above the unit. The unit was recently replaced and is in excellent condition.

Another oil fired, gravity vent, hot air furnace hung horizontally above the accessible ceiling in the station common room serves this area and adjacent offices, including the police offices. There is a dial type thermostat controlling this unit in the common area. This unit has no direct ducted outdoor air and is vented directly through the roof above the unit. The unit is in fair condition. Both furnaces are fueled from a pair of 330 gallon oil tanks mounted exterior to the rear of the building under an awning.

The garage area on the opposite end of the building from the fire truck garage includes (3) horizontal style electric unit heaters hung from the ceiling near each of the overhead doors blowing into the garage. Each is controlled by a unit mounted dial thermostat.

The EMT's office adjacent to the fire truck garage includes a length of electric baseboard heat with an integral dial thermostat.

### AIR CONDITIONING

There are two separate ductless split systems in the building. A 2-ton wall mounted unit serves the common room between the offices with the outdoor unit on grade just outside the rear door. A 1.5-ton wall mounted unit serves the police office with this outdoor unit mounted on a wall stand projecting from the front of the building. Both units have remote controller operating devices and are in good condition.

### VENTILATION

There is a ceiling cabinet exhaust fan in the bathroom adjacent to the common space.

The fire truck garage includes (3) ceiling paddle fans for general air circulation that are locally switched on or off.

There is no form of fume or general exhaust in either of the garages.

### RECOMMENDATIONS

Update heating equipment from oil to gas to save energy due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

Update to programmable type thermostats for control of the furnaces and/or the electric unit heaters.

Replace the common area furnace with two units and reconfigure the ductwork to provide better zoning and control. Separate the distribution to the police offices from that of the common area and provide dedicated thermostats for each unit.

Provide an exhaust fan in the bathroom adjacent to the EMT office.

Provide direct ducted outdoor air for the furnace serving the fire truck garage with a roof cap intake and damper assembly linked to the furnace operation. Also add a general exhaust fan in this garage to operate during occupied periods in conjunction with the furnace.

Replace the other garage's electric unit heaters with a warm air furnace and supply air distribution similar to the fire truck garage and provide a direct ducted outdoor air/intake and damper assembly as noted above. Also include a general exhaust fan in this garage to operate in conjunction with the new furnace.

## **ELECTRICAL**

### EXISTING SYSTEMS

The building is served by a single 200 amp electric service and panelboard located in the rear of the apparatus bay. The service equipment is in good condition. There is also a 150amp electrical panel labeled "Emergency" that is fed by the manual transfer switch and generator.

The building also has a 100amp manual transfer switch to which a generator is attached in the event of a power outage. An existing 15kW, 240/120volt diesel fired generator is located in a small addition at the rear of the building. This equipment is in good condition.

The lighting consists of 8' industrial fluorescent fixtures with T8 lamps in the vehicle bays and 2x4 recessed acrylic lensed fixtures in office and other areas. The lighting in the maintenance bays and other areas is adequate.

The exit signs are fluorescent type without batteries. These fixtures are in fair condition.

The exterior lighting consists of wall mounted high pressure sodium fixtures controlled by a time clock. These fixtures are in fair condition.

## RECOMMENDATIONS

The manual transfer switch should be replaced with an automatic transfer switch and controls.

New LED exit signs with integral batteries should be provided to replace the existing.

The exterior lighting should be replaced with a high-efficiency LED type fixture to improve the lighting levels and reduce energy costs.

A fire alarm system should also be added to the facility.

## PLUMBING

Water is provided by a well pump which serves both the Police and Fire Building and the DPW Building. The expansion tank for the pump and the controls for the pump are in the Police and Fire Building, and they appear to be in fair condition. The pump is in the well, and therefore its condition is not included in this review.

There is a stainless steel kitchen sink in the meeting/open area, but it does not have a faucet. It appears to be in good condition. Per the staff, the water from the well is not potable, therefore the absence of a faucet.

As the water is not potable, the well water should be tested to check whether or not, with the right filtration/treatment, it would be acceptable for drinking. If so, the appropriate filtration/treatment systems should be provided. Where the filtration/treatment system would create an unacceptable pressure drop on the system, the well pump should be replaced with a larger well pump.

There are no floor drains in any of the apparatus bays.

There is an air compressor in apparatus bay area towards the West. It appears to be in good condition. There is no permanent compressed air piping system in the building; hoses only are connected to the compressor.

A tank type electric water heater in the Police and Fire Building provides hot water for the lavatories. There is no mixing valve provided with the water heater. The water heater appears to be in poor to fair condition, but it also appears to be relatively old, and electric water heaters tend to have relatively short lives, therefore the water heater should be replaced in the near future.

There is an accessible restroom, and both the lavatory and the water closet appear to be in good condition. The water closet is a floor mount vitreous china tank type fixture, and the lavatory is a wall mount vitreous china fixture. The water closet is not a low flow fixture.

There also is a non-accessible restroom, and both the lavatory and the water closet appear to be in fair condition. The water closet is a floor mount vitreous china tank type fixture, and the lavatory is a wall mount vitreous china fixture. The water closet is not a low flow fixture.

## **FIRE PROTECTION**

The building does not have a sprinkler system.







Description	Note	Quantity	Unit	Price	Total
Basic Quantities		GFA		Girth	
level 1		7,416 sf		457 lf	
<b>General</b>					
3 Door Hardware					\$
replace knob set with levers		14	ea	1,003.76	14,053
remove exterior door hardware		1	ea	68.97	69
disposal		1	ea	145.20	145
exterior door hardware		1	ea	1,563.23	1,563
Sub Total - Direct Cost					15,830
General Conditions		20.00%			3,166
Overhead & Profit		23.00%			4,369
Design & Price Reserve		15.00%			3,505
Escalation	Aug-15	8.16%			2,193
Bond		3.00%			872
Soft Costs/Design Fees		30.00%			8,981
Total Project Cost					<u>\$38,916</u>
4 Toilet Rooms					\$
minor modifications to door clearance		1	ea	2,890.00	2,890
Sub Total - Direct Cost					2,890
General Conditions		20.00%			578
Overhead & Profit		23.00%			798
Design & Price Reserve		15.00%			640
Escalation	Aug-15	8.16%			400
Bond		3.00%			159
Soft Costs/Design Fees		30.00%			1,640
Total Project Cost					<u>\$7,105</u>
3 Doors From Fire Equipment					\$
reconfigure doors and partitions to provide correct clearance		4	loc	2,890.00	11,560
Sub Total - Direct Cost					11,560
General Conditions		20.00%			2,312
Overhead & Profit		23.00%			3,191
Design & Price Reserve		15.00%			2,559
Escalation	Aug-15	8.16%			1,601
Bond		3.00%		288.95	637
Soft Costs/Design Fees		30.00%			6,558
Total Project Cost					<u>\$28,418</u>



Description	Note	Quantity	Unit	Price	Total
<b>3 Kitchen Cabinets</b>					<b>\$</b>
remove kitchen base cabinet		12	lf	9.24	111
disposal		1	ea	78.30	78
new kitchen base cabinet ADA compliant		12	lf	208.80	2,506
Sub Total - Direct Cost					2,695
General Conditions		20.00%			539
Overhead & Profit		23.00%			744
Design & Price Reserve		15.00%			597
Escalation	Aug-15	8.16%			373
Bond		3.00%			148
Soft Costs/Design Fees		30.00%			1,529
Total Project Cost					<u><u>\$6,625</u></u>
<b>4 Ceilings</b>					<b>\$</b>
demo suspended ceilings (act) and lighting		7,416	sf	1.45	10,753
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new act ceilings		7,416	sf	3.76	27,884
new lighting		7,416	sf	12.34	91,513
Sub Total - Direct Cost					132,687
General Conditions		20.00%			26,537
Overhead & Profit		23.00%			36,622
Design & Price Reserve		15.00%			29,377
Escalation	Aug-15	8.16%			18,378
Bond		2.40%			5,846
Soft Costs/Design Fees		30.00%			74,834
Total Project Cost					<u><u>\$324,281</u></u>
<b>4 Replace Windows</b>					<b>\$</b>
demo windows		108	sf	1.83	198
disposal		1	ea	59.40	59
new aluminum windows		108	sf	52.03	5,619
sealant		72	lf	6.18	445
Sub Total - Direct Cost					6,321
General Conditions		20.00%			1,264
Overhead & Profit		23.00%			1,745
Design & Price Reserve		15.00%			1,400
Escalation	Aug-15	8.16%			876
Bond		3.00%			348
Soft Costs/Design Fees		30.00%			3,586
Total Project Cost					<u><u>\$15,540</u></u>



Description	Note	Quantity	Unit	Price	Total
<b>2 Vehicle Exhaust Removal System</b>					<b>\$</b>
vehicle exhaust system for 8 bays		4,399	sf	5.28	23,227
Sub Total - Direct Cost					23,227
General Conditions		20.00%			4,645
Overhead & Profit		23.00%			6,411
Design & Price Reserve		15.00%			5,142
Escalation	Aug-15	8.16%			3,217
Bond		3.00%			1,279
Soft Costs/Design Fees		30.00%			13,176
<b>Total Project Cost</b>					<b>\$57,097</b>
<b>3 Replace Damaged Door</b>					<b>\$</b>
remove existing door and frame		1	leaf	47.96	48
disposal		1	ea	48.40	48
new h.m. door, frame and hardware		1	leaf	1,541.08	1,541
paint door		1	leaf	101.43	101
Sub Total - Direct Cost					1,738
General Conditions		20.00%			348
Overhead & Profit		23.00%			480
Design & Price Reserve		15.00%			385
Escalation	Aug-15	8.16%			241
Bond		3.00%			96
Soft Costs/Design Fees		30.00%			986
<b>Total Project Cost</b>					<b>\$4,274</b>
<b>4 New Trench Drain</b>					<b>\$</b>
saw cut concrete	allowance	262	lf	1.94	508
remove concrete slab	allowance	131	sf	9.68	1,268
disposal		1	ea	290.40	290
excavation inside existing building	allowance	10	cy	108.42	1,084
disposal off site	allowance	10	cy	24.72	247
trench drain - piping and cover	allowance	131	lf	112.65	14,757
connect to drainage system	allowance	1	ea	513.50	514
Sub Total - Direct Cost					18,668
General Conditions		20.00%			3,734
Overhead & Profit		23.00%			5,152
Design & Price Reserve		15.00%			4,133
Escalation	Aug-15	8.16%			2,586
Bond		3.00%			1,028
Soft Costs/Design Fees		30.00%			10,590
<b>Total Project Cost</b>					<b>\$45,891</b>



Description	Note	Quantity	Unit	Price	Total
<b>Accessible Entrance Door</b>					<b>\$</b>
add push button operator to door		4	ea	3,341.00	13,364
wire and conduit		300	lf	7.11	2,133
cut and patch		1	ls	257.79	258
<b>Sub Total - Direct Cost</b>					<b>15,755</b>
General Conditions		20.00%			3,151
Overhead & Profit		23.00%			4,348
Design & Price Reserve		15.00%			3,488
Escalation	Aug-15	8.16%			2,182
Bond		3.00%			868
Soft Costs/Design Fees		30.00%			8,938
<b>Total Project Cost</b>					<b>38,730</b>
<b>3 Gutters</b>					<b>\$</b>
clean gutters	laborer	1	day	481.85	482
disposal		1	ea	121.00	121
reattach gutters with slope		457	lf	3.93	1,796
seal all joints and end caps	allowance	16	ea	28.08	449
<b>Sub Total - Direct Cost</b>					<b>2,848</b>
General Conditions		20.00%			570
Overhead & Profit		23.00%			786
Design & Price Reserve		15.00%			631
Escalation	Aug-15	8.16%			395
Bond		3.00%			157
Soft Costs/Design Fees		30.00%			1,616
<b>Total Project Cost</b>					<b>\$7,003</b>
<b>3 Pipe Away Downspouts</b>					<b>\$</b>
pipe away water at downspouts	allowance	16	loc	287.49	4,600
clean all water stains at walls	allowance	16	loc	91.96	1,471
fill and compact low spots around building	allowance	16	loc	69.86	1,118
<b>Sub Total - Direct Cost</b>					<b>7,189</b>
General Conditions		20.00%			1,438
Overhead & Profit		23.00%			1,984
Design & Price Reserve		15.00%			1,592
Escalation	Aug-15	8.16%			996
Bond		3.00%			396
Soft Costs/Design Fees		30.00%			4,079
<b>Total Project Cost</b>					<b>\$17,674</b>
<b>3 Expansion Joint</b>					<b>\$</b>
sawcut joint		40	lf	28.27	1,131
expansion joint in wall		40	lf	23.11	924
<b>Sub Total - Direct Cost</b>					<b>2,055</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			411
Overhead & Profit		23.00%			567
Design & Price Reserve		15.00%			455
Escalation	Aug-15	8.16%			285
Bond		3.00%			113
Soft Costs/Design Fees		30.00%			1,166
<b>Total Project Cost</b>					<b>\$5,052</b>
<b>3 Re-Pointing</b>					
minor re-pointing of cmu and brick around entire building 5% allowance		457	sf	31.67	14,473
<b>Sub Total - Direct Cost</b>					<b>14,473</b>
General Conditions		20.00%			2,895
Overhead & Profit		23.00%			3,995
Design & Price Reserve		15.00%			3,204
Escalation	Aug-15	8.16%			2,005
Bond		3.00%			797
Soft Costs/Design Fees		30.00%			8,211
<b>Total Project Cost</b>					<b>\$35,580</b>
<b>3 Replace Aprons</b>					
demo concrete aprons at overhead doors		399	sf	1.58	630
sawcut pavement		133	lf	4.67	621
demo asphalt pavement		133	sf	0.43	57
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
8" concrete apron		532	sf	7.96	4,235
<b>Sub Total - Direct Cost</b>					<b>8,080</b>
General Conditions		20.00%			1,616
Overhead & Profit		23.00%			2,230
Design & Price Reserve		15.00%			1,789
Escalation	Aug-15	8.16%			1,119
Bond		3.00%			445
Soft Costs/Design Fees		30.00%			4,584
<b>Total Project Cost</b>					<b>\$19,863</b>
<b>3 Miscellaneous Wood Rot/Damage</b>					
demo T 1-11 siding		3,948	sf	2.42	9,554
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new fiber cement siding		3,948	sf	4.48	17,687
paint siding		3,948	sf	2.14	8,449
patch, prime, repaint trim		795	lf	4.59	3,649
<b>Sub Total - Direct Cost</b>					<b>41,876</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			8,375
Overhead & Profit		23.00%			11,558
Design & Price Reserve		15.00%			9,271
Escalation	Aug-15	8.16%			5,800
Bond		3.00%			2,306
Soft Costs/Design Fees		30.00%			23,756
<b>Total Project Cost</b>					<b>\$102,942</b>
<b>3 Overhead Door Jambs</b>					<b>\$</b>
demo damaged sections of trim		144	sf	1.71	246
replace trim with fiber cement siding		144	sf	7.54	1,086
paint trim		144	sf	2.86	412
<b>Sub Total - Direct Cost</b>					<b>1,744</b>
General Conditions		20.00%			349
Overhead & Profit		23.00%			481
Design & Price Reserve		15.00%			386
Escalation	Aug-15	8.16%			242
Bond		3.00%			96
Soft Costs/Design Fees		30.00%			989
<b>Total Project Cost</b>					<b>\$4,287</b>
<b>3 Paint West Wall Of Equipment Bays</b>					<b>\$</b>
prep and paint wall		1,000	sf	2.01	2,010
<b>Sub Total - Direct Cost</b>					<b>2,010</b>
General Conditions		20.00%			402
Overhead & Profit		23.00%			555
Design & Price Reserve		15.00%			445
Escalation	Aug-15	8.16%			278
Bond		3.00%			111
Soft Costs/Design Fees		30.00%			1,140
<b>Total Project Cost</b>					<b>\$4,941</b>
<b>2 Bricks At Corner Of East Wall</b>					<b>\$</b>
replace damaged bricks	allowance	80	sf	40.91	3,273
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
sawcut joint between brick and CMU		20	lf	28.27	565
filler, backer rod and sealant		20	lf	6.18	124
<b>Sub Total - Direct Cost</b>					<b>6,499</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			1,300
Overhead & Profit		23.00%			1,794
Design & Price Reserve		15.00%			1,439
Escalation	Aug-15	8.16%			900
Bond		3.00%			358
Soft Costs/Design Fees		30.00%			3,687
<b>Total Project Cost</b>					<b>\$15,977</b>
<b>3 Floor At Overhead Doors</b>					<b>\$</b>
sawcut concrete slab		50	lf	4.61	231
demo slab		200	sf	1.56	312
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
drill and dowel into existing floor	12" o.c.	50	ea	69.21	3,461
patch concrete slab		200	sf	24.20	4,840
<b>Sub Total - Direct Cost</b>					<b>11,381</b>
General Conditions		20.00%			2,276
Overhead & Profit		23.00%			3,141
Design & Price Reserve		15.00%			2,520
Escalation	Aug-15	8.16%			1,576
Bond		3.00%			627
Soft Costs/Design Fees		30.00%			6,456
<b>Total Project Cost</b>					<b>\$27,977</b>
<b>3 Hose Dryer</b>					<b>\$</b>
demo hose dryer	allowance	1	ea	1,210.00	1,210
disposal		1	ea	181.50	182
new hose dryer	allowance	1	ea	25,675.00	25,675
<b>Sub Total - Direct Cost</b>					<b>27,067</b>
General Conditions		20.00%			5,413
Overhead & Profit		23.00%			7,470
Design & Price Reserve		15.00%			5,993
Escalation	Aug-15	8.16%			3,749
Bond		3.00%			1,491
Soft Costs/Design Fees		30.00%			15,355
<b>Total Project Cost</b>					<b>\$66,538</b>

**Mechanical**





Description	Note	Quantity	Unit	Price	Total
<b>4 Replace Oil Fired Equipment</b>					
remove oil fired equipment		1	ea	753.06	753
disposal		1	ea	242.00	242
new gas service - trench only - service by gas company		200	lf	26.18	5,236
misc. exterior repairs from trench		1	ea	1,936.00	1,936
cast iron gas boiler	300mbh	1	ea	8,606.06	8,606
hot water pumps	40gpm	2	ea	2,629.12	5,258
gas piping allowance	1 1/4"	100	lf	16.95	1,695
Sub Total - Direct Cost					23,726
General Conditions		20.00%			4,745
Overhead & Profit		23.00%			6,548
Design & Price Reserve		15.00%			5,253
Escalation	Aug-15	8.16%			3,286
Bond		3.00%			1,307
Soft Costs/Design Fees		30.00%			13,460
<b>Total Project Cost</b>					<b>58,325</b>
<b>3 Replace Existing Thermostats</b>					
demo existing thermostats	allowance	15	ea	72.60	1,089
disposal		1	ea	48.40	48
new thermostats	allowance	15	ea	256.75	3,851
Sub Total - Direct Cost					4,988
General Conditions		20.00%			998
Overhead & Profit		23.00%			1,377
Design & Price Reserve		15.00%			1,104
Escalation	Aug-15	8.16%			691
Bond		3.00%			275
Soft Costs/Design Fees		30.00%			2,830
<b>Total Project Cost</b>					<b>12,263</b>
<b>3 Common Area Furnace</b>					
replace furnace, pumps, air handler, and condensing units		-	sf	20.88	-
disposal		1	ea	-	-
electrician		1	day	581.27	581
reconfigure ductwork	allowance	7,416	sf	1.03	7,638
separate distribution to police and provide dedicated thermostats		1,975	sf	10.78	21,291
Sub Total - Direct Cost					29,510
General Conditions		20.00%			5,902
Overhead & Profit		23.00%			8,145
Design & Price Reserve		15.00%			6,534
Escalation	Aug-15	8.16%			4,087
Bond		3.00%			1,625
Soft Costs/Design Fees		30.00%			16,741
<b>Total Project Cost</b>					<b>\$72,544</b>



Description	Note	Quantity	Unit	Price	Total
<b>3 Exhaust Fan In Bathroom</b>					<b>\$</b>
provide exhaust fan in bathroom		1	ea	1,540.50	1,541
cut and patch		1	ea	91.88	92
electrician		1	day	581.27	581
Sub Total - Direct Cost					2,214
General Conditions		20.00%			443
Overhead & Profit		23.00%			611
Design & Price Reserve		15.00%			490
Escalation	Aug-15	8.16%			307
Bond		3.00%			122
Soft Costs/Design Fees		30.00%			1,256
<b>Total Project Cost</b>					<b>\$5,443</b>
<b>3 Direct Ducted Outdoor Air</b>					<b>\$</b>
provide direct ducted outdoor air for furnace w/ roof cap and damper a:		1	ea	3,594.50	3,595
provide general exhaust fan in garage		1	ea	1,540.50	1,541
electrician		1	day	581.27	581
Sub Total - Direct Cost					5,717
General Conditions		20.00%			1,143
Overhead & Profit		23.00%			1,578
Design & Price Reserve		15.00%			1,266
Escalation	Aug-15	8.16%			792
Bond		3.00%			315
Soft Costs/Design Fees		30.00%			3,243
<b>Total Project Cost</b>					<b>\$14,054</b>
<b>3 Other Garage's Electric Unit Heaters Replacement</b>					<b>\$</b>
demo electric unit heaters	allowance	4	ea	2,334.10	9,336
provide warm air furnace and supply air		2,020	sf	23.11	46,682
provide direct ducted outdoor air for furnace w/ roof cap and damper a:		1	ea	3,594.50	3,595
provide general exhaust fan in garage		1	ea	2,567.50	2,568
Sub Total - Direct Cost					62,181
General Conditions		20.00%			12,436
Overhead & Profit		23.00%			17,162
Design & Price Reserve		15.00%			13,767
Escalation	Aug-15	8.16%			8,613
Bond		2.40%			2,740
Soft Costs/Design Fees		30.00%			35,070
<b>Total Project Cost</b>					<b>\$151,969</b>



Description	Note	Quantity	Unit	Price	Total
<b>Electrical</b>					
<b>3 Manual Transfer Switch</b>					
					\$
demo manual transfer switch		1	ea	282.75	283
disposal		1	ea	84.83	85
automatic transfer switch and controls	60 amp	1	ea	4,128.15	4,128
Sub Total - Direct Cost					4,496
General Conditions		20.00%			899
Overhead & Profit		23.00%			1,241
Design & Price Reserve		15.00%			995
Escalation	Aug-15	8.16%			623
Bond		3.00%			248
Soft Costs/Design Fees		30.00%			2,551
Total Project Cost					\$11,053
<b>3 LED Exit Signs</b>					
					\$
demo existing exit signs		10	ea	62.48	625
disposal		1	ea	96.80	97
exit signs throughout		7,416	sf	0.49	3,634
Sub Total - Direct Cost					4,356
General Conditions		20.00%			871
Overhead & Profit		23.00%			1,202
Design & Price Reserve		15.00%			964
Escalation	Aug-15	8.16%			603
Bond		3.00%			240
Soft Costs/Design Fees		30.00%			2,471
Total Project Cost					\$10,707
<b>3 Upgrade Exterior Lighting</b>					
					\$
demo exterior lighting fixture	allowance	10	ea	72.60	726
disposal		1	ea	145.20	145
upgrade existing exterior lighting to LED	allowance	10	ea	771.00	7,710
Sub Total - Direct Cost					8,581
General Conditions		20.00%			1,716
Overhead & Profit		23.00%			2,368
Design & Price Reserve		15.00%			1,900
Escalation	Aug-15	8.16%			1,189
Bond		3.00%			473
Soft Costs/Design Fees		30.00%			4,868
Total Project Cost					\$21,095



Description	Note	Quantity	Unit	Price	Total
<b>2 Fire Alarm System</b>					<b>\$</b>
add fire alarm system to facility		7,416	sf	2.47	18,318
Sub Total - Direct Cost					18,318
General Conditions		20.00%			3,664
Overhead & Profit		23.00%			5,056
Design & Price Reserve		15.00%			4,056
Escalation	Aug-15	8.16%			2,537
Bond		3.00%			1,009
Soft Costs/Design Fees		30.00%			10,392
<b>Total Project Cost</b>					<b>\$45,032</b>
<b>Plumbing</b>					
<b>Replace Well Pump And Add Filtration</b>					
demo well pump		1	ea	208.12	208
demo expansion tank		1	ea	174.24	174
disposal		1	ea	55.47	55
new well pump		1	ea	4,416.10	4,416
new expansion tank		1	ea	3,697.20	3,697
source water filtration system	reverse osmosis	1	ea	20,540.00	20,540
Sub Total - Direct Cost					29,090
General Conditions		20.00%			5,818
Overhead & Profit		23.00%			8,029
Design & Price Reserve		15.00%			6,441
Escalation	Aug-15	8.16%			4,029
Bond		3.00%			1,602
Soft Costs/Design Fees		30.00%			16,503
<b>Total Project Cost</b>					<b>71,512</b>
<b>Sink Faucet</b>					
sink faucet at existing sink		1	ea	266.20	266
Sub Total - Direct Cost					266
General Conditions		20.00%			53
Overhead & Profit		23.00%			73
Design & Price Reserve		15.00%			59
Escalation	Aug-15	8.16%			37
Bond		3.00%			15
Soft Costs/Design Fees		30.00%			151
<b>Total Project Cost</b>					<b>654</b>



Description	Note	Quantity	Unit	Price	Total
<b>Replace Electric Water Heater</b>					
remove electric water heater		1	ea	62.48	62
disposal		1	ea	48.40	48
new electric water heater		1	ea	2,233.73	2,234
install mixing valve		1	ea	3,748.55	3,749
<b>Sub Total - Direct Cost</b>					<b>6,093</b>
General Conditions		20.00%			1,219
Overhead & Profit		23.00%			1,682
Design & Price Reserve		15.00%			1,349
Escalation	Aug-15	8.16%			844
Bond		3.00%			336
Soft Costs/Design Fees		30.00%			3,457
<b>Total Project Cost</b>					<b>14,980</b>
<b>Public Safety Renovation/Addition/Roof Raising</b>					
Public Safety renovation/addition/roof raising		8,084	ea	211.97	1,713,542
<b>Sub Total - Direct Cost</b>					<b>1,713,542</b>
General Conditions		12.00%			205,625
Overhead & Profit		14.00%			268,683
Design & Price Reserve		15.00%			328,178
Escalation	Aug-15	8.16%			205,308
Bond		1.60%			43,541
Soft Costs/Design Fees		30.00%			829,463
<b>Total Project Cost</b>					<b>3,594,340</b>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW POLICE STATION  
 BRIMFIELD, MA 01010

GFA 4,088



Description	Note	Quantity	Unit	Price	Total
<b>General</b>					
New Police Station					\$
New Police Station (see cost plan)		4,088	sf	372.80	1,524,006
Sub Total - Direct Cost					1,524,006
General Conditions		12.00%			182,881
Overhead & Profit		14.00%			238,964
Design & Price Reserve		15.00%			291,878
Escalation	Aug-15	8.16%			182,599
Bond		1.60%			38,725
Soft Costs/Design Fees		30.00%			737,716
Total Project Cost					3,196,769





COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 PUBLIC SAFETY RENOVATION AND ADDITION  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Public Safety Renovation And Addition		GFA(SF):		8,084		Date: Jul-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	Floor Area	%	Element Quantities	Unit	Element Unit Rate	
<b>A SUBSTRUCTURE</b>										
A10	Foundations	16,286	17,194	2.01	2.13	1.0%	668 SF	SF	24.38	
A20	Basement Construction	908		0.11			668 SF	SF	1.36	
<b>B SHELL</b>			219,416		27.14	12.8%				
B10	Superstructure	24,322		3.01			2,043 SF	SF	11.91	
B20	Exterior Closure	155,766		19.27			2,268 SF	SF	68.68	
B30	Roofing	39,328		4.86			2,043 SF	SF	19.25	
<b>C INTERIORS</b>			346,362		42.85	20.2%				
C10	Interior Construction	199,028		24.62			8,084 SF	SF	24.62	
C20	Stairs	0		0.00			0 FLT	FLT	0.00	
C30	Interior Finishes	147,334		18.23			8,084 SF	SF	18.23	
<b>D SERVICES</b>			540,433		66.85	31.5%				
D10	Conveying Systems	0		0.00			0 STOP	STOP	0.00	
D20	Plumbing	70,068		8.67			8,084 SF	SF	8.67	
D30	HVAC	252,021		31.18			8,084 SF	SF	31.18	
D40	Fire Protection	36,378		4.50			8,084 SF	SF	4.50	
D50	Electrical Systems	181,966		22.51			8,084 SF	SF	22.51	
<b>E EQUIPMENT &amp; FURNISHINGS</b>			89,524		11.07	5.2%				
E10	Equipment	47,805		5.91			8,084 SF	SF	5.91	
E20	Furnishings	41,719		5.16			8,084 SF	SF	5.16	





COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 PUBLIC SAFETY RENOVATION AND ADDITION  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: Public Safety Renovation And Addition		Date: Jul-13		Sheet No: 2 OF 2				
Uniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF	Floor Area	%	Element Quantities	Unit	Element Unit Rate
<b>F SPECIAL CONSTRUCTION &amp; DEMOLITION</b>		\$ 74,160		9.17	4.3%			
F10 Special Construction	0		0.00			0	SF	0.00
F20 Selective Demolition	74,160		9.17			7,416	SF	10.00
<b>G BUILDING SITEWORK</b>		\$ 426,453		52.75	24.9%			
G10 Site Preparation	40,420		5.00			8,084	SF	5.00
G20 Site Improvements	372,673		46.10			8,084	SF	46.10
G30 Site Civil/Mechanical Utilities	10,020		1.24			668	SF	15.00
G40 Site Electrical Utilities	3,340		0.41			668	SF	5.00
G90 Other Site Construction	0		0.00			0	SF	0.00
<b>SUBTOTAL</b>		\$ 1,713,542		211.97	100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0		0.00				
Z20 CONTINGENCIES	0.0%	0		0.00				
Z30 CM AT RISK PREMIUM	0.0%	0		0.00				
<b>Z90 PROJECT COST ESTIMATE</b>		\$ 1,713,542		211.97				



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW POLICE STATION  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Police Station		GFA(SF):		4,088		Date: Jul-13		Sheet No: 1 OF 2		
Uniformat Element (Levels 2&3)		Amount	Total Cost	Rate \$/SF	Floor Area	%	Element Quantities	Unit	Element Unit Rate	
<b>A SUBSTRUCTURE</b>										
A10	Foundations	99,665	105,225	24.38	25.74	6.9%	4,088 SF	SF	24.38	
A20	Basement Construction	5,560		1.36			4,088 SF	SF	1.36	
<b>B SHELL</b>										
B10	Superstructure	98,357	426,085	24.06	104.23	28.0%	4,088 SF	SF	24.06	
B20	Exterior Closure	249,034		60.92			3,626 SF	SF	68.68	
B30	Roofing	78,694		19.25			4,088 SF	SF	19.25	
<b>C INTERIORS</b>										
C10	Interior Construction	100,647	175,703	24.62	42.98	11.5%	4,088 SF	SF	24.62	
C20	Stairs	0		0.00			0 FLT	FLT	0.00	
C30	Interior Finishes	75,056		18.36			4,088 SF	SF	18.36	
<b>D SERVICES</b>										
D10	Conveying Systems	0	350,546	0.00	85.75	23.0%	0 STOP	STOP	0.00	
D20	Plumbing	39,858		9.75			4,088 SF	SF	9.75	
D30	HVAC	188,048		46.00			4,088 SF	SF	46.00	
D40	Fire Protection	18,396		4.50			4,088 SF	SF	4.50	
D50	Electrical Systems	104,244		25.50			4,088 SF	SF	25.50	
<b>E EQUIPMENT &amp; FURNISHINGS</b>										
E10	Equipment	63,364	94,024	15.50	23.00	6.2%	4,088 SF	SF	15.50	
E20	Furnishings	30,660		7.50			4,088 SF	SF	7.50	



COSTPRO INC.  
 TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 NEW POLICE STATION  
 BRIMFIELD, MA 01010

Project Cost Plan (Uniformat II Level 3) COSTPRO, INC.

Project: New Police Station		Date: Jul-13		Sheet No: 2 OF 2			
Uniformat Element (Levels 2&3)	Amount	Total Cost	Rate \$/SF Floor Area	%	Element Quantities	Unit	Element Unit Rate
<b>F SPECIAL CONSTRUCTION &amp; DEMOLITION</b>	\$	\$					
F10 Special Construction	0	0	0.00	0.0%	0	SF	0.00
F20 Selective Demolition	0	0	0.00		0	SF	0.00
<b>G BUILDING SITEWORK</b>		372,417		24.4%			
G10 Site Preparation	40,880		10.00		4,088	SF	10.00
G20 Site Improvements	188,457		46.10		4,088	SF	46.10
G30 Site Civil/Mechanical Utilities	102,200		25.00		4,088	SF	25.00
G40 Site Electrical Utilities	40,880		10.00		4,088	SF	10.00
G90 Other Site Construction	0		0.00		0	SF	0.00
<b>SUBTOTAL</b>		1,524,000		100.0%			
Z10 GENERAL REQUIREMENTS	0.0%	0					
Z20 CONTINGENCIES	0.0%	0					
Z30 CM AT RISK PREMIUM	0.0%	0					
<b>Z90 PROJECT COST ESTIMATE</b>	\$	1,524,000	\$				372.80

TOWN OF BRIMFIELD  
Massachusetts

PUBLIC SAFETY BUILDING  
Program Areas

	EXISTING SPACE	PROPOSED AREA	DEPT AREAS
<b>FIRE</b>			
Entry	88		
Police Chief	129		
Police Lieutenant	234		
Fire Chief	229	229	
Equipment Bays	4036	4036	
Elec/Comp	84	84	
Duty Officer	51	176	
Radio Room	38		
Kitchen	90	111	
Day Room	538	462	
Toilet's	78		
Storage	38		
Lobby		50	
Bunk Rooms		324	
Men's Toilet		147	
Women's Toilet		123	
Unassigned	247	460	

<b>TOTAL FIRE</b>	<b>5880</b>	<b>6202</b>	
-------------------	-------------	-------------	--

<b>AMBULANCE</b>			
Ambulance Office	145	184	
Ambulance Bays	742	742	
Unassigned			

<b>TOTAL AMBULANCE</b>	<b>887</b>	<b>926</b>	
------------------------	------------	------------	--

<b>TOTAL FIRE &amp; AMBULANCE</b>	<b>6767</b>	<b>7128</b>	
-----------------------------------	-------------	-------------	--

TOWN OF BRIMFIELD  
Massachusetts

POLICE DEPARTMENT  
Proposed Program Areas

	IN TOWN HALL		IN NEW BUILDING
<b>POLICE</b>			
Vestibule/Waiting	93		100
Reception	73		82
Interview Room	64		82
Officer's Report Room	85		103
Duty Officer	101		129
Administrator	61		164
Storage			61
Police Chief	232		213
Lieutenants Office	155		180
Lunch/Meetings/Training Room	331		416
Storage			24
Evidence Storage	187		316
Weight Room	238		173
Men's Locker Room	199		229
Women's Locker Room	88		84
Men's Toilet	154		142
Women's Toilet	111		138
Custodian	14		16
Bulk Evidence Storage			515
Unassigned	193		452
<b>TOTAL POLICE - NET ROOM AREA</b>	<b>2379</b>		<b>3619</b>
Bulk Evidence Storage As Separate Building		500	



# BUILDING USE AUDIT - CONDITION ASSESSMENT

Town of Brimfield, Massachusetts

## Brimfield Public Library

25 Main Street

Year Constructed: 1903  
Construction Type: IIIB  
Fire Sprinklers: No  
Building Area per Floor:  
    Basement: 806 SF  
    First Floor: 2404 SF  
    Total Area: 3210 SF



### General:


The current building is limited in use due to the rear wing being at a lower floor elevation. The original building is cramped while the rear wing is lightly used as a historic museum space.

### The building is not handicapped accessible:

3 Entrance door is located in a thick wall and equipped with a closer. There is insufficient clearance at the side of the door, both interior and exterior. At the exterior of the entrance door, the door is recessed 12 inches and the wall is angled on the required side clearance on the door. Add a push button operator to the door.




3 Original entrance doors have a step on the exterior side and a 1" high threshold on the interior. Exterior risers are not equal heights. Code requires that all public entrances be handicapped accessible. This requirement may have been waived due to the historic nature of the building.




3 Cracks in ceiling in multiple areas. Verify plaster is secure and patch cracks. Repaint ceilings.


3 Although the only building door at grade, the exterior door to the Sherman Memorial Room is not provided with an access sidewalk so that it could be used by persons with disabilities. Provide a sidewalk around building to connect to parking area.\*




2 Handrails are too low on stairs from Memorial Room to Main Library. Replace handrails and provide with extensions.



3 Kitchenette is not accessible. Construct new accessible kitchenette.



3 Toilet room is not ADA Accessible. Insufficient floor area, no grab bars, and non-compliant plumbing fixtures. Door is only 32" wide, hardware non-compliant and inadequate area on pull side of door. Provide both men's and women's accessible restrooms.



3 Cracks and bubbling in vinyl tile near door from addition to existing build and at rear door. Replace damaged tiles.


3 Door from original building to addition is located in a thick wall and does not meet the required push or pull areas on either side of door. Remove door.



3 Sash cords at window in Children's room replacement.



2 Stairs down to basement are narrow, 8" rise at each tread and no hand rails. Center railing is loose and low. Basement is damp and not used for library storage. Leave stair and re-secure railing.



3 Circulation desk is not ADA compliant. Construct new compliant circulation desk.

3 Signage within building is not ADA compliant. Replace signage.




3 Furniture does not provide maneuvering clearance for wheelchairs. Reorganize furniture.



3 Water from downspouts be piped away from the building, to minimize the potential for water infiltration at the Ground Floor level and to reduce hydrostatic pressure on the foundation walls.

2 Wood rot and paint peeling apparent at trim, soffit and fascia boards. Repair or replace rotted items and re-paint.

3 Cracks are present in mortar joints. Re-pointing stone facade around entire existing structure. (Allow 5% of wall area)




3 Asphalt shingles on addition appear to be aged and are in need of replacement.



2 Gutter has fallen off and is damaged on the both the existing structure and the addition. Pieces on ground need to be reinstalled and gutters and down spouts repaired.



2 Stucco at rear of addition is pulling away from lath and cracking and bubbling. Around rear door at corner beads stucco is cracking and falling out of Jambs. Stucco at grade on all 3 sides appears to have water damage from down spouts and gutters needing repairs. Remove damaged areas of stucco and replace incorporating expansion joints to reduce future cracking and delamination.



3 Frame around Bulkhead doors made of painted Plywood that is peeling and appears to have water damage. Replace bulkhead doors with more secure painted metal unit.



2 Slate tile on roof of existing building needs minor repairs.



## Electrical

3 If air conditioning is added to the building, the electrical service should be upgraded at the same time.

2 Review the fire alarm system coverage and upgrade the system to include ADA compliant speaker/strobes.

4 Remove the lighting in the basement and replace with new.

## **Mechanical**

3 The hot air furnace is in poor condition and needs to be replaced.

3 The hot water boiler is in poor condition and needs to be replaced.

3 Provide air conditioning in the Sherman Memorial Room.

3 Ventilation of the building is done using operable windows. There are no mechanical means of ventilation within the building, however, in the original portion of the building there is a grille located at the very peak of the ceiling which might have been used as some form of natural ventilation at one time. Provide mechanical ventilation for the library.

## **Plumbing**

3 Provide localized point-of use electric water heaters to reduce the use of oil for hot water heating.

4 Upgrade the plumbing fixtures to meet ADA requirements and current code requirements for low water consuming fixtures.

## PROGRAM INFORMATION

The current library is severely overcrowded with insufficient and undefined space for any of the functions. Cramped adult areas overlap with cramped children's area. There is no children's program space. Staff areas are grossly inadequate and have no workroom or office space. In contrast the addition to the rear of the original building has space and is used almost exclusively for the historic collection. This area is lightly used as it is separated from the main areas of the library by a doorway and stairs.

This is a lovely historic building and in planning any addition it will be necessary to minimize the impact of the new construction. It is also strongly desirable to have the library on one level for handicapped accessibility and easy of movement of materials. There appears to be sufficient headroom to raise the level of the floor in the existing rear addition to accomplish this.

As the building is contiguous with the Town Hall Annex we believe that the set back requirements between the two buildings can be removed as it is effectively one parcel, thus allowing an expansion in that direction.

Existing parking and access to the building are not handicapped accessible. It is recommended that space be provided in the Annex parking lot an a new walk created around the front of the Annex to the new library entrance. A walk should also be provided to the current parking.


A Library Space Needs chart is provided together with a Test Fit floor plan for the suggested expansion.






**Drumme Rosane Anderson, Inc.**  
235 Bear Hill Road, 4th Floor  
Waltham, MA 02451

Planning 617-964-1700  
Architecture 617-964-1701 fax  
Interior Design info@draws.com



**BASEMENT FLOOR PLAN**




**Town Of Brimfield**  
Municipal Facilities Study and Planning  
Brimfield, Massachusetts

**EXISTING LIBRARY FLOOR PLANS**


Scale: 1/8"=1'-0"  
Drawn by: AJ/CGH  
Job No. 13002.00  
Date: 6/21/13

**EX-L1**





**FIRST FLOOR PLAN**



Scale: 1/8"=1'-0"  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 6/21/13


**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**EXISTING LIBRARY FLOOR PLANS**


**EX-L2**









**BASEMENT FLOOR PLAN**







**FIRST FLOOR PLAN**





MUNICIPAL FACILITIES STUDY AND PLANNING  
Town of Brimfield, Massachusetts

## Public Library

### Structural

#### **Structural Description:**

The Danielson-Lincoln Memorial Library is a one-story (plus partial Basement), wood framed structure, located at 25 Main Street in Brimfield. The building was constructed in 1903 and is listed on the National Register of Historic Places.



The Library is L-shaped in plan (including the Sherman Memorial Room, that was added to the south/back of the original building). Functions at the First Floor include the Front Desk and Collections in the original building; a Work Room and a Bathroom separate this area from the Sherman Memorial Room. The Basement (western two-thirds of the original building) is not used for Library services. Access to the Basement is gained by an internal stair; there is also a bulkhead on the south side of the western wing. The (slate) roof of the original building consists of two intersecting gables; a low pitch gable roof was also constructed over the Sherman Memorial Room. .

Typical foundation walls are rubble stone. Basement Floor construction is a concrete slab on grade (thickness unknown). First Floor construction in the original building is wood framed, with 2" (nominal) wood joists supported by timber beams. Floor construction in the Sherman Memorial Room is a concrete slab on grade (thickness unknown); this floor is approximately two feet lower than the main floor level. Roof construction is also wood framed; the details of this construction were not determined at the site. Exterior walls are solid stone construction, except the upper gable ends of the main (north-south) gable over the entry are stucco finish.

No original construction drawings for the building or previous structural reports were available.

#### **Structural Conditions/Issues – Comments and Recommendations:**

Structural conditions at the Danielson-Lincoln Memorial Library (building exterior) were observed during a brief visit to the site on May 13, 2013. Generally speaking, the wood-framed structure appears to be performing satisfactorily; there is no evidence of structural distress that would indicate significantly overstressed, deteriorated or failed structural members. Foundations appear to be performing adequately; there are no signs of significant, total or differential settlements.

Structural/structurally related conditions observed during site visit are noted below:

- The condition of the exterior stone walls appears to be generally satisfactory. Masonry joints appear to be in satisfactory condition as well.
- The capacity of the First Floor framing was not determined; however, the use of the building has not changed since the original construction, and there are no reports of any structurally related issues.
- The capacity of the roof framing was not determined; however, roof framing appears to be functioning as originally intended.

- There are damaged/missing areas of roof trim at a number of locations around the building. Downspouts are disconnected and some downspouts do not properly direct water away from the foundation walls. If not repaired, these conditions will continue to allow moisture into the building and allow water to build up behind foundation walls.



- The exterior stucco finish at the back, gable end wall of the Sherman Memorial Room is failing and has bowed outwards. This condition should be repaired to prohibit moisture from entering the walls.
- Wood framing may typically be protected (to a degree) by the ceiling construction; however, elsewhere it is unprotected. There are no sprinklers. Fire rating requirements should be reviewed in conjunction with future renovations to the facility.



### **Building Code Requirements and Additional Comments:**

#### **Massachusetts State Building Code Requirements – General Comments:**

Proposed renovations, alterations, repairs and additions to the Danielson-Lincoln Memorial Library would be governed by the provisions of the Massachusetts State Building Code (MSBC – 780 CMR 8<sup>th</sup> Edition) and the Massachusetts Existing Building Code (MEBC). These documents are based on amended versions of the 2009 International Building Code (IBC) and the 2009 International Existing Building Code (IEBC), respectively.

The MEBC allows the Design Team to choose one of three (3) compliance methods. Structurally, the Prescriptive Compliance Method is preferred. Section 101.5.4.0 of the Massachusetts Amendments (Chapter 34) would require that the existing building be investigated in sufficient detail to ascertain the effects of any proposed work (or change in use) in the area under consideration, and the entire building or structure and its foundations, if impacted by the proposed work or change in use.

Additions – General Comments:

The Library is currently in need of additional space. The design and construction of any proposed addition(s) would be conducted in accordance with the Code for new construction. Significant additions should be structurally separated from the existing building by an expansion (seismic) joint to avoid an increase in gravity loads and/or lateral loads to existing structural elements. Smaller additions can be structurally attached to the existing building, provided they do not increase the demand - capacity ratio of the existing lateral force resisting elements in the building by more than 10%.

Renovations/Alterations – General Comments:

Where proposed alterations to existing structural elements carrying gravity loads results in a stress increase of over 5%, the affected element would need to be reinforced or replaced to comply with the Code for new construction. Proposed alterations to existing structural elements carrying lateral load (e.g. the perimeter walls) which result in an increase in the demand - capacity ratio of over 10% should be avoided, if possible. Essentially, this means that removal of, or major alterations to the exterior walls should be minimized. If this is not possible, more significant seismic upgrades/reinforcing will be required; potentially including the addition of lateral force resisting elements (shear walls, etc.).

**End of Structural Report**





TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**Public Library**

25 Main Street

MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS

Prepared By:

Consulting Engineering Services  
510 Chapman Street, Suite 201  
Canton, MA 02021

July 3, 2013

**GENERAL**

The mechanical, electrical, plumbing, and fire protection systems were reviewed in conformance with the requirements of the following State and National codes and regulations, as applicable:

- Massachusetts State Building Code 8th Edition
- Massachusetts State Fire Prevention Regulations
- NFPA Latest Editions
- Massachusetts Plumbing Code
- Massachusetts Mechanical Code
- Massachusetts Electrical code (NEC 2011 Edition)
- Illuminating Engineering Society of North America (IESNA) Lighting Handbook
- ASHRAE 90.1 Latest Edition

The scope of this study does not include operational assessment of the fixtures and equipment reviewed; it includes only a brief visual review of the fixtures and equipment. Therefore notes regarding the condition of the fixtures and equipment may or may not be indicative of the actual condition of the systems and equipment and/or the expected life of the fixtures and equipment. Therefore it is recommended that services of a qualified technician be retained to evaluate the actual condition of fixtures and equipment prior to replacement.

## **MECHANICAL**

### **HEATING**

There are two (2) heating systems within the facility.

One system consists of an oil fired hot air furnace located in the basement of the Library. This system provides heating air to the original portion of the library via decorative grilles located in the floor.

The second system consists of an oil fired hot water boiler located in a small room in the basement of the library. This system provides heating water to the baseboard radiation in the Sherman Memorial Room.

The air system that serves the original portion of the library does include a humidifier. This piece of equipment is badly deteriorated and needs replacement.

The hot air furnace and hot water boiler are in poor condition.

### **AIR CONDITIONING**

Any air conditioning is provided with window type air conditioners.

### **VENTILATION**

Ventilation of the building is done using operable windows. There are no mechanical means of ventilation within the building, however, in the original portion of the building there is a grille located at the very peak of the ceiling which might have been used as some form of natural ventilation at one time.

### **CONTROLS**

Local wall mounted thermostats are located in the main portion of the library and the Sherman Memorial Room to control the heating systems.

### **RECOMMENDATIONS**

Replace the existing hot air furnace with a new furnace with integral air conditioning.

Replace the oil fired boiler with new.

Provide air conditioning in the Sherman Memorial Room.

Provide mechanical ventilation.

## **ELECTRICAL**

### EXISTING SYSTEMS

There is a single 200amp, 120/240volt, single phase electric service that serves the building. This consists of a utility company meter socket and meter on the exterior of the building and a 200amp panelboard in the basement. This equipment is in fair to poor condition.

The lighting throughout the library consists of surface or pendant mounted fluorescent fixtures. There are also some recessed downlights in the Sherman Memorial Room. The basement has limited incandescent lighting. The lighting fixtures in the Library and Sherman Memorial Room are in good condition. The lighting in the basement is in poor condition.

There is a combination fire alarm and security system in the building. This consists of smoke and heat detectors, security contacts, fire alarm horns, and a key pad. This system is in fair to good condition.

### RECOMMENDATIONS

If air conditioning is added to the building, the electrical service should be upgraded at the same time.

Review the fire alarm system coverage and upgrade the system to include ADA compliant speaker/strobes.

Remove the lighting in the basement and replace with new

## **PLUMBING**

### EXISTING SYSTEMS

Cold water is from a well. The pump for the system is in the well therefore the condition of the pump is not included in this study. There is an existing well pump in the basement that is no longer in use. Domestic water comes from the well on the campus that serves multiple building. There is no compression tank for the system that was visible which means that the water pressure is controlled via another building.

Hot water is provided via a coil in the hot water boiler. The hot water discharge from coil is routed directly to the fixtures using hot water. There is no manually adjustable mixing valve.

The exposed water piping in the basement is copper, and it appears to be in fair condition. The exposed drain piping in the basement is cast iron and it appears to be in fair to condition.

The water closet in the restroom is a floor mount vitreous china tank type unit and it appears to be in good condition. This is not an ADA compliant or low-flow water closet.

The lavatory in the restroom is the wall mounted vitreous china type, NON ADA compliant, and it appears to be in good condition.

The work area in the Sherman Memorial Room has a single bowl stainless steel sink. Both the sink and the faucet are not ADA compliant and appear to be in fair to good condition.

## RECOMMENDATIONS

Provide localized point-of use electric water heaters to reduce the use of oil for hot water heating.

Upgrade the plumbing fixtures to meet ADA requirements and current code requirements for low water consuming fixtures.

## FIRE PROTECTION

The building does not have a sprinkler system.



Description	Note	Quantity	Unit	Price	Total
Basic Quantities		GFA	Girth		
basement		848 sf		130 lf	
level 1		2,576 sf		257 lf	
<b>General</b>					
3 Entrance Door					\$
automatic door opener		1	ea	3,341.00	3,341
wire and conduit		100	lf	7.11	711
cut and patch		1	ls	257.79	258
Sub Total - Direct Cost					4,310
General Conditions		20.00%			862
Overhead & Profit		23.00%			1,190
Design & Price Reserve		15.00%			954
Escalation	Aug-15	8.16%			597
Bond		3.00%			237
Soft Costs/Design Fees		30.00%			2,445
Total Project Cost					\$10,595
3 Plaster Ceilings					\$
verify plaster is secure		3,424	sf	0.26	890
patch cracks in ceiling as required		3,424	sf	4.47	15,305
repaint ceilings		3,424	sf	1.36	4,657
Sub Total - Direct Cost					20,852
General Conditions		20.00%			4,170
Overhead & Profit		23.00%			5,755
Design & Price Reserve		15.00%			4,617
Escalation	Aug-15	8.16%			2,888
Bond		3.00%		288.95	1,148
Soft Costs/Design Fees		30.00%			11,829
Total Project Cost					\$51,259
3 Sidewalk Around Building					\$
concrete sidewalk		380	sf	6.63	2,519
Sub Total - Direct Cost					2,519
General Conditions		20.00%			504
Overhead & Profit		23.00%			695
Design & Price Reserve		15.00%			558
Escalation	Aug-15	8.16%			349
Bond		3.00%			139
Soft Costs/Design Fees		30.00%			1,429
Total Project Cost					\$6,193



Description	Note	Quantity	Unit	Price	Total
<b>3 Handrails and Extensions</b>					<b>\$</b>
remove handrail		8	lf	3.39	27
disposal		1	ea	24.20	24
new handrail		8	lf	179.90	1,439
handrail extensions		4	ea	252.14	1,009
Sub Total - Direct Cost					2,499
General Conditions		20.00%			500
Overhead & Profit		23.00%			690
Design & Price Reserve		15.00%			553
Escalation	Aug-15	8.16%			346
Bond		3.00%			138
Soft Costs/Design Fees		30.00%			1,418
Total Project Cost					<u>\$6,144</u>
<b>3 Kitchenette</b>					<b>\$</b>
demo kitchenette		1	ea	338.80	339
disposal		1	ea	145.20	145
accessible kitchenette		1	ea	659.87	660
Sub Total - Direct Cost					1,144
General Conditions		20.00%			229
Overhead & Profit		23.00%			316
Design & Price Reserve		15.00%			253
Escalation	Aug-15	8.16%			158
Bond		3.00%			63
Soft Costs/Design Fees		30.00%			649
Total Project Cost					<u>\$2,812</u>
<b>3 Toilet Room</b>					<b>\$</b>
demo existing toilet room	small area	38	sf	14.52	552
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new toilet rooms		2	ea	12,975.91	25,952
Sub Total - Direct Cost					29,041
General Conditions		20.00%			5,808
Overhead & Profit		23.00%			8,015
Design & Price Reserve		15.00%			6,430
Escalation	Aug-15	8.16%			4,022
Bond		3.00%			1,599
Soft Costs/Design Fees		30.00%			16,475
Total Project Cost					<u>\$71,390</u>



Description	Note	Quantity	Unit	Price	Total
<b>3 Cracks/Bubbling In Vinyl Tile</b>					<b>\$</b>
demo VCT where cracking and bubbling disposal	allowance	100	sf	0.62	62
VCT to match existing vinyl base	allowance	100	sf	2.94	294
		40	lf	2.48	99
<b>Sub Total - Direct Cost</b>					<b>528</b>
General Conditions		20.00%			106
Overhead & Profit		23.00%			146
Design & Price Reserve		15.00%			117
Escalation	Aug-15	8.16%			73
Bond		3.00%			29
Soft Costs/Design Fees		30.00%			300
<b>Total Project Cost</b>					<b>\$1,299</b>
<b>3 Door From Original Building</b>					<b>\$</b>
remove door and frame cut and patch	allowance	1	leaf	47.96	48
		1	ea	259.50	260
<b>Sub Total - Direct Cost</b>					<b>308</b>
General Conditions		20.00%			62
Overhead & Profit		23.00%			85
Design & Price Reserve		15.00%			68
Escalation	Aug-15	8.16%			43
Bond		3.00%			17
Soft Costs/Design Fees		30.00%			175
<b>Total Project Cost</b>					<b>\$758</b>
<b>3 Sash Cords</b>					<b>\$</b>
replace sash cord in children's room windows		2	ea	266.22	532
<b>Sub Total - Direct Cost</b>					<b>532</b>
General Conditions		20.00%			106
Overhead & Profit		23.00%			147
Design & Price Reserve		15.00%			118
Escalation	Aug-15	8.16%			74
Bond		3.00%			29
Soft Costs/Design Fees		30.00%			302
<b>Total Project Cost</b>					<b>\$1,308</b>
<b>2 Basement Stairs</b>					<b>\$</b>
resecure existing railing- carpenter		1	day	542.80	543
<b>Sub Total - Direct Cost</b>					<b>543</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			109
Overhead & Profit		23.00%			150
Design & Price Reserve		15.00%			120
Escalation	Aug-15	8.16%			75
Bond		3.00%			30
Soft Costs/Design Fees		30.00%			308
<b>Total Project Cost</b>					<b>\$1,335</b>
<b>3 Circulation Desk</b>					<b>\$</b>
remove circulation desk		16	lf	11.34	181
disposal		1	ea	157.35	157
new ADA circulation desk		16	lf	692.90	11,086
<b>Sub Total - Direct Cost</b>					<b>11,424</b>
General Conditions		20.00%			2,285
Overhead & Profit		23.00%			3,153
Design & Price Reserve		15.00%			2,529
Escalation	Aug-15	8.16%			1,582
Bond		3.00%			629
Soft Costs/Design Fees		30.00%			6,481
<b>Total Project Cost</b>					<b>\$28,083</b>
<b>3 Signage</b>					<b>\$</b>
demo all signage		3,424	sf	0.05	171
disposal		1	ea	96.80	97
new ADA compliant signage		3,424	sf	0.16	548
<b>Sub Total - Direct Cost</b>					<b>816</b>
General Conditions		20.00%			163
Overhead & Profit		23.00%			225
Design & Price Reserve		15.00%			181
Escalation	Aug-15	8.16%			113
Bond		3.00%			45
Soft Costs/Design Fees		30.00%			463
<b>Total Project Cost</b>					<b>\$2,006</b>
<b>3 Reorganize Furniture For ADA Compliance</b>					<b>\$</b>
reorganize furniture for ADA compliance	labor only	10	days	401.55	4,016
<b>Sub Total - Direct Cost</b>					<b>4,016</b>
General Conditions		20.00%			803
Overhead & Profit		23.00%			1,108
Design & Price Reserve		15.00%			889
Escalation	Aug-15	8.16%			556
Bond		3.00%			221
Soft Costs/Design Fees		30.00%			2,278
<b>Total Project Cost</b>					<b>\$9,871</b>





Description	Note	Quantity	Unit	Price	Total
<b>3 Pipe Downspouts Away From Building</b>					<b>\$</b>
extend downspouts horizontally 8' each	allowance	12	loc	287.49	3,450
Sub Total - Direct Cost					3,450
General Conditions		20.00%			690
Overhead & Profit		23.00%			952
Design & Price Reserve		15.00%			764
Escalation	Aug-15	8.16%			478
Bond		3.00%			190
Soft Costs/Design Fees		30.00%			1,957
Total Project Cost					<u><u>\$8,481</u></u>
<b>2 Trim/Soffit/Fascia Repairs</b>					<b>\$</b>
replace rotted items	allowance	257	lf	24.20	6,219
disposal		1	ea	903.00	903
paint repairs		257	lf	3.08	792
Sub Total - Direct Cost					7,914
General Conditions		20.00%			1,583
Overhead & Profit		23.00%			2,184
Design & Price Reserve		15.00%			1,752
Escalation	Aug-15	8.16%			1,096
Bond		3.00%			436
Soft Costs/Design Fees		30.00%			4,490
Total Project Cost					<u><u>\$19,455</u></u>
<b>3 Repoint Stone Façade</b>					<b>\$</b>
repoint stone façade - allow 5% of wall area		180	sf	31.67	5,701
Sub Total - Direct Cost					5,701
General Conditions		20.00%			1,140
Overhead & Profit		23.00%			1,573
Design & Price Reserve		15.00%			1,262
Escalation	Aug-15	8.16%			790
Bond		3.00%			314
Soft Costs/Design Fees		30.00%			3,234
Total Project Cost					<u><u>\$14,014</u></u>
<b>3 Asphalt Shingles</b>					<b>\$</b>
demo roof shingles		1,040	sf	1.26	1,310
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
roof shingles		1,040	sf	3.93	4,087
flashings		1	ls	2,246.00	2,246
Sub Total - Direct Cost					10,180

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 LIBRARY  
 BRIMFIELD, MA 01010

GFA 3,424



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			2,036
Overhead & Profit		23.00%			2,810
Design & Price Reserve		15.00%			2,254
Escalation	Aug-15	8.16%			1,410
Bond		3.00%			561
Soft Costs/Design Fees		30.00%			5,775
<b>Total Project Cost</b>					<b>\$25,026</b>
<b>2 Gutters</b>					
reinstall fallen gutters	allowance	200	lf	4.78	956
repair gutters		257	lf	6.83	1,755
repair downspouts		168	lf	3.42	575
<b>Sub Total - Direct Cost</b>					<b>3,286</b>
General Conditions		20.00%			657
Overhead & Profit		23.00%			907
Design & Price Reserve		15.00%			728
Escalation	Aug-15	8.16%			455
Bond		3.00%			181
Soft Costs/Design Fees		30.00%			1,864
<b>Total Project Cost</b>					<b>\$8,078</b>
<b>2 Stucco</b>					
remove damaged areas of stucco	allow 50%	658	sf	3.39	2,231
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new stucco to match existing		658	sf	10.54	6,935
paint stucco		658	sf	3.06	2,013
incorporate new expansion joints	15' o.c.	88	lf	28.08	2,471
<b>Sub Total - Direct Cost</b>					<b>16,187</b>
General Conditions		20.00%			3,237
Overhead & Profit		23.00%			4,468
Design & Price Reserve		15.00%			3,584
Escalation	Aug-15	8.16%			2,242
Bond		3.00%			892
Soft Costs/Design Fees		30.00%			9,183
<b>Total Project Cost</b>					<b>\$39,793</b>
<b>3 Bulkhead</b>					
remove wood bulkhead		1	ea	145.20	145
disposal		1	ea	72.60	73
new metal bulkhead		1	ea	1,097.00	1,097
<b>Sub Total - Direct Cost</b>					<b>1,315</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			263
Overhead & Profit		23.00%			363
Design & Price Reserve		15.00%			291
Escalation	Aug-15	8.16%			182
Bond		3.00%			72
Soft Costs/Design Fees		30.00%			746
<b>Total Project Cost</b>					<b>\$3,232</b>

2 Slate Roof					\$
minor repair to slate roof on existing building		2,241	sf	13.20	29,581
dumpster rental			2 weeks	734.71	1,469
load & truck	10 mile round trip	40	cy	55.27	2,211
dump charges		16	ton	87.12	1,394

Sub Total - Direct Cost 34,655

General Conditions		20.00%			6,931
Overhead & Profit		23.00%			9,565
Design & Price Reserve		15.00%			7,673
Escalation	Aug-15	8.16%			4,800
Bond		3.00%			1,909
Soft Costs/Design Fees		30.00%			19,660
<b>Total Project Cost</b>					<b>\$85,193</b>

**Mechanical**

Furnace Replacement					\$
replace furnace, pumps, air handler, and condensing units		3,424	sf	20.88	71,493
disposal		1	ea	7,149.30	7,149
electrician		1	day	581.27	581

Sub Total - Direct Cost 79,223

General Conditions		20.00%			15,845
Overhead & Profit		23.00%			21,866
Design & Price Reserve		15.00%			17,540
Escalation	Aug-18	21.68%			29,154
Bond		2.40%			3,927
Soft Costs/Design Fees		30.00%			50,267

Total Project Cost 217,822

Replace Oil Fired Boiler					\$
demo boiler		3,424	sf	3.39	11,607
disposal		1	ea	1,161.60	1,162
oil fired boiler	2000mbh	1	ea	22,650.27	22,650
electrician		1	day	581.27	581

Sub Total - Direct Cost 36,000



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			7,200
Overhead & Profit		23.00%			9,936
Design & Price Reserve		15.00%			7,970
Escalation	Aug-15	8.16%			4,986
Bond		3.00%			1,983
Soft Costs/Design Fees		30.00%			20,423
<b>Total Project Cost</b>					<b>\$88,498</b>

Air Conditioning Control At Sherman Memorial Room					\$
provide air conditioning	allowance	997	sf	25.68	25,603
cutting and patching		1	ea	1,239.19	1,239
electrician		1	day	581.27	581
<b>Sub Total - Direct Cost</b>					<b>27,423</b>

General Conditions		20.00%			5,485
Overhead & Profit		23.00%			7,569
Design & Price Reserve		15.00%			6,072
Escalation	Aug-15	8.16%			3,798
Bond		3.00%			1,510
Soft Costs/Design Fees		30.00%			15,557
<b>Total Project Cost</b>					<b>\$67,414</b>

Provide Mechanical Ventilation					\$
provide mechanical ventilation for library	allowance	3,424	ea	20.54	70,329
electrician		1	day	581.27	581
<b>Sub Total - Direct Cost</b>					<b>70,910</b>

General Conditions		20.00%			14,182
Overhead & Profit		23.00%			19,571
Design & Price Reserve		15.00%			15,699
Escalation	Aug-15	8.16%			9,822
Bond		2.40%			3,124
Soft Costs/Design Fees		30.00%			39,992
<b>Total Project Cost</b>					<b>\$173,300</b>

**Electrical**

Upgrade Electrical Service					\$
replace power distribution equipment		3,424	sf	5.14	17,599
disposal		1	ea	851.79	852
<b>Sub Total - Direct Cost</b>					<b>18,451</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			3,690
Overhead & Profit		23.00%			5,092
Design & Price Reserve		15.00%			4,085
Escalation	Aug-15	8.16%			2,556
Bond		3.00%			1,016
Soft Costs/Design Fees		30.00%			10,467
<b>Total Project Cost</b>					<b>\$45,357</b>
<b>Upgrade Fire Alarm System</b>					
upgrade fire alarm system		3,424	sf	2.47	\$ 8,457
<b>Sub Total - Direct Cost</b>					<b>8,457</b>
General Conditions		20.00%			1,691
Overhead & Profit		23.00%			2,334
Design & Price Reserve		15.00%			1,872
Escalation	Aug-15	8.16%			1,171
Bond		3.00%			466
Soft Costs/Design Fees		30.00%			4,797
<b>Total Project Cost</b>					<b>\$20,788</b>
<b>Basement Lighting</b>					
remove basement lighting		848	sf	0.58	\$ 492
disposal		1	ea	242.00	242
lighting in basement		848	sf	12.34	10,464
<b>Sub Total - Direct Cost</b>					<b>11,198</b>
General Conditions		20.00%			2,240
Overhead & Profit		23.00%			3,091
Design & Price Reserve		15.00%			2,479
Escalation	Aug-15	8.16%			1,551
Bond		3.00%			617
Soft Costs/Design Fees		30.00%			6,353
<b>Total Project Cost</b>					<b>\$27,529</b>
<b>Plumbing</b>					
<b>Point Of Use Water Heaters</b>					
point of use water heaters and rough in		2	ea	1,417.26	\$ 2,835
<b>Sub Total - Direct Cost</b>					<b>2,835</b>
General Conditions		20.00%			567
Overhead & Profit		23.00%			782
Design & Price Reserve		15.00%			628
Escalation	Aug-15	8.16%			393
Bond		3.00%			156
Soft Costs/Design Fees		30.00%			1,608
<b>Total Project Cost</b>					<b>\$6,969</b>



Description	Note	Quantity	Unit	Price	Total
Upgrade Fixtures To Low Flow					\$
demo fixtures		1	ea	145.20	145
toilet		1	ea	2,485.34	2,485
Sub Total - Direct Cost					<u>2,630</u>
General Conditions		20.00%			526
Overhead & Profit		23.00%			726
Design & Price Reserve		15.00%			582
Escalation	Aug-15	8.16%			364
Bond		3.00%			145
Soft Costs/Design Fees		30.00%			1,492
Total Project Cost					<u><u>\$6,465</u></u>
Library Expansion/Renovation					\$
Library expansion/renovation (cost plan)		4,488	sf	227.23	1,019,823
Sub Total - Direct Cost					<u>1,019,823</u>
General Conditions		12.00%			122,379
Overhead & Profit		14.00%			159,908
Design & Price Reserve		15.00%			195,317
Escalation	Aug-15	8.16%			122,190
Bond		2.00%			32,392
Soft Costs/Design Fees		30.00%			495,603
Total Project Cost					<u><u>\$2,147,612</u></u>

TOWN OF BRIMFILED

Massachusetts

LIBRARY

Program Areas

	EXISTING SPACE	SUGGESTED PROGRAM	TEST FIT AREAS - SEE PLAN
<b>LIBRARY - BASEMENT</b>			
Mechanical / Storage	806	806	806
<b>TOTAL LIBRARY - BASEMENT</b>	<b>806</b>	<b>806</b>	<b>806</b>

<b>LIBRARY - FIRST FLOOR</b>			
Book Stack #1	803		
Book Stack #2	661		
Storage #1	25	25	
Storage #2	45	45	45
Storage #3	31		
Kitchenette			25
Toilet	32		
Sherman Memorial Room	697		
Work Area	110		116
Entry		58	58
Director's Office		77	77
Circulation		360	163
AV/Public Circ Area			313
Children's		822	713
Fiction		435	294
Handicapped Toilets		110	110
Reading Room		661	661
Adult non-fiction / Reference/Historic		803	803
<b>TOTAL LIBRARY - FIRST FLOOR</b>	<b>2404</b>	<b>3396</b>	<b>3378</b>

<b>LIBRARY - NET AREA</b>			
Basement	806	806	806
First Floor	2404	3396	3378
<b>TOTAL LIBRARY - NET AREA</b>	<b>3210</b>	<b>4202</b>	<b>4184</b>

<b>LIBRARY - GROSS AREA</b>			
Basement	1124	1124	1124
First Floor	3010	4075	4071
<b>TOTAL LIBRARY - NET AREA</b>	<b>4134</b>	<b>5199</b>	<b>5195</b>





BUILDING USE AUDIT - CONDITION ASSESSMENT  
Town of Brimfield, Massachusetts

**Brimfield Highway Department**

Wales Road

Year Constructed: Approx. 1995  
Construction Type: Although the main building is IIB work to the building has lowered the classification to VB

Fire Sprinklers: No

Building Area per Floor:  
First Floor: 6776 SF  
Mezzanine: 747 SF  
Total Area: 7523 SF

Shed Area per Building:  
Shed #1: 2228 SF  
Shed #2: 313 SF  
Total Area: 2541 SF

Documents Used in Study:  
Aerial Photographs.

**Main Building:**

- 3 Replace all locksets with lever hardware type except at the two toilet rooms. Add closer to exterior doors to Entrance Hall and Break Room.
- 4 VCT flooring in the Hall is damaged in several places. In other areas (Office, Toilets & Break Rm.) VCT is not performing well. Remove existing VCT flooring and base, replace with sheet vinyl.
- 3 Door to Toilet #2, both approaches do not meet code. Change door and frame to the opposite swing.
- 3 Door to Break Room has insufficient side clearances. Change door and frame to the opposite swing.



- 4 Suspended ceiling panels throughout are aged (dull/dirty & sagging) and need to be replaced.
- 3 Break Room kitchen base cabinet has no knee space and is not ADA compliant. Change base cabinets.
- 2 The riser/tread ratio and handrail on the wood stair up to the mezzanine do not meet code. Remove stair and build new metal stair.
- 2 At Mezzanine level the existing wood guardrail does not meet code. Remove and replace with new metal guardrail.
- 4 Install new trench drain and associated piping in existing concrete slab in Maintenance Bays and Vehicle / Storage Bays.
- 2 A storage container was placed adjacent to the west end of the building and a wood enclosure was constructed over it. Exiting from the storage container requires passing through three adjacent areas before reaching an exit access hallway. Code allows passage through only one adjacent space. Similarly, the direct and second exit from the vehicle bays has been enclosed by the wood structure leaving only one exit for the vehicle and maintenance bays. New exit doors should be added; one on the north side of the vehicle bays and one in the storage area adjacent to the container.
- The storage container is not a permanent solution to the needs of the facility and should be replaced with a metal building addition. The addition needs to accommodate the storage needs plus space for items of equipment that cannot be currently stored in the building. It should also include a wash bay for vehicles with a water recycling system. See program information below.

### **Structural**

The building is in general good condition. Refer to Structural Report.

### **Mechanical**

- 4 Update heating equipment from oil to gas, saving energy due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).
- 4 Update to programmable type thermostats for control of the furnaces.
- 4 Central air conditioning could easily be added for the furnace serving the office areas since the majority of the ductwork is accessible for installation of insulation. Add an evaporator coil on the discharge side of the furnace and provide a split system condensing unit outside the mechanical room piped to the coil. Further, provide a

means for outdoor air to this unit by ducting air from a small sidewall intake louver to the return side of the furnace. Provide a motorized damper on this outdoor air intake that opens upon activation of the fan.

- 2 There is no exhaust collection system. Add system to the maintenance bays (1st priority) and to the vehicle bays (2nd priority) or provide the following:
- 2 Depending on the usage of the vehicle fume exhaust system when the doors are closed it may be prudent to add a toxic gas detection system for the garage area to alert occupants upon a rise in CO and NO<sub>2</sub> emissions which can be life threatening when breathed in by humans at certain concentrations. This type of system can be as simple as
  - sounding an alarm or as complex as
  - energizing ventilation equipment to deplete levels upon detection.

## Plumbing

- 4 The water closet in the accessible bathroom at the front entrance should be replaced by a low flow fixture.
- 3 The laundry tub should be replaced.
- 2 The existing water heater should be provided with a mixing valve, such that 140°F can be maintained in the tank without the possibility of scalding at the fixtures.

## Electrical

- 2 The manual transfer switch should be replaced with an automatic transfer switch and fixed generator. The use of a portable generator presents a safety concern with the dispensing of fuel, etc.
- 2 New LED exit signs with integral batteries should be provided to replace the existing.
- 4 The exterior lighting should be replaced with a high-efficiency LED type fixture to improve the lighting levels and reduce energy costs.

## Shed #1

- 2 Salt and sand mixture is not fully contained within the building as a significant gap exists between the walls of the facility and the asphalt paving inside the facility. Overtime this will (or has) caused salt to leach into the ground. For the interior it is recommended that a continuous steel angle be bolted to the horizontal wood boards and columns, and

painted with bituminous paint, and sealed to the paving. The angle should be a minimum 7"x4"x3/8" with the long leg vertical.

3 Exterior siding has deteriorated where it connects to the ground. Bottom of siding should be removed to a consistent height around the entire building (approx. 1'-0"). Metal flashing to be install at bottom of existing siding, and new horizontal pressure treated siding installed to grade.

2 Diagonal wall braces are generally in good condition but two members need to be replaced.

2 Metal roof is in poor condition and needs to be replaced.

### **Shed #2**


Building appears to be in good condition. No work is suggested at this time.

## **PROGRAM INFORMATION:**


### **Main Building**

An expansion of the facility is recommended to provide permanent storage (in lieu of the storage container) and to provide a vehicle wash bay with a re-circulating wash system.


The expansion should be constructed to match the existing construction type of the building.




**MEZZANINE PLAN**




**FIRST FLOOR PLAN**



**SHED #1 PLAN**




**SHED #2 PLAN**




**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts  
**EXISTING HIGHWAY DEPARTMENT & SHEDS FLOOR PLAN**

Scale: N.T.S.  
 Drawn by: ASJ  
 Job No. 13002.00  
 Date: 6/21/13







MEZZANINE PLAN




FIRST FLOOR PLAN



PROPOSED HIGHWAY DEPARTMENT



SHED #1 PLAN



SHED #2 PLAN

**Town Of Brimfield**  
 Municipal Facilities Study and Planning  
 Brimfield, Massachusetts

**PROPOSED HIGHWAY DEPARTMENT & SHEDS**  
**FLOOR PLAN**

Scale: N.T.S.  
 Drawn by: AJ/CGH  
 Job No. 13002.00  
 Date: 6/21/13





MUNICIPAL FACILITIES STUDY AND PLANNING  
Town of Brimfield, Massachusetts

## Highway Garage

Structural

### Structural Description:

The Brimfield Highway Garage is a one-story pre-engineered, steel framed structure, located at 34B Wales Road in Brimfield. The construction date of the building is unknown; however, it appears to be 1970's vintage.

The Highway Garage is rectangular in plan, approximately 120 feet long (east-west) and 60 feet wide (north-south). There is a small (attached) shed structure on the west end of the building. In addition, there are two, separate Storage Sheds on the grounds, located to the east of the Garage. The larger Shed (No. 1) is used for sand and salt storage and the smaller (newer) Shed (No. 2) is used for salt storage only.

Offices are located at the east end of the Garage; a wood framed Storage Mezzanine was constructed over the Offices as well. There five (5) overhead doors to the west of the Offices, located along the south side of the building. There is an additional overhead door at the northeast corner of the building, behind the Offices. The roof is relatively flat, pitching downwards to the back/north side of the building for drainage.

Typical foundation construction is assumed to be conventional spread footings, with a concrete slab on grade First (Ground) Floor. Foundation walls (12" thick) extend approximately four feet above the floor on the north, east and west sides of the building. Roof construction consists of 9½" deep, galvanized steel "zee" purlins spaced at 5+/- feet on centers, spanning approximately 20 feet to steel frames. Steel frames clear span the space (approximately 60 feet) and pitch downwards to the back for drainage, as noted above. A metal roof with "bag" insulation spans between the zee purlins. The east and west end walls of the building are framed with a continuous steel edge/rake beam, supported by steel columns (4 equally spaced, approximately 20 feet on centers). Lateral stability (wind and seismic loads) in the north-south direction is provided by the rigid steel frames, spaced every 20+/- feet. In the east-west direction, lateral stability is provided by a single, 20+/- feet long braced frame (steel "X" braces) on the back/north wall and by a single, 20+/- feet long rigid steel frame (located in the same structural bay as the braced frame on the opposite wall) on the front/south wall. These two, east- west lateral force resisting elements are enjoined by "X" bracing in the plane of the roof. Exterior wall construction is insulated metal panels, spanning vertically to 9½" deep, galvanized steel



“zee” girts, which span horizontally (20+/- feet) to the steel frames. There are two lines of girts between the top of the foundation wall and the eave, resulting in three (3), approximately equal wall panel spans. Full height, light gauge jamb studs have been provided at overhead door locations.

Shed No. 1 is a one-story, wood framed storage structure with a gable roof. The building is rectangular in plan; approximately 40 feet wide by 60 feet long. Prefabricated, metal plate connected wood trusses, spaced at 4+/- feet on centers, clear span the roof (approximately 40 feet, in the east-west direction). Two inch (nominal) wood purlins (laid flat) spaced at 2+/- feet on centers span between trusses and support a metal roof, with ribs spanning up and down the slope. The building is uninsulated. Walls are wood framed, with buttressed, double wall construction at the lower regions to withstand the horizontal pressure from piled sand/salt. Foundations are unknown; however, it appears that a pole foundation may have been used (typical for this type of structure).

Shed No. 2 is a newer, one-story, wood framed storage structure, also with a gable roof. The building is rectangular in plan; approximately 22 feet square. The roof is stick-framed, with tied wood rafters spaced at 2+/- feet on centers, clear spanning the width of the building (approximately 22 feet in the north-south direction). Two inch (nominal) purlins (laid flat) spaced at 2+/- feet on centers span between the rafters and support a metal roof, with ribs spanning up and down the slope. The building is uninsulated. Foundations consist of interlocking, stacked, precast concrete blocks (2 feet wide by 2 feet high by 6+/- feet long), extending 4+/- feet above the floor level. Lateral pressure from piled salt are resisted by gravity forces exerted by the weight of the stacked blocks.

No original construction drawings or previous structural reports were available for the Garage or the Storage Sheds.

### **Structural Conditions/Issues – Comments and Recommendations:**

Structural conditions at the Highway Garage were observed during a brief tour of the facility on May 13, 2013. Most of the roof and wall construction was exposed to view, except in the Office area. Generally speaking, floor and roof construction in the Garage appears to be performing satisfactorily; there is no evidence of structural distress that would indicate significantly overstressed, deteriorated or failed structural members. Foundations appear to be performing adequately; there are no signs of significant, total or differential settlements. The concrete slab on grade and the 4 feet high concrete wall on three sides of the building appear to be in satisfactory condition.

Structural/structurally related conditions observed during site visit are noted below:

- The condition of the metal panel exterior wall construction and backup steel girt framing system of the Garage appears to be generally satisfactory.

- The capacity of the wood framed Storage Mezzanine framing in the Garage was not determined; however, storage loading appears to be relatively light. Further review/evaluation is recommended in conjunction with future renovations to the building.
- The capacity of the Garage roof framing was not determined (pre-engineered steel framing is a proprietary design) ; however, roof framing appears to be functioning as originally intended.
- Steel roof framing of the Garage is unprotected and has no fire resistance rating. There are no sprinklers. Fire rating requirements should be reviewed in conjunction with future renovations to the facility.
- The wood framed roof and wall construction of Shed No. 1 and Shed No. 2 appears to be quite light (not uncommon for unoccupied storage building); further review/evaluation is recommended in conjunction with future plans for the grounds surrounding the Garage. The wood buttresses that laterally brace the lower, double wall construction of Shed No. 1 have been overstressed in the past; one brace has noticeably failed.



### **Building Code Requirements and Additional Comments:**

#### **Massachusetts State Building Code Requirements – General Comments:**

Proposed renovations, alterations, repairs and additions to the Brimfield Highway Garage would be governed by the provisions of the Massachusetts State Building Code (MSBC – 780 CMR 8<sup>th</sup> Edition) and the Massachusetts Existing Building Code (MEBC). These documents are based on amended versions of the 2009 International Building Code (IBC) and the 2009 International Existing Building Code (IEBC), respectively.

The MEBC allows the Design Team to choose one of three (3) compliance methods. Structurally, the Prescriptive Compliance Method is preferred. Section 101.5.4.0 of the Massachusetts Amendments (Chapter 34) would require that the existing building be investigated in sufficient detail to ascertain the effects of any proposed work (or change in use) in the area under consideration, and the entire building or structure and its foundations, if impacted by the proposed work or change in use.

#### **Additions – General Comments:**

The design and construction of any proposed additions would be conducted in accordance with the Code for new construction. Significant additions should be structurally separated from the existing building by an expansion (seismic) joint to avoid an increase in gravity loads and/or

lateral loads to existing structural elements. Smaller additions can be structurally attached to the existing building, provided they do not increase the demand - capacity ratio of the existing lateral force resisting elements in the building by more than 10%.

Renovations/Alterations – General Comments:

Where proposed alterations to existing structural elements carrying gravity loads results in a stress increase of over 5%, the affected element would need to be reinforced or replaced to comply with the Code for new construction. Proposed alterations to existing structural elements carrying lateral load (rigid frames or steel “X” bracing) which result in an increase in the demand - capacity ratio of over 10% should be avoided, if possible. Essentially, this means that removal of, or major alterations to these elements should be avoided. If this is not possible, more significant seismic upgrades/reinforcing will be required; potentially including the addition of lateral force resisting elements (additional “X” braces, etc.).

**End of Structural Report**

TOWN BUILDING ASSESSMENT STUDY AND CAPITAL MASTER PLAN  
Town of Brimfield, Massachusetts

**DPW Building**

34 Wales Street

MECHANICAL, ELECTRICAL, PLUMBING, AND FIRE PROTECTION SYSTEMS

Prepared By:

Consulting Engineering Services  
510 Chapman Street, Suite 201  
Canton, MA 02021

July 3, 2013

**GENERAL**

The mechanical, electrical, plumbing, and fire protection systems were reviewed in conformance with the requirements of the following State and National codes and regulations, as applicable:

- Massachusetts State Building Code 8th Edition
- Massachusetts State Fire Prevention Regulations
- NFPA Latest Editions
- Massachusetts Plumbing Code
- Massachusetts Mechanical Code
- Massachusetts Electrical code (NEC 2011 Edition)
- Illuminating Engineering Society of North America (IESNA) Lighting Handbook
- ASHRAE 90.1 Latest Edition

The scope of this study does not include operational assessment of the fixtures and equipment reviewed; it includes only a brief visual review of the fixtures and equipment. Therefore notes regarding the condition of the fixtures and equipment may or may not be indicative of the actual condition of the systems and equipment and/or the expected life of the fixtures and equipment. Therefore it is recommended that services of a qualified technician be retained to evaluate the actual condition of fixtures and equipment prior to replacement.

## MECHANICAL

### HEATING

An oil fired, gravity vent, hot air furnace located in the mechanical room below the mezzanine serves the adjacent offices and ancillary spaces with overhead ducted supply and returns. This unit comprises a single zone with a dial type thermostat in the main office area. A single 275 gallon oil tank in the same room has local fill and vent connections at the exterior wall of building and fuels this furnace.

Another oil fired, gravity vent, hot air furnace located on the mezzanine within the main garage serves the heated portion of the garages with a single supply trunk down the middle of the space. The unit is controlled from a single dial thermostat in the garage. This furnace is also fueled from the oil tank in the mechanical room below via a separate oil line. Both furnaces tie into a common double wall venting assembly routed through the floor of the mezzanine then up through the roof. Both furnaces are in fair to good condition.

### AIR CONDITIONING

There is no central air conditioning system in the building.

### VENTILATION

The men's and women's bathrooms located below the mezzanine are both exhausted through an inline fan mounted on the mezzanine discharging to a louver in the side of the building. Windows in the office areas are operable and appear to meet the required free area for natural ventilation and there is no form of outdoor air to this building provided mechanically.

The unheated portion of the garage bays includes a large sidewall propeller fan in the corner of the building for general exhaust. This fan is locally switched on or off.

The heated garage bays include (4) ceiling paddle fans for general air circulation that are locally switched on or off. This area also has a vehicle fume exhaust system mounted overhead with (2) hose drops (tail pipe connectors) and a PVC discharge pipe from the fan routed through the back of the building to a wall cap. This system is also locally switched.

### RECOMMENDATIONS

Update heating equipment from oil to gas, saving energy due to better equipment efficiencies and achieve an overall operating savings (if gas is locally available).

Update to programmable type thermostats for control of the furnaces.

Central air conditioning could easily be added for the furnace serving the office areas since the majority of the ductwork is accessible for installation of insulation. Add an evaporator coil on the discharge side of the furnace and provide a split system condensing unit outside the mechanical room piped to the coil. Further, provide a means for outdoor air to this unit by ducting air from a small sidewall intake louver to the return side of the furnace. Provide a motorized damper on this outdoor air intake that opens upon activation of the fan.

Depending on the usage of the vehicle fume exhaust system when the doors are closed it may be prudent to add a toxic gas detection system for the garage area to alert occupants upon a rise in CO and NO<sub>2</sub> emissions which can be life threatening when breathed in by humans at certain concentrations. This type of system can be as simple as sounding an alarm or as complex as energizing ventilation equipment to deplete levels upon detection.

## **ELECTRICAL**

### **EXISTING SYSTEMS**

The building is served by a single 200 amp electric service located in an equipment room accessed from the exterior of the building. The service equipment was installed in or around 1995 and is in good condition.

The building also has a 60amp manual transfer switch to which a portable generator is attached via portable cord in the event of a power outage. An existing 10,000w portable generator is stored in the maintenance bays. This generator is in good condition.

The lighting consists of 8' industrial fluorescent fixtures with T8 lamps in the maintenance bays and 2x4 recessed acrylic lensed fixtures in office and other areas. The lighting in the maintenance bays and other areas is adequate.

The exit signs are older fluorescent types without batteries. These fixtures are in poor condition.

The exterior lighting consists of wall mounted high pressure sodium fixtures controlled by a time clock. These fixtures are in fair condition.

### **RECOMMENDATIONS**

The manual transfer switch should be replaced with an automatic transfer switch and fixed generator. The use of a portable generator presents a safety concern with the dispensing of fuel, etc.

New LED exit signs with integral batteries should be provided to replace the existing.

The exterior lighting should be replaced with a high-efficiency LED type fixture to improve the lighting levels and reduce energy costs.

## **PLUMBING**

### **EXISTING SYSTEMS**

Water is provided by a well pump. See the Police and Fire Building study for additional information.

There is a stainless steel kitchen sink with a faucet and hose spray in the break room, which appears to be in good condition. As the water from the tap is not potable (see the Police and Fire Building study) a large bottled water unit is provided for drinking water.

There is an accessible restroom at the front entrance, and both the lavatory and the water closet in this restroom appear to be in good condition. The water closet is a floor mount vitreous china tank type fixture, and the lavatory is a wall mount vitreous china fixture. The water closet is not a low flow fixture.

There also is a second accessible restroom accessed from the service area, and the lavatory, the water closet, and the urinal in this restroom appear to be in good condition. The water closet is a floor mount vitreous china tank type fixture, the lavatory is a wall mount vitreous china fixture, and the urinal is a wall mount flush valve vitreous china type fixture. Both the water closet and the urinal are low flow fixtures.

There is a shower in the restroom accessed from the service area. Both the enclosure and the valve appear to be in fair condition. The valve appears to be the pressure balanced type.

There is a laundry tub in the service area which appears to be in fair to poor condition.

There is an air compressor in service area towards the East. It appears to be in good condition. There is no permanent compressed air piping system in the building; hoses only are connected to the compressor.

The water heater is an oil fired tank type water heater that appears to be in fair condition. There is no mixing valve provided with the water heater.

There are no floor drains in any of the service bays.

### **RECOMMENDATIONS**

The water closet in the accessible bathroom at the front entrance should be replaced by a low flow fixture.



The laundry tub should be replaced.

The existing water heater should be provided with a mixing valve, such that 140°F can be maintained in the tank without the possibility of scalding at the fixtures.

## **FIRE PROTECTION**

The building does not have a sprinkler system.



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
HIGHWAY DEPARTMENT  
BRIMFIELD, MA 01010

GFA 8,890



Description	Note	Quantity	Unit	Price	Total
<b>Basic Quantities</b>					
level 1		7,995	sf		
mezzanine		895	sf		
shed		2,425	sf		
salt shed		443	sf		
<b>3 Door Hardware</b>					
remove door hardware		9	ea	68.97	621
disposal		1	ea	96.80	97
new lever hardware		9	ea	874.74	7,873
exterior door closer		2	ea	1,563.23	3,126
Sub Total - Direct Cost					11,717
General Conditions		20.00%			2,343
Overhead & Profit		23.00%			3,234
Design & Price Reserve		15.00%			2,594
Escalation	May-15	8.16%			1,623
Bond		3.00%			645
Soft Costs/Design Fees		30.00%			6,647
<b>Total Project Cost</b>					<b>\$28,803</b>
<b>4 VCT Flooring</b>					
demo VCT flooring		527	sf	0.62	327
demo base		215	lf	0.96	206
disposal		1	ea	96.80	97
self leveling underlayment		527	sf	1.21	638
sheet vinyl flooring		527	sf	7.35	3,873
vinyl base		215	lf	2.52	542
Sub Total - Direct Cost					5,683
General Conditions		20.00%			1,137
Overhead & Profit		23.00%			1,569
Design & Price Reserve		15.00%			1,258
Escalation	May-15	8.16%			787
Bond		3.00%			313
Soft Costs/Design Fees		30.00%			3,224
<b>Total Project Cost</b>					<b>\$13,971</b>
<b>3 Toilet #2</b>					
demo door and frame		1	leaf	47.96	48
disposal		1	ea	48.40	48
new h.m. door and frame		1	leaf	1,541.08	1,541
paint door		1	ea	120.05	120
patch wall as required		1	ea	306.25	306
Sub Total - Direct Cost					2,063

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
HIGHWAY DEPARTMENT  
BRIMFIELD, MA 01010

GFA 8,890



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			413
Overhead & Profit		23.00%			569
Design & Price Reserve		15.00%			457
Escalation	May-15	8.16%			286
Bond		3.00%			114
Soft Costs/Design Fees		30.00%			1,171
<b>Total Project Cost</b>					<b>\$5,073</b>
<b>3 Break Room</b>					<b>\$</b>
demo door and frame		1	leaf	47.96	48
disposal		1	ea	48.40	48
new h.m. door and frame		1	leaf	1,541.08	1,541
paint door		1	ea	120.05	120
patch wall as required		1	ea	306.25	306
<b>Sub Total - Direct Cost</b>					<b>2,063</b>
General Conditions		20.00%			413
Overhead & Profit		23.00%			569
Design & Price Reserve		15.00%			457
Escalation	May-15	8.16%			286
Bond		3.00%			114
Soft Costs/Design Fees		30.00%			1,171
<b>Total Project Cost</b>					<b>\$5,073</b>
<b>4 Ceilings</b>					<b>\$</b>
demo suspended ceilings (act)		8,890	sf	0.73	6,490
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new act ceilings		8,890	sf	3.76	33,426
<b>Sub Total - Direct Cost</b>					<b>42,453</b>
General Conditions		20.00%			8,491
Overhead & Profit		23.00%			11,717
Design & Price Reserve		15.00%			9,399
Escalation	May-15	8.16%			5,880
Bond		3.00%			2,338
Soft Costs/Design Fees		30.00%			24,083
<b>Total Project Cost</b>					<b>\$104,361</b>
<b>3 Modify Kitchen Base Cabinet</b>					<b>\$</b>
demo kitchen base cabinets		7	lf	9.24	65
disposal		1	ea	72.60	73
base cabinets with ADA required knee space and ctop		7	lf	262.50	1,838
<b>Sub Total - Direct Cost</b>					<b>1,976</b>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
HIGHWAY DEPARTMENT  
BRIMFIELD, MA 01010

GFA

8,890



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			395
Overhead & Profit		23.00%			545
Design & Price Reserve		15.00%			437
Escalation	May-15	8.16%			274
Bond		3.00%			109
Soft Costs/Design Fees		30.00%			1,121
<b>Total Project Cost</b>					<b>\$4,857</b>
<b>2 Stair To Mezzanine</b>					
					\$
demo stair		50	lfr	33.88	1,694
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new steel pan stair		50	lfr	130.69	6,535
radial rubber stair tread/riser		50	lfr	19.56	978
new guard rail		24	lf	179.90	4,318
new hand rail		24	lf	154.20	3,701
paint guard rail		24	lf	14.70	353
paint hand rail		24	lf	4.29	103
cut and patch as required		1	ea	1,010.95	1,011
<b>Sub Total - Direct Cost</b>					<b>21,230</b>
General Conditions		20.00%			4,246
Overhead & Profit		23.00%			5,859
Design & Price Reserve		15.00%			4,700
Escalation		8.16%			2,940
Bond		3.00%			1,169
Soft Costs/Design Fees		30.00%			12,043
<b>Total Project Cost</b>					<b>52,187</b>
<b>2 Mezzanine Guardrail</b>					
					\$
demo wood guardrail		64	lf	4.63	296
disposal		1	ea	66.20	66
metal guardrail		64	lf	198.60	12,710
paint guard rail		64	lf	14.70	941
<b>Sub Total - Direct Cost</b>					<b>14,013</b>
General Conditions		20.00%			2,803
Overhead & Profit		23.00%			3,868
Design & Price Reserve		15.00%			3,103
Escalation	May-15	8.16%			1,941
Bond		3.00%			772
Soft Costs/Design Fees		30.00%			7,950
<b>Total Project Cost</b>					<b>\$34,450</b>

TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
HIGHWAY DEPARTMENT  
BRIMFIELD, MA 01010

GFA

8,890



Description	Note	Quantity	Unit	Price	Total
<b>4 New Trench Drain</b>					<b>\$</b>
saw cut concrete	allowance	200	lf	1.94	388
remove concrete slab	allowance	100	sf	9.68	968
disposal	allowance	1	ea	242.00	242
excavation inside existing building	allowance	7	cy	108.42	759
disposal off site	allowance	7	cy	24.72	173
trench drain - piping and cover	allowance	100	lf	112.65	11,265
connect to drainage system	allowance	1	ea	513.50	514
<b>Sub Total - Direct Cost</b>					<b>14,309</b>
General Conditions		20.00%			2,862
Overhead & Profit		23.00%			3,949
Design & Price Reserve		15.00%			3,168
Escalation	May-15	8.16%			1,982
Bond		3.00%			788
Soft Costs/Design Fees		30.00%			8,117
<b>Total Project Cost</b>					<b>\$35,175</b>
<b>2 Storage Container - Additional Exits</b>					<b>\$</b>
demo exterior walls for new openings		2	ea	242.00	484
disposal		1	ea	169.40	169
exterior h.m. door, frame and hardware		2	leaf	2,740.69	5,481
paint exterior door		2	leaf	157.73	315
<b>Sub Total - Direct Cost</b>					<b>6,449</b>
General Conditions		20.00%			1,290
Overhead & Profit		23.00%			1,780
Design & Price Reserve		15.00%			1,428
Escalation	May-15	8.16%			893
Bond		3.00%			355
Soft Costs/Design Fees		30.00%			3,659
<b>Total Project Cost</b>					<b>\$15,854</b>
<b>Highway Department Addition</b>					<b>\$</b>
demo wood storage enclosure		903	sf	4.84	4,371
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
metal building addition		2,456	sf	250.37	614,909
addition from other side of building		348	sf	250.37	87,129
water recycling system in wash bay	arch quote	1	ea	30,000.00	30,000
catch basin		1	ea	2,420.00	2,420
saw cut concrete	allowance	200	lf	1.94	388
remove concrete slab	allowance	100	sf	9.68	968
disposal	allowance	1	ea	242.00	242
excavation inside existing building	allowance	7	cy	108.42	759
disposal off site	allowance	7	cy	24.72	173
trench drain - piping and cover	allowance	100	lf	112.65	11,265
connect to drainage system	allowance	1	ea	513.50	514
<b>Sub Total - Direct Cost</b>					<b>755,675</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		14.00%			105,795
Overhead & Profit		16.00%			137,835
Design & Price Reserve		15.00%			149,896
Escalation	May-15	8.16%			93,775
Bond		2.00%			24,860
Soft Costs/Design Fees		30.00%			380,351
<b>Total Project Cost</b>					<b>\$1,648,187</b>

**Mechanical**

Heating Equipment					\$
demo oil heating equipment		1	ea	704.37	704
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new gas service - trench only - service by gas company		200	lf	26.18	5,236
misc. exterior repairs from trench		1	ea	1,936.00	1,936
cast iron gas boiler	160mbh	1	ea	4,589.90	4,590
cast iron gas boiler	60mbh	1	ea	1,721.21	1,721
condensing unit	3 ton	1	ea	6,547.13	6,547
gas piping allowance	1 1/4"	100	lf	16.95	1,695
<b>Sub Total - Direct Cost</b>					<b>24,966</b>
General Conditions		20.00%			4,993
Overhead & Profit		23.00%			6,891
Design & Price Reserve		15.00%			5,528
Escalation	May-15	8.16%			3,458
Bond		3.00%			1,375
Soft Costs/Design Fees		30.00%			14,163
<b>Total Project Cost</b>					<b>\$61,374</b>

Replace Existing Thermostats					
demo existing thermostats	allowance	10	ea	72.60	726
disposal		1	ea	48.40	48
new thermostats	allowance	10	ea	256.75	2,568
<b>Sub Total - Direct Cost</b>					<b>3,342</b>

General Conditions		20.00%			668
Overhead & Profit		23.00%			922
Design & Price Reserve		15.00%			740
Escalation	May-15	8.16%			463
Bond		3.00%			184
Soft Costs/Design Fees		30.00%			1,896
<b>Total Project Cost</b>					<b>8,215</b>



Description	Note	Quantity	Unit	Price	Total
<b>Central Air</b>					<b>\$</b>
add evaporator coil on discharge side of furnace		1	ea	1,540.50	1,541
condensing unit	3 ton	1	ea	6,547.13	6,547
split system condensing unit piped to coil	allowance	100	lf	6.90	690
vent unit to exterior		1	ea	1,283.75	1,284
small motorized damper		1	ea	829.77	830
electrician		1	day	478.97	479
<b>Sub Total - Direct Cost</b>					<b>11,371</b>
General Conditions		20.00%			2,274
Overhead & Profit		23.00%			3,138
Design & Price Reserve		15.00%			2,517
Escalation	May-15	8.16%			1,575
Bond		3.00%			626
Soft Costs/Design Fees		30.00%			6,450
<b>Total Project Cost</b>					<b>\$27,951</b>
<b>Vehicle Exhaust Collection Sytem</b>					<b>\$</b>
exhaust collection system maintenance bays		1,564	sf	5.14	8,039
exhaust collection system vehicle bays		4,408	sf	5.14	22,657
<b>Sub Total - Direct Cost</b>					<b>30,696</b>
General Conditions		20.00%			6,139
Overhead & Profit		23.00%			8,472
Design & Price Reserve		15.00%			6,796
Escalation	May-15	8.16%			4,252
Bond		3.00%			1,691
Soft Costs/Design Fees		30.00%			17,414
<b>Total Project Cost</b>					<b>\$75,460</b>
<b>Toxic Gas Detection System</b>					<b>\$</b>
garage area - alarm only	C02 and NO2	5,972	sf	0.77	4,598
<b>Sub Total - Direct Cost</b>					<b>4,598</b>
General Conditions		20.00%			920
Overhead & Profit		23.00%			1,269
Design & Price Reserve		15.00%			1,018
Escalation	May-15	8.16%			637
Bond		3.00%			253
Soft Costs/Design Fees		30.00%			2,609
<b>Total Project Cost</b>					<b>\$11,304</b>
<b>Toxic Gas Detection System</b>					<b>\$</b>
garage area - energizing ventilation equipment	C02 and NO2	5,972	sf	7.70	45,984
<b>Sub Total - Direct Cost</b>					<b>45,984</b>



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
HIGHWAY DEPARTMENT  
BRIMFIELD, MA 01010

GFA

8,890



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			9,197
Overhead & Profit		23.00%			12,692
Design & Price Reserve		15.00%			10,181
Escalation	May-15	8.16%			6,369
Bond		3.00%			2,533
Soft Costs/Design Fees		30.00%			26,087
<b>Total Project Cost</b>					<b>\$113,043</b>
<b>Shed #1</b>					<b>\$</b>
continuous p.t. 2"x10" bolted to horizontal boards		201	lf	2.79	561
paint - bituminous		201	lf	2.72	547
sealant		201	lf	6.18	1,242
<b>Sub Total - Direct Cost</b>					<b>2,350</b>
General Conditions		20.00%			470
Overhead & Profit		23.00%			649
Design & Price Reserve		15.00%			520
Escalation	May-15	8.16%			326
Bond		3.00%			129
Soft Costs/Design Fees		30.00%			1,333
<b>Total Project Cost</b>					<b>\$5,777</b>
<b>Shed #1 Exterior Wall</b>					<b>\$</b>
saw cut perimeter of exterior wood wall	1' up from ground	201	lf	28.27	5,682
remove siding	1' up from ground	201	sf	2.42	486
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
metal flashing at perimeter		201	lf	16.85	3,387
pressure treated horizontal wood siding		201	sf	3.00	603
<b>Sub Total - Direct Cost</b>					<b>12,695</b>
General Conditions		20.00%			2,539
Overhead & Profit		23.00%			3,504
Design & Price Reserve		15.00%			2,811
Escalation	May-15	8.16%			1,758
Bond		3.00%			699
Soft Costs/Design Fees		30.00%			7,202
<b>Total Project Cost</b>					<b>\$31,208</b>
<b>Shed #1 Wall Braces</b>					<b>\$</b>
demo two diaganol wall braces	2 each @ 12'	24	lf	14.04	337
disposal		1	ea	48.35	48
replace diaganal wall braces	small area	24	lf	16.97	407
<b>Sub Total - Direct Cost</b>					<b>792</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			158
Overhead & Profit		23.00%			219
Design & Price Reserve		15.00%			175
Escalation	May-15	8.16%			110
Bond		3.00%			44
Soft Costs/Design Fees		30.00%			449
<b>Total Project Cost</b>					<b>\$1,947</b>
<b>Shed #1 Roof</b>					<b>\$</b>
demo metal roof		2,425	sf	2.37	5,747
dumpster rental		1	weeks	734.71	735
load & truck	10 mile round trip	20	cy	55.27	1,105
dump charges		8	ton	87.12	697
new metal roof		2,425	sf	16.85	40,861
<b>Sub Total - Direct Cost</b>					<b>49,145</b>
General Conditions		20.00%			9,829
Overhead & Profit		23.00%			13,564
Design & Price Reserve		15.00%			10,881
Escalation	May-15	8.16%			6,807
Bond		3.00%			2,707
Soft Costs/Design Fees		30.00%			27,880
<b>Total Project Cost</b>					<b>\$120,813</b>
<b>Electrical</b>					
<b>Generator And Automatic Transfer Switch</b>					<b>\$</b>
generator - gas 50kw		1	ea	29,760.60	29,761
<b>Sub Total - Direct Cost</b>					<b>29,761</b>
General Conditions		20.00%			5,952
Overhead & Profit		23.00%			8,214
Design & Price Reserve		15.00%			6,589
Escalation	May-15	8.16%			4,122
Bond		3.00%			1,639
Soft Costs/Design Fees		30.00%			16,883
<b>Total Project Cost</b>					<b>\$73,160</b>
<b>Exit Signs</b>					
demo existing exit signs		10	ea	62.48	625
disposal		1	ea	48.40	48
exit signs throughout		8,890	sf	0.41	3,645
<b>Sub Total - Direct Cost</b>					<b>4,318</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			864
Overhead & Profit		23.00%			1,192
Design & Price Reserve		15.00%			956
Escalation	May-15	8.16%			598
Bond		3.00%			238
Soft Costs/Design Fees		30.00%			2,450
<b>Total Project Cost</b>					<b>10,616</b>
<b>Exterior LED Lighting</b>					
demo existing exterior lighting	allowance	10	ea	43.56	436
disposal		1	ea	242.00	242
new exterior lighting	allowance	10	ea	771.00	7,710
<b>Sub Total - Direct Cost</b>					<b>8,388</b>
General Conditions		20.00%			1,678
Overhead & Profit		23.00%			2,315
Design & Price Reserve		15.00%			1,857
Escalation	May-15	8.16%			1,162
Bond		3.00%			462
Soft Costs/Design Fees		30.00%			4,759
<b>Total Project Cost</b>					<b>20,621</b>
<b>Plumbing</b>					
<b>Replace Water Closets</b>					
remove water closet		1	ea	117.13	117
disposal		1	ea	48.40	48
low flow water closet		1	ea	2,485.34	2,485
<b>Sub Total - Direct Cost</b>					<b>2,650</b>
General Conditions		20.00%			530
Overhead & Profit		23.00%			731
Design & Price Reserve		15.00%			587
Escalation	May-15	8.16%			367
Bond		3.00%			146
Soft Costs/Design Fees		30.00%			1,503
<b>Total Project Cost</b>					<b>6,514</b>
<b>Replace Laundry Tub</b>					
remove laundry tub		1	ea	165.77	166
disposal		1	ea	48.40	48
new laundry tub		1	ea	3,517.48	3,517
<b>Sub Total - Direct Cost</b>					<b>3,731</b>



Description	Note	Quantity	Unit	Price	Total
General Conditions		20.00%			746
Overhead & Profit		23.00%			1,030
Design & Price Reserve		15.00%			826
Escalation	May-15	8.16%			517
Bond		3.00%			206
Soft Costs/Design Fees		30.00%			2,117
<b>Total Project Cost</b>					<b>9,173</b>
<b>Install Mixing Valve</b>					
install mixing vlave		1	ea	3,748.55	3,749
<b>Sub Total - Direct Cost</b>					<b>3,749</b>
General Conditions		20.00%			750
Overhead & Profit		23.00%			1,035
Design & Price Reserve		15.00%			830
Escalation	May-15	8.16%			519
Bond		3.00%			206
Soft Costs/Design Fees		30.00%			2,127
<b>Total Project Cost</b>					<b>9,216</b>

HIGHWAY DEPARTMENT  
Program Areas

	EXISTING SPACE	QUANTITY	PROPOSED AREA	NEW ADDITIONS
<b>HIGHWAY DEPT. - FIRST FLOOR</b>				
Hall	61		61	
Office	186		331	145
Toilet Rooms	113		113	
Custodian	36		36	
Mechanical Room	120		166	46
Break Room	178		319	141
Maintenance Bays	1565		1565	
Vehicle Bays	4408		6688	2280
<b>TOTAL HIGHWAY DEPT. - FIRST FLOOR</b>	<b>6667</b>		<b>9279</b>	<b>2612</b>

<b>HIGHWAY DEPT. - MEZZANINE</b>				
Storage	747		747	
<b>TOTAL HIGHWAY DEPT. - MEZZANINE</b>	<b>747</b>		<b>747</b>	

<b>HIGHWAY DEPT. - NET ROOM AREA</b>				
First Floor	6667		9279	2612
Mezzanine	747		747	
<b>TOTAL HIGHWAY DEPT. - NET ROOM AREA</b>	<b>7414</b>		<b>10026</b>	<b>2612</b>

<b>HIGHWAY DEPT. - NET GROSS AREA</b>				
First Floor	7130		9921	2791
Mezzanine	816		816	
<b>TOTAL HIGHWAY DEPT. - NET GROSS AREA</b>	<b>7946</b>		<b>10737</b>	<b>2791</b>

USE GROUP S-1  
Type VB Construction  
Single Story 9,000 SF

<b>HIGHWAY DEPT. - SHED #1 - NET AREA</b>	<b>2228</b>
-------------------------------------------	-------------

<b>HIGHWAY DEPT. - SHED #2 - NET AREA</b>	<b>313</b>
-------------------------------------------	------------



## Use of Cost Estimate Information

At study phase we do not know how the Town might package contracts or combine items. Accordingly we price each item in the study as work performed by a General Contractor, requiring professionally designed bid documents and construction oversight & contract administration by a professional design team. These and other factors affect the study direct cost estimates as follows;

An item is added for General Conditions. This is a General Contractor item to cover the cost of all of the items stipulated in a typical construction contract and bid specification including such items as insurance, temporary utilities, site offices, OSHA requirements, and other non-direct costs of performing work that are required of a General Contractor. The percentage used is based on the size of the contract. The smaller the contract, the higher the percentages because fixed costs are spread over a smaller base figure.

An item is added for Overhead and Profit. Again, this is a General Contractor item. It covers the cost of the GC home office, estimating staff, admin staff, and other standard overhead items. It also includes a fair and reasonable profit margin in normal market conditions. Again, the smaller the contract, the higher the percentage is to meet the necessary expenses of doing business.

An item is added for Design & Price Reserve. It is important to note that actual designs put out to bid often vary from design solutions envisaged in studies. A study is conceptual in nature whereas bids are based on fully developed design documents. The full amount of money required will not be known until the contract is complete along with the cost of any extras. It is not uncommon for additional unforeseen work to be uncovered during further design investigation or during construction. Rotted roof deck, rock excavation, code changes requiring a different design solution are all examples of possible additional costs that may be incurred on the design side. On the price side this contingency guards against changing economic conditions and inflationary pressures beyond the norm as the economy improves.

Escalation at a rate of 4% per annum is added from the date the estimate is prepared to update the estimate to its anticipated earliest bid date. This item covers the normal annual increases in union wages and normal annual material price increases. All prices indicated will need to be increased by 4% per annum to their projected bid date over the years covered in this report.

The cost of bonding the General Contractor and his subcontractors is added. The rate of this insurance varies with the size of the contract and the annual construction volume of the winning bidder.

Owner soft costs typically run 30% on public work projects. Soft costs include architectural, engineering, financing, and legal fees, and any other Town-paid pre- and post-construction expenses. Costs are included in each item for a professional design team to fully explore and develop a complete design solution through bid documents, manage the bid process and supervise & administer the construction contract.

The cumulative effect of all of these compounded percentages uplift the total Direct Cost estimates significantly to the total Project Cost estimate.

Whether items are bid to a GC or to a sub-contractor, whether an architectural team is involved, whether wage rates are applicable are examples of how these estimates may vary. It is very important to understand that the procurement method and contract packaging do have a considerable impact on budgeting for the construction, and that the soft cost portion of the estimates should not be allocated to the hard construction budget. Also that the construction bid price is not normally the final construction cost or the total cost of the project when all expenditures are tallied.



TOWN OF BRIMFIELD BUILDING USE AUDIT - CONDITIONS ASSESSMENT  
 MARKUP LIST  
 BRIMFIELD, MA 01010



Description	Note	Quantity	Unit	Price	Total
<b>Markups - To Be Calculated Cumulatively</b>					
<b>General Conditions</b>					
Project Value Less Than 200k				20.00%	
Project Value 200k - 500k				16.00%	
Project Value 500k - 1mil				14.00%	
Project Value 1mil - 2mil				12.00%	
Project Value 2mil - 5mil				10.00%	
<b>Overhead &amp; Profit</b>					
Project Value Less Than 200k				23.00%	
Project Value 200k - 500k				18.00%	
Project Value 500k - 1mil				16.00%	
Project Value 1mil - 2mil				14.00%	
Project Value 2mil - 5mil				12.00%	
Design & Price Reserve				15.00%	
<b>Escalation</b>					
1 Years From Now	Aug-14			4.00%	
2 Years From Now	Aug-15			8.16%	
3 Years From Now	Aug-16			12.50%	
4 Years From Now	Aug-17			17.00%	
5 Years From Now	Aug-18			21.68%	
<b>Bond</b>					
Project Value Less Than 100k				3.00%	
Project Value 100k - 1mil				2.40%	
Project Value 1mil - 2mil				2.00%	
Project Value 2mil - 5mil				1.60%	
Project Value 5mil - 10mil				1.34%	
Soft Costs/Design Fees				30.00%	